

Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-25762
5. Indicate Type of Lease
STATE [X] FEE []
6. State Oil & Gas Lease No.
L-3025

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [] Other SWD []
2. Name of Operator
EOG Resources, Inc.
3. Address of Operator
104 South Fourth Street, Artesia, NM 88210
4. Well Location
Unit Letter P : 330 feet from the South line and 990 feet from the East line
Section 2 Township 11S Range 34E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4134'GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [] PLUG AND ABANDON [X]
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: []

SUBSEQUENT REPORT OF:

REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

EOG Resources, Inc. plans to plug and abandon this well as follows:

- 1. MIRU all safety equipment as needed. NU BOP. POOH with production equipment.
2. Set a CIBP at 13,083'. Pressure test. Spot 30 sx Class "H" cement on top of CIBP to 12,812'. WOC and tag. This will cover Devonian perms.
3. Spot a 25 sx Class "H" cement plug from 11,790'-11,564'. This will cover Atoka top and spacer requirement.
4. Perforate at 9140'. Attempt injection rate. Squeeze with 50 sx Class "H" cement from 9140'-8941'. WOC and tag. This will cover Wolfcamp top.
5. Perforate at 7820'. Attempt injection rate. Squeezed with 45 sx Class "H" cement from 7820'-7641'. WOC and tag. This will cover Abo top.
6. Perforate at 5540'. Attempt injection rate. Squeeze with 35 sx Class "C" cement from 5540'-5384'. WOC and tag. This will cover Glorieta top.
7. Perforate at 4246'. Attempt injection rate. Squeeze with 60 sx Class "C" cement from 4246'-3979'. WOC and tag. This will cover casing shoe and San Andres top.
8. Perforate at 2815'. Attempt injection rate. Spot a 25 sx Class "C" cement plug from 2815'-2563'. WOC and tag. This will cover Yates top.
9. Spot a 25 sx Class "C" cement plug from 2100'-1848'. This will cover Anhydrite top.
10. Perforate at 507'. Attempt injection rate. Spot 55 sx Class "C" cement from 507' and circulate up to surface. Verify cement at surface. Back fill as needed.
11. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached

4" diameter 4' tall Above Ground Marker

SEE ATTACHED CONDITIONS OF APPROVAL

Spud Date:

[Empty box for Spud Date]

Rig Release Date:


[Empty box for Rig Release Date]

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina Huerta TITLE Regulatory Specialist DATE March 31, 2022

Type or print name Tina Huerta E-mail address: tina_huerta@eogresources.com PHONE: 575-748-4168
For State Use Only

APPROVED BY: Kerry Fortner TITLE Compliance Officer A DATE 5/3/22
Conditions of Approval (if any): 575-263-6633



Sec-TWN-RNG: 2-11S-34E		API: 30-025-25762							
Surface 330' FSL & 990' FEL		GR: 4134'							
CASING DETAIL									
#	Hole Size	Csg. Size	Wt.	Grade	Top	Bottom	Sx Cmt	TOC	TOC by
A	17 1/2	13 3/8	48	H-40	0	457	450	Surface	Circ.
B	11	8 5/8	24/32	K-55	0	4196	1525	Surface	Circ.
C	7 7/8	5 1/2	17/20	N-80	0	13180	455	11,130	CBL
FORMATION TOPS									
Formation	Top (MD)	Formation	Top (MD)						
Anhydrite	2,050	Mississippian	12,892						
Yates	2,765	Devonian	13,114						
San Andres	4,050								
Glorieta	5,490								
Abo	7,770								
Wolfcamp	9,090								
Atoka	11,740								
PLUGS									
#	SX	Class	Top	Bottom	Δ	Notes	Tag		
1	30	H	12812	13083	271	CIBP at 13083'. Pressure test. Spot 30 sx. WOC & Tag. Devonian Perfs	Y		
2	25	H	11564	11790	226	Spot 25 sx at 11790'. Atoka top & spacer requirement	N		
3	50	H	8941	9140	199	Perf at 9140'. Attempt Inj. Sqz 50 sx. WOC & tag. Wolfcamp top	Y		
4	45	H	7641	7820	179	Perf at 7820'. Attempt Inj. Sqz 45 sx. WOC & tag. Abo top	Y		
5	35	C	5384	5540	156	Perf at 5540'. Attempt Inj. Sqz 35 sx. WOC & tag. Glorieta top	Y		
6	60	C	3979	4246	267	Perf at 4246'. Attempt Inj. Sqz 60 sx. WOC & tag. Int. Csg. Shoe & San Andres top	Y		
7	25	C	2563	2815	252	Perf at 2815'. Attempt Inj. <u>SPOT 25 sx</u> . WOC & tag. Yates top.	Y		
8	25	C	1848	2100	252	Spot 25 sx at 2100'. Anhydrite top	N		
9	55	C	0	507	507	Perf at 507'. Attempt Inj. Spot 55 sx. Bring CTS. Sur. Csg. Shoe & Surface	Y		
PERFORMANCE DETAIL									
Formation	Top	Bottom	Formation	Top	Bottom				
Devonian	13,133	13,167							
Sqz'd	Atoka	11,911	11,916						
ADDITIONAL DETAIL									
DV tool [8 5/8"] at 2088'									
5 1/2" remedial cement job will prevent circulating squeeze plugs up the 5.5"/8.625" annulus to surface.									
Squeeze plugs will be communicating with OH section from 4,196' - 11,130'.									
Perforations for plugs 8, 9 & 11 should not breakdown. Verify & spot cement. Plug 10 is spotted regardless.									
KJP 3/18/2022									

**CONDITIONS OF APPROVAL
FOR PLUGGING AND ABANDONMENT
OCD - Southern District**

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at **(575)-263-6633** at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water will not be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) **Fusselman**
 - B) **Devonian**
 - C) **Morrow**
 - D) **Wolfcamp**
 - E) **Bone Springs**
 - F) **Delaware**
 - G) **Any salt sections**
 - H) **Abo**
 - I) **Glorieta**
 - J) **Yates.**
 - K) **Potash---(In the R-111-P Area (Potash Mine Area),**
A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. **Operator name**
- 2. **Lease and Well Number**
- 3. **API Number**
- 4. **Unit letter**
- 5. **Quarter Section (feet from the North, South, East or West)**
- 6. **Section, Township and Range**
- 7. **Plugging Date**
- 8. **County**

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 94664

COMMENTS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 94664
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	5/3/2022

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 94664

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 94664
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval	5/3/2022