

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: FEDERAL 30 Well Location: T19S / R33E / SEC 30 / County or Parish/State: LEA /

NESW /

M

Well Number: 02 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMNM073240 Unit or CA Name: FEDERAL 30 Unit or CA Number:

NMNM72438

US Well Number: 3002527671 Well Status: Producing Gas Well Operator: KAISER FRANCIS OIL

COMPANY

### **Notice of Intent**

**Sundry ID: 2670780** 

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 05/09/2022 Time Sundry Submitted: 02:23

Date proposed operation will begin: 06/06/2022

**Procedure Description:** -POOH w/ 1 ½" IJ tubing -POOH w/ 2 7/8" tubing. -Set retainer above junk @ 12,000'. Sqz 200sx Class H below retainer. Spot 30sx on top. -Circ hole w/ NM-approved plugging mud -Spot 60 sk Class H plug @ 9965' (DV tool/Bone Spring plug) -Spot 50 sk Class H plug @ 7900' (Delaware plug) -Cut and pull 5 ½" casing f/ ~5365'. -Spot 125sx Class C @ 5415' (5 ½" stub plug/ 9 5/8" shoe plug). WOC & tag -Spot 150 sx Class C @ 3010' (DV Tool/Yates plug) WOC & tag -Spot 100 sx Class C @ 1365' -Spot 100' Class C surface plug -Cut off wellhead below ground level and weld on marker.

## **Surface Disturbance**

Is any additional surface disturbance proposed?: No

### **NOI Attachments**

### **Procedure Description**

Federal\_30\_2\_Revised\_20220509142244.pdf

Federal\_30\_2\_Proposed\_P\_A\_20220509142213.pdf

**Accepted for Record Only** 

SUBJECT TO LIKE APPROVAL BY BLM NMOCD 5/12/22



eceived by OCD: 4/20/2022 11:59:58 AM Well Name: FEDERAL 30

Well Location: T19S / R33E / SEC 30 /

NESW /

County or Parish/State: LEA/ 2 of

Well Number: 02

Type of Well: CONVENTIONAL GAS

Unit or CA Name: FEDERAL 30

**Allottee or Tribe Name:** 

**Unit or CA Number:** NMNM72438

**US Well Number: 3002527671** 

Lease Number: NMNM073240

Well Status: Producing Gas Well

Operator: KAISER FRANCIS OIL

COMPANY

Zip:

## **Conditions of Approval**

### **Specialist Review**

FEDERAL 30 02 2667817 COA AND PROCEDURE 20220510095232.pdf

## **Operator**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: CHRISTINA OPFER Signed on: MAY 09, 2022 02:22 PM

Name: KAISER FRANCIS OIL COMPANY

Title: Regulatory Manager

Street Address: 6733 S YALE AVENUE

City: TULSA State: OK

Phone: (918) 491-4468

Email address: CHRISTINAO@KFOC.NET

#### **Field**

**Representative Name:** 

**Street Address:** 

City: State:

Phone:

**Email address:** 

## **BLM Point of Contact**


Signature: Keith Immatty


**BLM POC Name: KEITH P IMMATTY BLM POC Title: ENGINEER** 

**BLM POC Phone:** 5759884722 BLM POC Email Address: KIMMATTY@BLM.GOV

**Disposition:** Approved Disposition Date: 05/10/2022

date of starting a proposed compl  1. POOH w/ 13 2. POOH w/ 25 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C 11. Spot 100' Cla 12. Cut off wellf	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging I lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'. Class C @ 5415' (5 ½" stu Class C @ 3010' (DV Too Class C @ 1365' ass C surface plug lead below ground level  12/15/1981	sions. (Clearly state all pertine ERULE 19.15.7.14 NMAC. For Sqz 200sx Class H below retained mud tool/Bone Spring plug) aware plug)  Ib plug/ 9 5/8" shoe plug). WC I/Yates plug) WOC & tag  and weld on marker.  Rig Release Date:  Is true and complete to the beautiful Exegulatory	er. Spot 30sx or OC & tag  St of my knowle Manager	/15/1982	
3. Describe propose date of starting a proposed compl  1. POOH w/ 1 3 2. POOH w/ 2 5 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C 11. Spot 100' Cla 12. Cut off wellf	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging of lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'. Class C @ 5415' (5 ½" stuctors C @ 3010' (DV Too Class C @ 1365' lass C surface plug lased below ground level  12/15/1981  the information above in the strong s	sions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. For Each English For Each Englis	ent details, and r Multiple Comparer. Spot 30sx or OC & tag	pletions: Attach wellbore diagram of top.  /15/1982	
3. Describe propose date of starting a proposed compl  1. POOH w/ 1 3 2. POOH w/ 2 5 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C 11. Spot 100' Cla	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging of lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'. Class C @ 5415' (5 ½" stucture Class C @ 3010' (DV Too Class C @ 1365' ass C surface plug mead below ground level	God 200sx Class H below retained tool/Bone Spring plug) aware plug)  by plug/ 9 5/8" shoe plug). Wollyates plug) WOC & tag  and weld on marker.	ent details, and r Multiple Compart of the Compart	pletions: Attach wellbore diagram of n top.	
3. Describe propose date of starting a proposed compl  1. POOH w/ 1 3 2. POOH w/ 2 5 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C 11. Spot 100' Cla	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging of lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'. Class C @ 5415' (5 ½" stucture Class C @ 3010' (DV Too Class C @ 1365' ass C surface plug mead below ground level	God 200sx Class H below retained tool/Bone Spring plug) aware plug)  by plug/ 9 5/8" shoe plug). Wollyates plug) WOC & tag  and weld on marker.	ent details, and r Multiple Compart of the Compart	pletions: Attach wellbore diagram of n top.	
Describe propose date of starting a proposed compl  1. POOH w/ 1 ? 2. POOH w/ 2 ? 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C 11. Spot 100' Cla	any proposed work). Seetion or recompletion.  2" IJ tubing 7/8" tubing. above junk @ 12,000'. Seetion or recompletion.  NM-approved plugging a lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'.  Class C @ 5415' (5 ½" stuckless C @ 3010' (DV Too Class C @ 1365' ass C surface plug	sions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. For Sqz 200sx Class H below retained tool/Bone Spring plug) aware plug)  aware plug)  b plug/ 9 5/8" shoe plug). WC l/Yates plug)	ent details, and r Multiple Com er. Spot 30sx or	pletions: Attach wellbore diagram of	
Describe propose date of starting a proposed compl  1. POOH w/ 1 ? 2. POOH w/ 2 ? 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C 11. Spot 100' Cla	any proposed work). Seetion or recompletion.  2" IJ tubing 7/8" tubing. above junk @ 12,000'. Seetion or recompletion.  NM-approved plugging a lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'.  Class C @ 5415' (5 ½" stuckless C @ 3010' (DV Too Class C @ 1365' ass C surface plug	sions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. For Sqz 200sx Class H below retained tool/Bone Spring plug) aware plug)  aware plug)  b plug/ 9 5/8" shoe plug). WC l/Yates plug)	ent details, and r Multiple Com er. Spot 30sx or	pletions: Attach wellbore diagram of	
Describe proposed date of starting a proposed comple 1. POOH w/ 1 7 2. POOH w/ 2 7 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C 9. Spot 150 sx C 10. Spot 100 sx C	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging of lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'. Class C @ 5415' (5 ½" stu Class C @ 3010' (DV Too Class C @ 1365'	Gions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. For Signal For Foreign	ent details, and r Multiple Com er. Spot 30sx or	pletions: Attach wellbore diagram of	
Describe propose date of starting a proposed compl  1. POOH w/ 13 2. POOH w/ 25 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull 8. Spot 125sx C	any proposed work). Seetion or recompletion.  2" IJ tubing 7/8" tubing. above junk @ 12,000'. See NM-approved plugging a lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/ ~5365'.  Class C @ 5415' (5 ½" stu	Gions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. For Signal For Foreign	ent details, and r Multiple Com er. Spot 30sx or	pletions: Attach wellbore diagram of	
Describe proposedate of starting a proposed comple 1. POOH w/ 13 2. POOH w/ 23 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C 7. Cut and pull	any proposed work). Seetion or recompletion.  2" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging of lass H plug @ 9965' (DV lass H plug @ 7900' (Del 5 ½" casing f/~5365'.	Signary state all pertine EE RULE 19.15.7.14 NMAC. For Signary 200sx Class H below retained tool/Bone Spring plug) aware plug)	ent details, and r Multiple Com er. Spot 30sx or	pletions: Attach wellbore diagram of	
Describe proposed date of starting a proposed comple 1. POOH w/ 1 3 2. POOH w/ 2 7 3. Set retainer 4. Circ hole w/ 5. Spot 60 sk C 6. Spot 50 sk C	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing. above junk @ 12,000'. S NM-approved plugging I lass H plug @ 9965' (DV lass H plug @ 7900' (Del	sions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. Fo	ent details, and r Multiple Com	pletions: Attach wellbore diagram of	
Describe proposed date of starting a proposed comple 1. POOH w/ 1 3 2. POOH w/ 2 3. Set retainer 4. Circ hole w/	any proposed work). Seetion or recompletion.  2" IJ tubing  7/8" tubing.  above junk @ 12,000'. S  NM-approved plugging in	Gions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. Fo	ent details, and r Multiple Com	pletions: Attach wellbore diagram of	
Describe proposed date of starting a proposed comple 1. POOH w/ 1 3 2. POOH w/ 2 3 3. Set retainer	any proposed work). Seetion or recompletion.  4" IJ tubing  7/8" tubing.  above junk @ 12,000'. Seep	ions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. Fo	ent details, and r Multiple Com	pletions: Attach wellbore diagram of	
Describe proposed date of starting a proposed comple 1. POOH w/ 13 2. POOH w/ 27	any proposed work). Seetion or recompletion.  4" IJ tubing 7/8" tubing.	ions. (Clearly state all pertine EE RULE 19.15.7.14 NMAC. Fo	ent details, and r Multiple Com	pletions: Attach wellbore diagram of	
Describe propos date of starting proposed compl	any proposed work). SE etion or recompletion.	ions. (Clearly state all pertine	ent details, and	= -	
Describe propositions date of starting a	any proposed work). SE	ions. (Clearly state all pertine	ent details, and	= -	
TUED:					
OWNHOLE COMN LOSED-LOOP SY	MINGLE	_			
ERFORM REMED EMPORARILY AB JLL OR ALTER C	ANDON CHAN	GE PLANS	_	LLING OPNS. PAND A	
NO <sup>·</sup> ERFORM REMED	TICE OF INTENTION		SUBS	SEQUENT REPORT OF:  K	
. Check Appropria	ate Box to Indicate Natu	ire of Notice, Report or Other	Data		
	II. Lie	3589' GF			
Section 30		Township 19S Range vation (Show whether DR, RK		PM County Lea	
Unit Letter Section 30		et from the <u>South</u> line ar			
. Well Location	,	,			
. Address of Oper	ator P.O. Box 21468, Tu	lsa, OK 74121		TO. POOLITAINE OF WINGCAL	
Kaiser-Francis Oil Company				12361  10. Pool name or Wildcat	
. Name of Operat				9. OGRID Number	
1. Type of Well: Oil Well 🗵 Gas Well 🗌 Other				2	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Federal 30  8. Well Number	
OO NOT LISE THIS CODA		D REPORTS ON WELLS	IFFERENT	7. Lease Name or Unit Agreement Name	
220 S. St. Francis Dr., S 7505	anta Fe, NM				
<u> District IV</u> – (505) 476-34	10 Rio Brazos Rd., Aztec, NM 87410 <u>trict IV</u> – (505) 476-3460  Santa Fe, NM 87505		5	6. State Oil & Gas Lease No.	
<u> District III</u> – (505) 334-61	.78	1220 South St. Francis Dr.		30-025-27671  5. Indicate Type of Lease  STATE FEE FED FED	
	<u>I</u> – (575) 748-1283 rst St., Artesia, NM 88210 OIL CONSERVATION DIVISION		ISION		
• • •				WELL API NO.	
625 N. French Dr., Hob <u>istrict II</u> – (575) 748-12	<del>-</del>	017	Kesources	neviseu July 10, 2015	
Office <u>District I</u> – (575) 393-616 1625 N. French Dr., Hob <u>District II</u> – (575) 748-12 311 S. First St., Artesia, I	<del>-</del>	ergy, Minerals and Natural		Form C-103 Revised July 18, 2013	





# Kaiser-Francis Oil Company Federal 30-2 API #30-025-27671 Proposed Plugging Procedure


Kaiser-Francis Oil Company is submitting a Notice of Intent, form C-103F, regarding the Federal 30-2. The Bone Spring, Delaware and Yates/7 Rivers are productive in the area. Below is the planned plugging procedure to isolate them.


- 1. POOH w/ 1 ½" IJ tubing
- 2. POOH w/ 2 7/8" tubing.
- 3. Set retainer above junk @ 12,000'. Sqz 200sx Class H below retainer. Spot 30sx on top.
- 4. Circ hole w/ NM-approved plugging mud
- 5. Spot 60 sk Class H plug @ 9965' (DV tool/Bone Spring plug)
- 6. Spot 50 sk Class H plug @ 7900' (Delaware plug)
- 7. Cut and pull 5  $\frac{1}{2}$ " casing f/ ~5365'.
- 8. Spot 125sx Class C @ 5415' (5 1/2" stub plug/ 9 5/8" shoe plug). WOC & tag
- 9. Spot 150 sx Class C @ 3010' (DV Tool/Yates plug) WOC & tag
- 10. Spot 100 sx Class C @ 1365'
- 11. Spot 100' Class C surface plug
- 12. Cut off wellhead below ground level and weld on marker.

# Kaiser-Francis Oil Company Federal 30-2 API #30-025-27671 Proposed Plugging Procedure

Kaiser-Francis Oil Company is submitting a Notice of Intent, form C-103F, regarding the Federal 30-2. The Bone Spring, Delaware and Yates/7 Rivers are productive in the area. Below is the planned plugging procedure to isolate them.

- 1. POOH w/ 1 ½" IJ tubing
- 2. POOH w/ 2 7/8" tubing.
- 3. Set retainer above junk @ 12,000'. Sqz 200sx Class H below retainer. Spot 30sx on top.
- 4. Circ hole w/ NM-approved plugging mud
- 5. Spot 60 sk Class H plug @ 9965' (DV tool/Bone Spring plug)
- 6. Spot 50 sk Class H plug @ 7900' (Delaware plug)
- 7. Cut and pull 5 ½" casing f/ ~5365'.
- 8. Spot 125sx Class C @ 5415' (5 1/2" stub plug/ 9 5/8" shoe plug). WOC & tag
- 9. Spot 150 sx Class C @ 3010' (DV Tool/Yates plug) WOC & tag
- 10. Spot 100 sx Class C @ 1365'
- 11. Spot 100' Class C surface plug
- 12. Cut off wellhead below ground level and weld on marker.





District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 100240

#### **COMMENTS**

Operator:	OGRID:
KAISER-FRANCIS OIL CO	12361
PO Box 21468	Action Number:
Tulsa, OK 74121146	100240
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### COMMENTS

Created By		Comment Date
plmartinez	DATA ENTRY PM	5/12/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 100240

#### **CONDITIONS**

Operator:	OGRID:
KAISER-FRANCIS OIL CO	12361
PO Box 21468	Action Number:
Tulsa, OK 74121146	100240
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	Like approval from BLM	5/12/2022