

Office  
 District I – (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II – (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III – (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV – (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM  
 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-045-29458
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Havasu Com
8. Well Number 1
9. OGRID Number 372171
10. Pool name or Wildcat Basin Fruitland Coal

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator HILCORP ENERGY COMPANY	
3. Address of Operator 382 Road 3100, Aztec, NM 87410	
4. Well Location Unit Letter <u>P</u> : <u>790'</u> feet from the <u>SOUTH</u> line and <u>790'</u> feet from the <u>EAST</u> line Section <u>22</u> Township <u>32N</u> Range <u>13W</u> NMPM County <u>San Juan</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5924' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: <input type="checkbox"/>		<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>	
---	--	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Hilcorp Energy Company requests permission to P&A the subject well per the attached procedures, current and proposed wellbore schematics. A closed loop system will be used.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Amanda Walker TITLE Operations/Regulatory Technician – Sr. DATE 02/10/2022

Type or print name Amanda Walker E-mail address: mwalker@hilcorp.com PHONE: (346) 237-2177

**For State Use Only**

APPROVED BY: Amanda Walker TITLE Petroleum Specialist DATE 6/17/2022

Conditions of Approval (if any):



**HILCORP ENERGY COMPANY**  
**HAVASU COM 1**  
**NOTICE OF INTENT TO PERMANENTLY ABANDON**

API #: 3004529458

**JOB PROCEDURES**

- ☒ NMOCD **Contact OCD 24 hrs prior to MIRU. Record and document all casing pressures daily, including BH, IC (if present) and PC. Comply with all NMOCD and HEC safety and environmental regulations.**
- ☐ BLM
1. Hold pre-job safety meeting. Comply with all **NMOCD** and HEC safety and environmental regulations. Scope location for base beam. If base beam can not be used, test rig anchors prior to moving in rig. Verify there is no H2S present prior to beginning operations. Verify cathodic is offline.
  2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in WellView.
  3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure.
  4. Pull rod string and plunger assembly.
  5. ND wellhead and NU BOPE. Test and chart BOPs as per regulations. Record pressure test.
  6. TOO H while scanning with 2-7/8" tubing, laying down bad joints. Pull tubing pump out of hole.
  7. RIH w/ CICR and set at 1230', in the casing above the openhole completion.
  8. Roll the hole with fluid. TOO H. RU WL and run CBL from plug depth at 1230' to surface, while keeping hole loaded. Report results to NMOCD.
  9. Pump **Plug 1, 1230'-1130'** (Openhole Completion: 1240'-1310', Pictured Cliffs Top 1206', Fruitland Coal pre-perforated joint 1156'-1196'). Mix & pump 18 sx of Class G cement and spot plug on top of retainer to cover the openhole completion below and the PC top. PU and reverse circulate tubing clean. WOC 4 hours, then RIH and tag plug to confirm TOC.
  10. If tagged cement is not above open pre-perforated joint, RIH w/ CICR and set at 1106'. \*If tagged cement is above 1156', skip steps 10 and 11.\*
  11. \*If necessary, Pump **Plug 2, 1106'-1006'** (Fruitland Coal pre-perforated joint 1156'-1196'). Mix & pump 18 sx of Class G cement and spot plug on top of retainer to cover the Fruitland Coal perforations. PU and reverse circulate tubing clean. Pressure test plug, and if plug does not test, WOC 4 hours then RIH and tag plug to confirm TOC.
  12. LD tubing to 648'.
  13. Pump **Plug 3, 648'-548'** (Fruitland Coal Top: 598'). Mix & pump 18 sx of Class G cement and spot balanced plug to cover the Fruitland Coal top. PU and reverse circulate tubing clean. If a good pressure test is achieved, do not WOC. If not, WOC 4 hours then RIH to tag plug to confirm TOC.
  14. LD tubing to 164', then TOO H.
  15. RU WL and perforate at 189' below the surface casing shoe at 139'.
  16. Establish injection rate into perforations and circulation up the bradenhead with water.
  17. RIH w/ CICR and set at 164', 25' above the perforations. Sting into CICR.
  18. Pump **Plug 4, 189'-Surface** (Surface Casing Shoe: 139', Kirtland Top 0'). Mix & pump Class G cement from 189' to surface until getting good returns up the bradenhead (approximately 40+ sx). Spot ~26 sx of Class G cement on top of CICR to surface.
  19. ND BOP. Cut off wellhead below surface flange per regulations. Top off w/ cement if needed. Install P&A marker. RDMO. Restore surface location and submit reports to NMOCD.




## Current Schematic

Well Name: HAVASU COM #1

API / UWI 3004529458	Surface Legal Location 022-032N-013W-P	Field Name BASIN (FRUITLAND COAL) #3046	Route 0211	State/Province NEW MEXICO	Well Configuration Type Vertical
Ground Elevation (ft) 1,805.64	Original KB/RT Elevation (ft) 1,809.64	KB-Ground Distance (ft) 4.00	KB-Casing Flange Distance (ft)	KB-Tubing Hanger Distance (ft)	


## Original Hole [Vertical]





**HILCORP ENERGY COMPANY  
HAVASU COM 1  
NOTICE OF INTENT TO PERMANENTLY ABANDON**

**HAVASU COM 1 - PROPOSED P&A SCHEMATIC**



**District I**

1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 80554

**CONDITIONS**

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 80554
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

**CONDITIONS**

Created By	Condition	Condition Date
kpickford	CBL required	2/16/2022
kpickford	Notify NMOCD 24 Hours Prior to beginning operations	2/16/2022
kpickford	Add a plug 740'-840' to cover the Fruitland Coal top @ 790'.	6/17/2022