Office State of New Mexico	Form C-103 of
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Relation 1625 N. French Dr., Hobbs, NM 88240	esources Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	VISION 30-039-30531
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1220 South St. Francis I	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	E-289-23
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAIDIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC	
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☒ Other	8. Well Number
	258H
2. Name of Operator HILCORP ENERGY COMPANY	9. OGRID Number 372171
3. Address of Operator	10. Pool name or Wildcat
382 Road 3100, Aztec, NM 87410	S. Los Pinos Fruitland Sand/Pictured Cliffs
4. Well Location	
Unit Letter <u>K</u> <u>2685</u> feet from the <u>North</u> line and	
Section 2 Township 30N Range	07W NMPM Rio Arriba County
11. Elevation (Show whether DR, RKB, 6295' GL	, RT, GR, etc.)
02)(02	
PULL OR ALTER CASING	ent details, and give pertinent dates, including estimated date. Multiple Completions: Attach wellbore diagram of e attached procedure, current and proposed wellbore
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of	my knowledge and belief.
SIGNATURE <u>Cherylene Weston</u> TITLE <u>Operation</u>	ns / Regulatory Technician DATE 10/02/2023
Type or print name <u>Cherylene Weston</u> E-mail address: <u>cweston@legory.com.</u> For State Use Only	-
APPROVED BY: Monica Kushling TITLE Deputy C Conditions of Approval (if any):	oil and Gas Inspector _{DATE} 10/25/2023



V

HILCORP ENERGY COMPANY NEBU 258H NOTICE OF INTENT TO PERMANENTLY ABANDON

API #: 3003930531

JOB PROCEDURES

- NMOCD Contact OCD 24 hrs prior to MIRU confirm a PTPW has been acquired from Jicarilla. Comply with all NMOCD and HEC safety and environmental regulations.
- 1. MIRU service rig and associated equipment, record all pressures on wellbore.
- 2. Load well, ND tree, NU BOPs and test.
- 3. TOOH w/ 2-3/8" 4.7# EUE J55 tbg set at 4,076'.
- 4. RU ELU, RIH w/ perf gun loaded w/ 4-1/2" 11.6# circ charges, shoot @ 2,790'.
- 5. MU 4-1/2" 11.6# bit/scraper, clear csg to 3,150', POOH. RIH w/ 4-1/2" 11.6# CICR on pipe and set @ 3,140' MD (50' TVD above PC Top).
- 6. Plug #1a | 2,815' 3,140' (CICR @ 3,140' | FRD Top @ 2,865') Pump 21sx (5.1 bbl) Class III "Select" cement and spot a 325' inside plug on top of CICR to cover the CICR, Fruitland Top and plug back the Pictured Cliffs formation.
 *POOH w/ pipe to LD stinger. RIH tag TOC w/ pipe after 4hr WOC.
- 7. Establish injections thru perf'd circ holes @ 2,790' into annulus.

Plug #1b | 2,790' - 3,140' Annular Plug (CICR @ 3,140' | FRD Top @ 2,865') Pump 35sx (8.5 bbl) Class III "Select" cement into circ holes @ 2,790' leaving a 350' cmt plug in the 7" x 4-1/2" annulus. *Note: cement volume includes 50' excess.
PU w/ work string to ~2,500', reverse out to clear tbg.

- 8. RU ELU, RIH w/ perf gun loaded w/ 4-1/2" 11.6# circ charges, shoot @ 2,777'. Establish circulation up annulus to surface.
- 9. Plug #2 | 2,627' 2,777' (DV Tool @ 2,777') Pump 25sx (6.1 bbl) Class III Select cement and circulate in a 150' balanced inside/outside plug to cover the DV Tool.

PU w/ work string to ~2,000', reverse out to clear tbg.


10. RU ELU, perf holes in 4-1/2" csg @ 2,489'. Establish circulation up annulus.

Plug #3 | 2,158' - 2,489' (Kirtland Top @ 2,439' | Ojo Top @ 2,258') Pump 54sx (13.2 bbl) Class III Select cement and circulate in a 331' balanced plug to cover the KRD & OJO Tops. POOH w/ work string, LD.

- 11. RU ELU, perf circ holes in 4-1/2" csg @ 356'. Establish circulation up annulus to surface.
 - Plug #4 | Surface 356' (Surface Shoe @ 306') Pump 50sx (12.2 bbl) Class III "Select" cement and spot a 356' inside/outside plug to cover the surface shoe from 356' to surface.
- 12. LD tubing. ND BOP and cut off wellhead below surface casing flange as per NMOCD. Top off cement at surface as needed. Weld new P&A maker.




HILCORP ENERGY COMPANY NEBU 258H NOTICE OF INTENT TO PERMANENTLY ABANDON





HILCORP ENERGY COMPANY NEBU 258H NOTICE OF INTENT TO PERMANENTLY ABANDON



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 271245

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	271245
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	set first plug minimum of 50 feet below intermediate shoe - Notify NMOCD 24 hours prior to moving on.	10/25/2023