ceived by OCP: 8/21/2024 3:13:24	PM State of New Mexico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO.
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-045-28653 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOSE)	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Sunco Disposal
PROPOSALS.)	Gas Well Other SWD Class I	8. Well Number
2. Name of Operator Agua Moss, LLC		9. OGRID Number 247130
3. Address of Operator		10. Pool name or Wildcat
PO Box 600 Farmington, NM 8749	9	SWD MV
4. Well Location		
Unit LetterE:_	1595feet from theNorth line and	_1005feet from theWestline
Section 2	Township 29N Range 12W	NMPM County San Juan
	11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
12 (1 1 1	5859' GL	
12. Check A	appropriate Box to Indicate Nature of Notic	e, Report or Other Data
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	MULTIPLE COMPL ☐ CASING/CEME nvestigate MIT Failure ☑ OTHER:	ENT JOB
13. Describe proposed or compl	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple (
NI 414411		
rease see the attached procedure for	a workover procedure regarding casing integrity.	
Spud Date:	Rig Release Date:	
	Rig Release Date:	dge and belief.
hereby certify that the information a	above is true and complete to the best of my knowle	
hereby certify that the information a		
hereby certify that the information a SIGNATUREPhilana Thompson Type or print namePhilana Thom	above is true and complete to the best of my knowle	ecalistDATE8/21/2024
For State Use Only	above is true and complete to the best of my knowle TITLERegulatory Compliance Spe	ecalistDATE8/21/2024 errion.bz PHONE: _505-486-1171

WORKOVER PROCEDURE

Well Information				
Well:	Sunco Disposal 1		Field:	Mesaverde SWD
Location:	1595' fnl &1005' fwl S2, T29N, R12W San Juan Co. New Mexico		Elevations:	5859' GL 5872' RKB
Location:			Depths:	4706' KB PBTD 4760' KB TD
Supervisor:	Jeff Davis (505.330.1617)		Engineer:	J. Ryan Davis (505.215.3292) Shacie Murray (505.330.7605)
API:	30-045-28653		Date:	August 21, 2024
Surface Casing:	8- 5/8" @ 209' KB w/ 150sx; Circ to surface		Production Casing:	5-1/2" @ 4750' KB w/ 230 sx stage 1, 515 sx stage 2, circ 25 sx to surf, DV tool @ 2244' KB
Tubulars:	2- 7/8" 6.5# EUE (Apoxy Coated) @ 4282' KB		Packer:	Arrow XL-W retrievable seal bore @ 4282' KB.
Perforations (MV) 4350-4460' KB 2 spf (2000 gals 15% HCL, Frac'd w/ 100,000# 20/40			% HCL, Frac'd w/ 100,000#	

Version 1 – Procedure subject to change based on actual well conditions encountered.

Workover Purpose: Identify Casing Leak Off

Prior to MIRU

- 1. Hold pre-job meeting to go over the workover plan to ensure there are no issues. Adjust plan as necessary based upon the meeting review.
- 2. Manifold csg to flow back tank.
- 3. Contact rig company to ensure new rubbers installed on BOP and tested to 3,500 psig

Set Circulating Plug in TBG


- 4. RU slickline.
- 5. RIH and set 1.78" plug in F nipple @ 4289' KB.
- 6. Slowly bleed off tbg pressure at surface to ensure tbg is dead.

Identify Leak Off

- 7. MIRU workover rig.
- 8. Pressure test tbg to 1000 psi.
- 9. If needed bleed off pressure on tbg and csg to flowback tank.

Page 1 of 3

- 10. ND WH, pull tubing hanger and remove. (Inspect hanger and send off to redress) NU BOP.
- 11. Drop tubing to neutral point at packer. Release seal assembly by rotating 4 turns to right at packer. (Release on-off tool by rotating ¼ turn to left at packer)
- 12. If unable to release from seal assembly, set a circulating slip stop plug above the on-off tool, and J-off the on-off tool.
- 13. Circulate well with fresh water.
- 14. TOH with injection string standing back.
- 15. Remove and redress seal assembly and on-off tool.
- 16. Pressure test casing with freshwater.
 - a. If casing passes report findings (C103R) and await approval to move forward.
 - b. If casing fails proceed with wireline work
- 17. MIRU wireline truck and perform needed tests
 - a. Tests will include but not limited to acoustic and temperature.
 - b. Analyze data to direct next steps with tools.
 - i. If conclusive data is collected that require a different path forward, report to OCD (C103R) and await approval (C103G for remedial work).
- 18. PU work string with RBP and packer.
- 19. Set RBP around 4276' KB, set packer above and pressure test RBP.
- 20. Isolate casing holes.
- 21. Report findings and next steps to OCD (C103R).
 - a. Await approval to move forward (C103G for remedial work).



Wellbore Schematic:




Figure 1: Wellbore Schematic

WORKOVER PROCEDURE

Well Information				
Well:	Sunco Disposal 1		Field:	Mesaverde SWD
Location:	1595' fnl &1005' fwl S2, T29N, R12W San Juan Co. New Mexico		Elevations:	5859' GL 5872' RKB
Location:			Depths:	4706' KB PBTD 4760' KB TD
Supervisor:	Jeff Davis (505.330.1617)		Engineer:	J. Ryan Davis (505.215.3292) Shacie Murray (505.330.7605)
API:	30-045-28653		Date:	August 21, 2024
Surface Casing:	8- 5/8" @ 209' KB w/ 150sx; Circ to surface		Production Casing:	5-1/2" @ 4750' KB w/ 230 sx stage 1, 515 sx stage 2, circ 25 sx to surf, DV tool @ 2244' KB
Tubulars:	2- 7/8" 6.5# EUE (Apoxy Coated) @ 4282' KB		Packer:	Arrow XL-W retrievable seal bore @ 4282' KB.
Perforations (MV) 4350-4460' KB 2 spf (2000 gals 15% HCL, Frac'd w/ 100,000# 20/40			% HCL, Frac'd w/ 100,000#	

Version 1 – Procedure subject to change based on actual well conditions encountered.

Workover Purpose: Identify Casing Leak Off

Prior to MIRU

- 1. Hold pre-job meeting to go over the workover plan to ensure there are no issues. Adjust plan as necessary based upon the meeting review.
- 2. Manifold csg to flow back tank.
- 3. Contact rig company to ensure new rubbers installed on BOP and tested to 3,500 psig

Set Circulating Plug in TBG


- 4. RU slickline.
- 5. RIH and set 1.78" plug in F nipple @ 4289' KB.
- 6. Slowly bleed off tbg pressure at surface to ensure tbg is dead.

Identify Leak Off

- 7. MIRU workover rig.
- 8. Pressure test tbg to 1000 psi.
- 9. If needed bleed off pressure on tbg and csg to flowback tank.

Page 1 of 3

- 10. ND WH, pull tubing hanger and remove. (Inspect hanger and send off to redress) NU BOP.
- 11. Drop tubing to neutral point at packer. Release seal assembly by rotating 4 turns to right at packer. (Release on-off tool by rotating ¼ turn to left at packer)
- 12. If unable to release from seal assembly, set a circulating slip stop plug above the on-off tool, and J-off the on-off tool.
- 13. Circulate well with fresh water.
- 14. TOH with injection string standing back.
- 15. Remove and redress seal assembly and on-off tool.
- 16. Pressure test casing with freshwater.
 - a. If casing passes report findings (C103R) and await approval to move forward.
 - b. If casing fails proceed with wireline work
- 17. MIRU wireline truck and perform needed tests
 - a. Tests will include but not limited to acoustic and temperature.
 - b. Analyze data to direct next steps with tools.
 - i. If conclusive data is collected that require a different path forward, report to OCD (C103R) and await approval (C103G for remedial work).
- 18. PU work string with RBP and packer.
- 19. Set RBP around 4276' KB, set packer above and pressure test RBP.
- 20. Isolate casing holes.
- 21. Report findings and next steps to OCD (C103R).
 - a. Await approval to move forward (C103G for remedial work).



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 376262

COMMENTS

Operator:	OGRID:
AGUA MOSS, LLC	247130
P.O. Box 600 Farmington, NM 87499	Action Number: 376262
	Action Type: [C-103] NOI Workover (C-103G)

COMMENTS

Created By		Comment Date
cchavez	C-103 G Investigation of Failed MIT	8/22/2024

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 376262

CONDITIONS

Operator:	OGRID:
AGUA MOSS, LLC	247130
P.O. Box 600	Action Number:
Farmington, NM 87499	376262
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
cchavez	None	8/22/2024