# Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: SJU TR-D Well Location: T25S / R37E / SEC 11 / County or Parish/State: LEA /

SENE / 32.1456829 / -103.1283991

Well Number: 12 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM4355 Unit or CA Name: SOUTH JUSTIS UNIT Unit or CA Number:

NMNM87877X

### **Notice of Intent**

**Sundry ID:** 2806567

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 08/13/2024 Time Sundry Submitted: 07:50

Date proposed operation will begin: 08/21/2024

Procedure Description: See attached P&A procedure and wellbore diagrams

### **Surface Disturbance**

Is any additional surface disturbance proposed?: No

### **NOI Attachments**

### **Procedure Description**

2024\_08\_13\_\_P\_and\_A\_procedure\_South\_Justis\_Unit\_\_D12\_with\_WBDs\_20240813074637.pdf

Page 1 of 2

Well Location: T25S / R37E / SEC 11 /

SENE / 32.1456829 / -103.1283991

County or Parish/State: LEA/ 2 of

Well Number: 12

Type of Well: OIL WELL

**Allottee or Tribe Name:** 

Lease Number: NMNM4355

Unit or CA Name: SOUTH JUSTIS UNIT Unit or CA Number:

NMNM87877X

**US Well Number: 3002521058** 

**Operator: TEAM OPERATING LLC** 

# **Conditions of Approval**

### **Specialist Review**

BLM\_Revised\_P\_A\_Procedure\_SJU\_TR\_D\_12\_20240822094855.pdf

## **Operator**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

**Operator Electronic Signature: KING TOMLINSON** Signed on: AUG 13, 2024 07:48 AM

Name: TEAM OPERATING LLC

Title: Vice President

Street Address: 16202 BUTERA ROAD

City: PINEHURST State: TX

Phone: (281) 356-7767

Email address: KING@TEAMOPERATING.COM

### **Field**

Representative Name: Austin Musgrave

**Street Address:** 

City: State: Zip:

Phone: (432)701-5144

Email address: austin.musgrave@teamoperating.com

### **BLM Point of Contact**

Signature: Zota Stevens

**BLM POC Name: ZOTA M STEVENS BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5752345998 BLM POC Email Address: ZSTEVENS@BLM.GOV

**Disposition:** Approved Disposition Date: 08/22/2024

Page 2 of 2

#### **BLM Revised P&A Procedure**

- 1. MIRU RIG.
- 2. RIH and TAG cmt at 4970'. Pressure Test casing.
- 3. RIH with CBL from 4970' to surface. Contact BLM after CBL.
- 4. Spot Cl C cmt 4970'- 4678'. WOC and TAG. (T/Glorieta)
- 5. Spot 25sx Cl C cmt from 4250'-4010'. (San Andres)
- 6. Spot 25sxs CI C cmt from 3100'-2860'. WOC and TAG (7 Rivers, Grayburg)
- 7. Perf and Sqz CI C cmt from 2400'-2250'. WOC and TAG (T/Yates)
- 8. Perf and Sqz 67sxs Cl C from 1039'-1040'. WOC and TAG
- 9. Perf and Sqz 650' 450'.
- 10. Perf and Sqz 250' to surface.
- 11. Cut and Install dry hole marker.

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** 

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified BY PHONE (numbers listed under 2.Notification) a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing. The following information shall be permanently inscribed on the plate: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

### **Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:**

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

#### P&A Procedure for the South Justis Unit #D12. NOTE: With BLM revisions as of 23 AUG 24

- 1. MIRU rig. Have 4950' of 2-3/8" 4.7# J-55 EUE 8rd tbg to be delivered to location to plug the well with. Release trapped pressure as necessary.
- 2. ND prod tree & NU BOP's. Pull the 1jt of 2-3/8" tbg & LD. PU 2-3/8" tbg and RIH w/ 2-3/8" tbg and tag cmt @ 4970', load well w/ fresh LSW, and press test csg to 500psi.
- 3. POOH w/ 2-3/8" tbg and stand back.
- 4. RU e-line and RIH w/ CBL to 4970'. Log well w/ CBL/GR/VDL from 4970' back to the surface. RD e-line. Have electronic copy of CBL sent to managing engineer and to BLM rep.
- 5. RIH w/ tbg & tag cmt @ 4970'. Mix/spot 31sxs of Class C cement 14.8ppg on top of cmt/CIBP for cmt plug from 4970'-4678 to cover CIBP w/ 35' cmt for production perfs & for the Glorieta. PU tbg 4600' & clear tbg & WOC. RIH @ tag cmt @ 4678' and circ wellbore w/ 9.0ppg mud.
- 6. PU tbg to 4250' and spot balanced 25sxs Class C cement 14.8ppg plug from 4250'-4010' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 25sxs Class C cement 14.8ppg plug from 3100'-2860' to cover the Langlie Mattix 7Riv Q Grayburg. PU tbg to 2600' & clear tbg. WOC. Then RIH w/ tbg and tag cmt plug @ 2860'.
- 8. PU tbg to 2300'. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 2399-2400'. POOH w/ spent perf gun & RD e-line.
- 9. RIH w/ tbg to 2400'. Spot/cmt squeeze 67sxs Class C 14.8ppg cmt w/ 42sxs outside the 5-1/2" csg & 25sxs inside the 5-1/2" csg from 2400'-2160'. PU tbg to 1800', clear tbg, & WOC. RIH w/ tbg & tag cmt & 2160'.
- 10. PU tbg to 1000'. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 1039'-1040'. POOH w/ spent perf gun & RD e-line.
- 11. RIH w/ tbg to 1040'. Spot/cmt squeeze 67sxs Class C 14.8ppg cmt w/ 42sxs outside the 5-1/2" csg & 25sxs inside the 5-1/2" csg from 1040'-800'. PU tbg to 600', clear tbg, & WOC. RIH w/ tbg & tag cmt & 800'. POOH w/ tbg & stand back.
- 12. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 13. RIH w/ tbg to 650'. Pump down tbg & establish circulation w/ 9.0ppg mud up backside of 5-1/2" csg. Spot/cmt squeeze 56sxs Class C 14.8ppg cmt w/ 34sxs outside the 5-1/2" csg & 22sxs inside the 5-1/2" csg from 650'-450'. PU tbg to 300', clear tbg, & POOH w/ tbg & LD.
- 14. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 249'-250'. POOH w/ spent perf gun & RD e-line.

- 15. Pump down 5-1/2" csg & establish circulation w/ 9.0ppg mud. Then pump 70sxs Class C 14.8ppg cmt down 5-1/2" csg & cmt sqz cmt back to surface in the 5-1/2" x 8-5/8" annulus w/ 43sxs of Class C 14.8ppg cmt & leave a balanced cmt plug in the 5-1/2" csg of 27sxs of Class C 14.8ppg cmt for cmt plug from 250' to surface.
- 16. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C 14.8ppg cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.


NOTE: Class C cement will be 14.8ppg, 1.32cu ft/sx (using 6.3gals water/sx & 0.84cu ft/sk cmt) & mud will be 9.0ppg.

Released to Imaging: 10/24/2024 3:43:28 PM



# TEAM OPERATING, LLC. Downhole Schematic








# **TEAM OPERATING, LLC. Downhole Schematic**





#### P&A Procedure for the South Justis Unit #D12. NOTE: With BLM revisions as of 23 AUG 24

- 1. MIRU rig. Have 4950' of 2-3/8" 4.7# J-55 EUE 8rd tbg to be delivered to location to plug the well with. Release trapped pressure as necessary.
- 2. ND prod tree & NU BOP's. Pull the 1jt of 2-3/8" tbg & LD. PU 2-3/8" tbg and RIH w/ 2-3/8" tbg and tag cmt @ 4970', load well w/ fresh LSW, and press test csg to 500psi.
- 3. POOH w/ 2-3/8" tbg and stand back.
- 4. RU e-line and RIH w/ CBL to 4970'. Log well w/ CBL/GR/VDL from 4970' back to the surface. RD e-line. Have electronic copy of CBL sent to managing engineer and to BLM rep.
- 5. RIH w/ tbg & tag cmt @ 4970'. Mix/spot 31sxs of Class C cement 14.8ppg on top of cmt/CIBP for cmt plug from 4970'-4678 to cover CIBP w/ 35' cmt for production perfs & for the Glorieta. PU tbg 4600' & clear tbg & WOC. RIH @ tag cmt @ 4678' and circ wellbore w/ 9.0ppg mud.
- 6. PU tbg to 4250' and spot balanced 25sxs Class C cement 14.8ppg plug from 4250'-4010' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 25sxs Class C cement 14.8ppg plug from 3100'-2860' to cover the Langlie Mattix 7Riv Q Grayburg. PU tbg to 2600' & clear tbg. WOC. Then RIH w/ tbg and tag cmt plug @ 2860'.
- 8. PU tbg to 2300'. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 2399-2400'. POOH w/ spent perf gun & RD e-line.
- 9. RIH w/ tbg to 2400'. Spot/cmt squeeze 67sxs Class C 14.8ppg cmt w/ 42sxs outside the 5-1/2" csg & 25sxs inside the 5-1/2" csg from 2400'-2160'. PU tbg to 1800', clear tbg, & WOC. RIH w/ tbg & tag cmt & 2160'.
- 10. PU tbg to 1000'. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 1039'-1040'. POOH w/ spent perf gun & RD e-line.
- 11. RIH w/ tbg to 1040'. Spot/cmt squeeze 67sxs Class C 14.8ppg cmt w/ 42sxs outside the 5-1/2" csg & 25sxs inside the 5-1/2" csg from 1040'-800'. PU tbg to 600', clear tbg, & WOC. RIH w/ tbg & tag cmt & 800'. POOH w/ tbg & stand back.
- 12. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 13. RIH w/ tbg to 650'. Pump down tbg & establish circulation w/ 9.0ppg mud up backside of 5-1/2" csg. Spot/cmt squeeze 56sxs Class C 14.8ppg cmt w/ 34sxs outside the 5-1/2" csg & 22sxs inside the 5-1/2" csg from 650'-450'. PU tbg to 300', clear tbg, & POOH w/ tbg & LD.
- 14. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 249'-250'. POOH w/ spent perf gun & RD e-line.


- 15. Pump down 5-1/2" csg & establish circulation w/ 9.0ppg mud. Then pump 70sxs Class C 14.8ppg cmt down 5-1/2" csg & cmt sqz cmt back to surface in the 5-1/2" x 8-5/8" annulus w/ 43sxs of Class C 14.8ppg cmt & leave a balanced cmt plug in the 5-1/2" csg of 27sxs of Class C 14.8ppg cmt for cmt plug from 250' to surface.
- 16. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C 14.8ppg cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.

NOTE: Class C cement will be 14.8ppg, 1.32cu ft/sx (using 6.3gals water/sx & 0.84cu ft/sk cmt) & mud will be 9.0ppg.



# TEAM OPERATING, LLC. Downhole Schematic








# TEAM OPERATING, LLC. Downhole Schematic





#### P&A Procedure for the South Justis Unit #D12. NOTE: With BLM revisions as of 23 AUG 24

- 1. MIRU rig. Have 4950' of 2-3/8" 4.7# J-55 EUE 8rd tbg to be delivered to location to plug the well with. Release trapped pressure as necessary.
- 2. ND prod tree & NU BOP's. Pull the 1jt of 2-3/8" tbg & LD. PU 2-3/8" tbg and RIH w/ 2-3/8" tbg and tag cmt @ 4970', load well w/ fresh LSW, and press test csg to 500psi.
- 3. POOH w/ 2-3/8" tbg and stand back.
- 4. RU e-line and RIH w/ CBL to 4970'. Log well w/ CBL/GR/VDL from 4970' back to the surface. RD e-line. Have electronic copy of CBL sent to managing engineer and to BLM rep.
- 5. RIH w/ tbg & tag cmt @ 4970'. Mix/spot 31sxs of Class C cement 14.8ppg on top of cmt/CIBP for cmt plug from 4970'-4678 to cover CIBP w/ 35' cmt for production perfs & for the Glorieta. PU tbg 4600' & clear tbg & WOC. RIH @ tag cmt @ 4678' and circ wellbore w/ 9.0ppg mud.
- 6. PU tbg to 4250' and spot balanced 25sxs Class C cement 14.8ppg plug from 4250'-4010' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 25sxs Class C cement 14.8ppg plug from 3100'-2860' to cover the Langlie Mattix 7Riv Q Grayburg. PU tbg to 2600' & clear tbg. WOC. Then RIH w/ tbg and tag cmt plug @ 2860'.
- 8. PU tbg to 2300'. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 2399-2400'. POOH w/ spent perf gun & RD e-line.
- 9. RIH w/ tbg to 2400'. Spot/cmt squeeze 67sxs Class C 14.8ppg cmt w/ 42sxs outside the 5-1/2" csg & 25sxs inside the 5-1/2" csg from 2400'-2160'. PU tbg to 1800', clear tbg, & WOC. RIH w/ tbg & tag cmt & 2160'.
- 10. PU tbg to 1000'. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 1039'-1040'. POOH w/ spent perf gun & RD e-line.
- 11. RIH w/ tbg to 1040'. Spot/cmt squeeze 67sxs Class C 14.8ppg cmt w/ 42sxs outside the 5-1/2" csg & 25sxs inside the 5-1/2" csg from 1040'-800'. PU tbg to 600', clear tbg, & WOC. RIH w/ tbg & tag cmt & 800'. POOH w/ tbg & stand back.
- 12. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 13. RIH w/ tbg to 650'. Pump down tbg & establish circulation w/ 9.0ppg mud up backside of 5-1/2" csg. Spot/cmt squeeze 56sxs Class C 14.8ppg cmt w/ 34sxs outside the 5-1/2" csg & 22sxs inside the 5-1/2" csg from 650'-450'. PU tbg to 300', clear tbg, & POOH w/ tbg & LD.
- 14. RU e-line & RIH w/ 1' perf gun @ 4spf & perf cmt sqz perfs @ 249'-250'. POOH w/ spent perf gun & RD e-line.


- 15. Pump down 5-1/2" csg & establish circulation w/ 9.0ppg mud. Then pump 70sxs Class C 14.8ppg cmt down 5-1/2" csg & cmt sqz cmt back to surface in the 5-1/2" x 8-5/8" annulus w/ 43sxs of Class C 14.8ppg cmt & leave a balanced cmt plug in the 5-1/2" csg of 27sxs of Class C 14.8ppg cmt for cmt plug from 250' to surface.
- 16. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C 14.8ppg cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.

NOTE: Class C cement will be 14.8ppg, 1.32cu ft/sx (using 6.3gals water/sx & 0.84cu ft/sk cmt) & mud will be 9.0ppg.



# TEAM OPERATING, LLC. Downhole Schematic








# TEAM OPERATING, LLC. Downhole Schematic





#### **BLM Revised P&A Procedure**

- 1. MIRU RIG.
- 2. RIH and TAG cmt at 4970'. Pressure Test casing.
- 3. RIH with CBL from 4970' to surface. Contact BLM after CBL.
- 4. Spot Cl C cmt 4970'- 4678'. WOC and TAG. (T/Glorieta)
- 5. Spot 25sx Cl C cmt from 4250'-4010'. (San Andres)
- 6. Spot 25sxs CI C cmt from 3100'-2860'. WOC and TAG (7 Rivers, Grayburg)
- 7. Perf and Sqz CI C cmt from 2400'-2250'. WOC and TAG (T/Yates)
- 8. Perf and Sqz 67sxs Cl C from 1039'-1040'. WOC and TAG
- 9. Perf and Sqz 650' 450'.
- 10. Perf and Sqz 250' to surface.
- 11. Cut and Install dry hole marker.

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** 

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified BY PHONE (numbers listed under 2.Notification) a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing. The following information shall be permanently inscribed on the plate: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

### **Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:**

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 394138

### **CONDITIONS**

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	394138
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
gcordero	Commingled well - must set CIBP @ 5780' - Test CIBP - spot 35' cmt on plugCBL must be submitted to OCD Permitting before submitting C-103P	10/24/2024