

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-021-20540
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> P <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Bravo Dome Unit
8. Well Number 271F
9. OGRID Number 495
10. Pool name or Wildcat West Bravo Dome CO2 Gas
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4333 GR

**SUNDRY NOTICES AND REPORTS ON WELLS** 2:20  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other X CO2

2. Name of Operator Hess Corporation

3. Address of Operator PO Box 840 Seminole TX 79360

4. Well Location  
 Unit Letter F : 1650 feet from the N line and 1650 feet from the W line  
 Section 27 Township 18N Range 30E NMPM County Harding

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> P AND A <input type="checkbox"/>
OTHER: Perf prod casing <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>		

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8-5-2013 Week of 8-5-2013

MIRU pulling unit, and equipment. Set up and hook tanks. Unset packer and circulate casing with produced water to kill well.  
 (If packer wont unset, run in w/plug and set plug in packer, pull off from packer & TOH w/fibreglass tbg & LD. PU & TIH w/ workstring & latch onto packer. TOH w/workstring & packer).ND WH & NU BOPs. TOOH and standback fibreglass tubing and packer. Ensure casing is loaded w/produced water to keep well dead. CI well.  
 DAY 2 MIRU wireline services. Tag PBTd to determine fill. Get on depth w/CL and perforate from 2004' - 2030' & 2075' - 2115' w/ 2 spf. RDMO wireline services. If fill found, TIH w/ bit and clean out. TOH w/bit and LD. PU & RIH w/ workstring and treating packer (might have to run tailpipe below treating packer & set packer at a higher depth).Set packer @ 1850'. Keep well SI  
 DAY 3 Rig up pumping company. Test lines to 5000 psi. Test kill switch to 3500 psi. Load backside to 500 psi. Establish rate and pressure using brine. Perform block job with 5000 gal 15# NEPE HCL acid and 10000# salt (4 acid stages and 3 block stages). Shut in well. Rig down pumping equipment. Flow back well to tank (-1.5x load volume and until pH > 6). Flow well overnight to tank.  
 Day 4Continue to flowback until pH > 6 OR pump water to circulate the salt down the perms  
 Release packer and circulate produced water to kill well. TOH w/ packer and workstring and LD. RIH w/ fibreglass tubing and injection packer.  
 Set packer @1930' and shut in well. ND BOP NU WH. Clean well site & RDMO. Return well to injection/disposal status Test disposal rate capacity of the well post job.  
 Any other rate tests required? Step rate etc?)

Spud Date:  Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C Smith TITLE Senior Regulatory Analyst DATE 7-11-2013

Type or print name Rita C Smith E-mail address: rsmith@hess.com PHONE: 432-758-6726

**For State Use Only**  
 APPROVED BY: Ed Martin TITLE **DISTRICT SUPERVISOR** DATE 7/17/2013

No FURTHER TESTING REQUIRED AT THIS TIME.

**WBDGU 1830 271F Workover Procedure**

Date: 05/21/2013

Well name:	WBDGU 1830 271F
API#	3002120540
KB/GL	3421/3410'
Surface size/weight	14" 104.2# @ 40'
Intermediate Casing size/wt	8 5/8" 24# @ 776'
Prod casing size/weight	5 1/2" @ 2251'
PBTD	
HTD	2260'
DOD	2260'
Tubing size	2 7/8" fiberglass @ 1960'
Perfs	2030'-2055'
Open Hole	2251' -2260'

**Engineer:** Madhuram Shah- Cell: 832-491-4519, email: mshah@hess.com**WO Summary:**

Well has low injectivity. WO plan is to MIRU, pull tbg and LD, perforate additional zone, perforate block acid job, flowback acid, run tbg and set packer and return the well back to injection

**NOTE's:****Need workstring, jars, bits, elevators/slips**  
Well will be re perfed in the upper zone & lower zone to increase injectivity

Day	Description	Daily Shop Sheet
1	MIRU pulling unit, and equipment. Set up and hook tanks. Unset packer and circulate casing with produced water to kill well. (If packer wont unset, run in w/plug and set plug in packer, pull off from packer & TOH w/fiberglass tbg & LD. PU & TIH w/ workstring & latch onto packer. TOH w/workstring & packer).ND WH & NU BOPs. TOOOh and standback fiberglass tubing and packer. Ensure casing is loaded w/produced water to keep well dead. CI well.	MIRU. TOOOh w/tbg & packer
2	MIRU wireline services. Tag PBTD to determine fill. Get on depth w/CL and perforate from 2004' - 2030' & 2075' - 2115' w/ 2 spf. RDMO wireline services. If fill found, TIH w/ bit and clean out. TOH w/bit and LD. PU & RIH w/ workstring and treating packer (might have to run tailpipe below treating packer & set packer at a higher depth).Set packer @ 1850'. Keep well SI	Perforation job
3	Rig up pumping company. Test lines to 5000 psi. Test kill switch to 3500 psi. Load backside to 500 psi. Establish rate and pressure using brine. Perform block job with 5000 gal 15% NEFE HCL acid and 10000# salt (4 acid stages and 3 block stages). Shut in well. Rig down pumping equipment. Flow back well to tank (~1.5x load volume and until pH > 6). Flow well overnight to tank.	Pump Acid Block Job
4	Continue to flowback until pH > 6 OR pump water to circulate the salt down the perfs	Flowback or Swab back acid load
5	Release packer and circulate produced water to kill well. TOH w/ packer and workstring and LD. RIH w/ fiberglass tubing and injection packer. Set packer @ 1930' and shut in well.	LD workstring & TIH w/injection tubing
6	ND BOP NU WH. Clean well site & RDMO. Return well to injection/disposal status	RDMO & return to injection
	Test disposal rate capacity of the well post job. Any other rate tests required? Step rate etc?)	Test well