Office Office	State of New 1	Mexico	Form C-103			
District I – (575) 393 6161	Energy, Minerals and N	atural Resources	Revised July 18 2013			
1625 N French Dr Hobbs NM 88240			WELL API NO			
District II - (575) 748 1283 811 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION		30-059 20485				
District III – (505) 334 6178	orr b This by Talesia Tim 60210		5 Indicate Type of Lease			
1000 Rio Brazos Rd Aztec NM 87410	000 Rio Brazos Rd Aztec NM 87410		FEE Surface and Minerals			
<u>District IV</u> – (505) 476 3477 1220 S St Francis Dr Santa Fe NM	Sainta Pe, INIVI	87303	6 State Oil & Gas Lease No			
87505						
	CES AND REPORTS ON WEL	LS	7 Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOS.			Sofia			
DIFFERENT RESERVOIR USE APPLICATION PROPOSALS)	ATION FOR PERMIT (FORM C 101	FOR SUCH				
·	Gas Well Other CO2		8 Well Number 1			
2 Name of Operator	Jus Well Giller CO2		9 OGRID Number			
Kodiak Petroleum (Montana), Inc			257794			
3 Address of Operator			10 Pool name or Wildcat			
Cannot be Located Well Declared C	Ornhaned by Order R-14049 in	Case 15323	Wildcat CO2 – Never Hooked Up			
~	Whiteat CO2 – Never Hooked Op					
4 Well Location '						
Unit Letter D (Lot 1) 305 f	eet from the North line and 120	0 feet from the West	line			
Section 18 Township 25 N	orth Range 30 East NMPM U	nion County				
11 Elevation (Show whether DR RKB RT GR etc.)						
The state of the s	6261 GL		The state of the s			
12 Check A	ppropriate Box to Indicate	Nature of Notice	Report or Other Data			
	FF1-0F1 = 011 to =1-0-1-0-1-0		, respect of outer Duta			
NOTICE OF INT	TENTION TO	l sue	SSEQUENT REPORT OF			
PERFORM REMEDÍAL WORK	PLUG AND ABANDON X	REMEDIAL WOR				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DF	RILLING OPNS P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB			
DOWNHOLE COMMINGLE						
CLOSED LOOP ŠYSTEM						
OTHER		OTHER				
13 Describe proposed or comple	eted operations (Clearly state a	Il pertinent details ar	nd give pertinent dates including estimated date			
		AC For Multiple Co	ompletions Attach wellbore diagram of			
proposed completion or reco	mpletion					
Estimated Start Date June 12	2 2017					
Plug and Abandon						
		sa Perforations 7-inc	h casing shoe and surface plug			
See Attached Procedure and	Diagrams					
I hereby certify that the information a	bove is true and complete to the	best of my knowleds	ge and belief			
. 1 .						
GIGNATURE // TO	mymy p. c	D	ATT (15/0045			
SIGNATURE / Jones	TITLE Supe	ervisor District IV DA	ATE 6/5/2017			
Type or print name Walles W. James	E mail address	a @atata mar DIYO	NE 505 410 1005 W!- C !!			
Type or print name William V Jones	E man address williamy jone	swstate nm us PHO	NE 303-419 1993 Work Cell			
For State Use Only						
APPROVED BY William V. Jones T.	ITI E Suparuson District IV E	ATE 6/5/2017				
APPROVED BY William V Jones To Conditions of Approval (if any) See		AIE 0/3/201/				
Conditions of Approval (II any) See A	Anacheu Frocedure					

PLUG & ABANDONMENT PROCEDURE

March 18, 2017

Sofia #1

Wildcat

305' FNL and 1200' FWL, Section 18, T-25 N, R-30-E Union County, New Mexico, API 30-059-20485 Lat / Long


Note All cement volumes use 100% excess outside pipe and 50' excess inside The stabilizing wellbore fluid will be 8 3 ppg, sufficient to balance all exposed formation pressures All cement will be Class B, mixed at 15 6 ppg with a 1 18 cf/sx yield

- 1 This project will use a steel waste pit to handle waste fluids from the well and cement was up
- 2 Comply with all NMOCD safety regulations MOL and RU single daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary. ND wellhead and NU BOP. Function test BOP.
- 3 Prepare a 2 375" tubing workstring and round trip a 4 5" string mill to 2020' TIH and set 4 5" cement retainer at 2000' Pressure test tubing to 1000 PSI Attempt to load the casing with water and circulate the well clean, note the two sets of open perforations may cause plug #1 to be unbalanced
- 4 Plug #1 (Yeso and Glorietta perforations and San Andres tops, 2132' to 1728') Step 1) Mix and pump 45 sxs Class B cement squeeze all 45 sxs under the CR and sting out Reverse circulate casing clean if have circulation to surface Step2) Mix and pump 90 sxs cement, with the casing valve shut, squeeze 48 sxs outside the casing and spot 42 sxs above the CR inside the casing (Note step 1 100% cement excess in/outside the casing from 2132' to 2000', and step 2 100% excess in/outside from 2000' to 1728') TOH and WOC TIH and tag TOC, reset plug if necessary TOH with tubing
- Plug #2 (Santa Rosa perforations and top, 1466' to 1150') Set a 4.5 cement retainer at 1250'
 Load the well with water and then circulate clean Pressure test casing to 800 PSI <u>If casing does not test, then spot or tag subsequent plugs as appropriate</u> Mix and pump 80 sxs cement, squeeze 70 sxs under the CR and spot 10 sxs above inside the casing PUH
- 6 Plug #3 (7" Surface casing shoe, Chinie and Exeter tops, 859 to 678') Mix 20 sxs and spot a balanced plug inside the casing to cover the casing shoe and formation top PUH to 100'
- Plug #4 (Surface plug, 248' to Surface) Attempt to pressure test the Bradenhead annulus to 300 PSI, note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 20 sxs cement and spot a balanced plug from 100' to surface, circulate good cement out casing valve. LD tubing. If BH annulus does not test, then after filling the inside, ND BOP and cut off WH. RIH with a 1-1/4" tremie pipe into annulus to 100'. Mix and pump 10 sxs tolfill the BH annulus to surface. POH with tremie pipe.
- 8 ND BÔP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per plant stipulations.

OWNER

SOFIA #1

Current Well



MD 2189 PBTD 2142

6 hole

4 5 10 5# J 55 Casing set @ 2189
Cement with 275 sxs and
75 sxs celloflake + cedar fiber
plugged off at float collar no cement in annulus

SOFIA #1

Proposed P&A

Wildcat

Spud 3/12/2008

305' FNL & 1200 FWL, Section 18, T-25-N, R-30-E, Union County, NM

Today's Date 3/18/17 Elevation 6261 GL Completed 05/05/2008

Lat 36 407472 / Long -103 790406 / API #30-059-20485

Dakota Sandstone @198

Top Pump Down 100 sxs in annulus

Morrison Formation @ 354

Plug #4 248' to surface With Class B cement 20 sxs

Exeter Sandstone @ 728

Plug #3 859 - 678 With Class B cement 20 sxs

Chinle Formation @ 750

7 20# J 55 Casing set @ 809 Cmt with 240 sxs (Circ to Surface 1 bbl)

10 hole

Bottom of cement at 1100' (CBL)

Santa Rosa Sandstone @ 1358

Plug #2 1466 – 1150 with Class B cement 80 sxs 70 sxs under and 10 above

Set 4 5 CR @ 1250'

Santa Rosa Perforations 1300 – 1345 1438 – 1466

Annulus Cement - unknown

Plug #1 2132' - 1728 with Class B cement 135 sxs 45 sxs below CR, then 90 sxs above squeeze 48 sxs outside

Glorietta Perforations 1874 - 1970

Set 4 5' CR @ 2000

Middle Yeso Perforations 2092' 2132 (160 holes)

4 5" 10 5# J 55 Casing set @ 2189 Cement with 275 sxs and 75 sxs celloflake + cedar fiber plugged off at float collar

San Andres Formation @ 1778

Glorietta Sandstone @1880

Yeso Formation @ 2000

6 hole

MD 2189 PBTD 2142

WVJONES (DISTRICT IV SUPERVISOR FOR OCD)

Wells

Operators

Operator Data

OCD Review

OCD Only

Administration

OCD Permitting

Land Searches

Land Details

Section 18-25N-30E

Normal

Total Acres 644 4

SOFIA #1 30-059-20485

County Union (59)									
0(1)	C (C)		B (B)		A (A)				
-Sederal 1	Fee ¹		Fee ¹	Ì	Fee ¹				
federal ² ,	Fee ²		Fee ²		Fee ²				
(59) 40 81	(59)	40	(59)	40	(59)	40			
E (2)	F (F) 1		G (G)		H (H)				
Enderal 1	Fee ¹		Fee ¹		Fee ¹				
Ebderet ²	Fee 2		Fee ²		Fee ²				
(59) 41 01	(59)	40	(59)	40	(59)	40			
L(3)	K (K)		J (J)		I (I)				
Federal	Fee 1		Fee ¹		Fee ¹				
Pederal	Fee ²		Fee ²		Fee ²				
(59) 41.2	(59)	40	(59)	40	(59)	40			
M (4) -	N (N)		O (O)		P (P)				
Fedoral	Fee 1		Fee ¹	ļ	Fee ¹				
Federal	Fee ²		Fee ²		Fee ²				
(59) 41 38	(59)	40	(59)	40	(59)	40			

Note 1 ≠ Surface Owner Rights

Note 2 = Sub Surface Mineral Rights

Land Restrictions

No land restrictions found for this section

Return to Search

New Mexico Energy Minerals and Natural Resources Department | Copyright 2012 1220 South St. Francis Drive | Santa Fe. NM 87505 | P. (505) 476-3200 | F. (505) 476-3220

> EMNRD Home OCD Main Page OCD Rules Help