

2364

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

District I
1625 N. French Dr., Hobbs, NM 88240

District II
1301 W. Grand Avenue, Artesia, NM 88210

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

FEB 24 2010

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Release Notification and Corrective Action**OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (575) 397-8251
Facility Name North Hobbs Unit Satellite #25 Trunk line	Facility Type Production

Surface Owner State of New Mexico	Mineral Owner Occidental Permian Limited Partnership	Lease No. 1RP-2364
--------------------------------------	---	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
'J'	25	18-S	37-E					LEA

Latitude North 32.71832° Longitude West 103.20002°**NATURE OF RELEASE**



Type of Release Crude Oil and Produced Water	Volume of Release 2 Bbls Oil X 15 Bbls Water	Volume Recovered 1 Bbls Oil X 10 Bbls Water
Source of Release 8" fiberglass trunk line	Date and Hour of Occurrence 11/26/2009 08:00 AM	Date and Hour of Discovery 11/26/2009 08:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.* An 8" fiberglass trunk line that is used to carry produced fluid from North Hobbs Unit Satellite #25 to the North Hobbs Unit Central T/B developed a leak causing spill. Isolated the trunk line by shutting valves at both ends.

Describe Area Affected and Cleanup Action Taken.* Area affected is approximately 50' X 100' of pasture to the east of NHU Satellite #25. All fluid possible was recovered via vacuum truck. Affected area was remediated to NMOCD guidelines for spills. Verbal permission given on 02/10/2010 to close site after reviewing soil analysis data. Work at this site was completed on 02/19/2010.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop		ENV. ENGINEER: Approved by District Supervisor: 	
Title: HES Specialist		Approval Date: 03/26/10	Expiration Date:
E-mail Address: Steven_Bishop@oxy.com		Conditions of Approval:	
Date: 02/23/2010 Phone: (575) 397-8251		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

DEC 22 2015



Occidental Permian Limited Partnership

February 23, 2010

New Mexico Oil Conservation Division
District I
1625 N. French Drive
Hobbs, New Mexico 88240

RECEIVED

**FEB 24 2010
HOBBSOCD**

Attn: Environmental Engineering

RE: Final Closure Letter
North Hobbs Unit Sat. #25 Trunk line
UL 'J', Sec. 25, T-18-S, R-37-E
1RP-2364

Leak occurred on 11/26/2009, at approximately 08:00 AM. An 8" fiberglass trunk line used to transfer fluid from North Hobbs Unit Satellite #25 to the North Hobbs Unit Central T/B developed a leak causing spill. Valves on both ends of the trunk line were shut to isolate leak. The line operates between 35 and 40 pounds and North Hobbs Unit Satellite #25 produces approximately 400 barrels of total fluid per day. The exact throughput of the line is unknown since there are 2 trunk lines that transfer produced fluid from this satellite. The area affected by this spill is an area measuring approximately 50' X 100', in the pasture directly east of Satellite #25 east fence. Approximately 17 barrels total was spilled, 2 barrels oil and 15 barrels of water. 1 barrel of oil and 10 barrels of water was recovered via vacuum trucks. The State of New Mexico is the surface owner. Depth to ground water according to State Engineers Office is an average of 42', for all wells in the area, giving this spill site a ranking of 20. Remediation of the spill site was as follows:

1. Piping was excavated and repaired.
2. Affected area was excavated and soil hauled to an approved site, Sundance Services, Parabo Facility near Eunice, NM.
3. Soil samples were obtained from affected area.
4. NMOCD guidelines were used to insure site is in compliance with guidelines.
5. Soils removed were replaced with clean fresh soils, where needed.
6. Soil analysis data is attached to this final closure letter.

February 23, 2010

Page 2

Met with Mr. Geoff Leking on 02/10/2010 and was given verbal permission to close this site. Lines excavation was filled and remediated area was covered with fresh soil. Work was completed on 02/19/2010. No further work is planned for this site. If you have any questions, or if I can be of further assistance, please contact me at (575) 397-8251.

A handwritten signature in black ink that reads "Steven M. Bishop". The signature is written in a cursive style with a large, stylized 'S' at the beginning.

Steven M. Bishop

HES Specialist

Steven_Bishop@oxy.com

(575) 397-8251

Attachments: Final C-141


Hand drawn map showing sample points

Cardinal Laboratories soil analysis data dated 02/14/2010 (2 pages)

OXY/NHU - Satellite #25

2-1-10

OXY PLANT





PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC.
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO (575) 397-0397

Receiving Date: 02/08/10
Reporting Date: 02/12/10
Project Owner: NOT GIVEN
Project Name: NHU SAT. #25
Project Location: HOBBS, NM


Sampling Date: 02/08/10
Sample Type: SOIL
Sample Condition: COOL & INTACT @ 5°C
Sample Received By: JH
Analyzed By: AB/ZL/HM


LAB NO.	SAMPLE ID	GRO (C ₈ -C ₁₀) (mg/kg)	DRO (C ₁₀ -C ₂₈) (mg/kg)	BENZENE (mg/kg)	TOLUENE (mg/kg)	ETHYL BENZENE (mg/kg)	TOTAL XYLENES (mg/kg)	CI* (mg/kg)
ANALYSIS DATE:		02/11/10	02/11/10	02/11/10	02/11/10	02/11/10	02/11/10	02/09/10
H19228-1	SP 1	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300	272
H19228-2	SP 2	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300	32
H19228-3	SP 3	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300	< 16
H19228-4	SP 4	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300	352
Quality Control		526	510	0.044	0.044	0.045	0.132	510
True Value QC		500	500	0.050	0.050	0.050	0.150	500
% Recovery		105	102	88.0	88.0	90.0	88.0	102
Relative Percent Difference		1.0	3.3	<1.0	<1.0	<1.0	<1.0	2.0

METHODS: TPH GRO & DRO - EPA SW-846 8015 M; BTEX - SW-846 8021B; CI- Std. Methods 4500-CI-B

*Analyses performed on 1:4 w/v aqueous extracts. Reported on wet weight.

TEXAS NELAP ACCREDITATION T104704398-08-TX FOR BENZENE, TOLUENE, ETHYL BENZENE,
AND TOTAL XYLENES. Not accredited for GRO/DRO and Chloride.


Lab Director


Date

H19228 TBCL BBC

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

1. The first part of the document is a list of the names of the persons who have been appointed to the various positions of the Board of Directors of the Corporation.

2. The second part of the document is a list of the names of the persons who have been appointed to the various positions of the Board of Directors of the Corporation.

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476

