PLUGGING PROCEDURE

Lobo Production Co. Gulf State 36-1 A-36-23N-06W 30-043-20660

· .

Presumed downhole conditions and equipment See attached schematic

Pull all production equipment and nipple up BOP

- 1. Go in hole with tbg. and set a plug from PBTDof 5557 ft. to 4980 ft. WOC & tag cement.
- 2. Load hole with 8.4 lb. 40 visc. Mud and test casing.
- 3. Pull tbg. To 4200 ft. and spot a plug from 4200 ft to 3940 ft.
- 4. Pull tbg. To 1980 ft. And spot a plug from 1980 ft. To 1365 ft.
- 5. Pull tbg. To 260 ft. And spot a plug fro 260 ft. To surface
- 6. Top off csg. with cement and set a dry hole marker.
- 7. Restore location.





