

**Sierra Blanca Operating Company
North Caprock Queen Unit # 14
30-025-00262
UL N, Sec 8, T13S, R32E
Plugging Procedure**

**10 .75 casing set 278 feet, Cement circulated
7" casing set 3033 feet, Cement circulated
5 1/2" liner set at 3043 feet, Top of liner at 2914 feet, Cement circulated
Top salt at 1685 feet
Base salt at 2490 feet**

Well fluids will be circulated to steel pit or plastic lined earthen pit

- 1. Move in rig up plugging unit**
- 2. Nipple up BOP**
- 3. Pull production equipment**
- 4. Run and set CIBP at 2900 feet**
- 5. Run tubing open ended and tag CIBP at 2900 feet**
- 6. Displace well with gelled brine water**
- 7. Spot 25 sacks Class C cement**
- 8. Pull tubing and WOC**
- 9. Run tubing and tag top of cement plug**
- 10. Pull tubing to 1735 feet**
- 11. Spot 25 sacks Class C cement**
- 12. Pull tubing to 350 feet**
- 13. Spot 30 sacks Class C cement**
- 14. Pull tubing and WOC**
- 15. Run tubing and tag cement plug, Maximum depth 228 feet**
- 16. Pull tubing to 60 feet**
- 17. Circulate cement to surface**
- 18. Pull tubing**
- 19. Cut off well head and install PA marker**
- 20. Rig down move out plugging rig**
- 21. Cut off service unit anchors and clean location**

