

**Leigh Operating Co.
Caudill State # 1
API # 30-025-27461
UL K, Sec 26, T15S, R36E
Plugging Procedure**

13 3/8" csg set 420 feet, Cement Circulated

9 5/8" csg set 4981 feet, Cemented with 1300 sacks, Calculated cement should have circulated in gauge hole

5 1/2" csg set 13780 feet, Cement with 1950 sacks, Calculated TOC 4671 feet

Perfs 13730-13748 feet

- 1. Move in rig up plugging rig**
- 2. Nipple up BOP**
- 3. Pull production equipment**
- 4. Run gauge ring with wire line to 13690 feet**
- 5. Pull wire line and tools**
- 6. Run and set Cast Iron Bridge Plug at 13690 feet**
- 7. Cap CIBP with 35 feet of cement with dump bailer**
- 8. Run tubing open ended and tag cement at 13655 feet**
- 9. Displace well with gelled brine water**
- 10. Pull tubing to 11542 feet**
- 11. Spot 25 sack cement plug**
- 12. Pull tubing to 8350 feet**
- 13. Spot 25 sack cement plug**
- 14. Pull tubing to 6525 feet**
- 15. Spot 25 sack cement plug**
- 16. Pull tubing to 5031 feet**
- 17. Spot 25 sack cement plug**
- 18. Pull tubing and WOC**
- 19. Run tubing and tag cement plug, Maximum depth 4931 feet**
- 20. Weld on pull nipple and stretch casing**
- 21. Cut and pull casing from 4000 feet if free**
- 22. Run tubing to 50 feet inside of casing stub**
- 23. Spot 40 sack cement plug**
- 24. Pull tubing and WOC**
- 25. Run tubing and tag cement plug, Maximum depth is 50 feet above casing stub**
- 26. Pull tubing to 2075 feet**
- 27. Spot 40 sack cement plug**
- 28. Pull tubing to 470 feet**
- 29. Spot 40 sack cement plug**
- 30. Pull tubing and WOC**
- 31. Run tubing and tag cement plug, Maximum depth 370 feet**
- 32. Pull tubing to 60 feet**
- 33. Circulate cement to surface**
- 34. Pull tubing**
- 35. Cut off wellhead and install PA marker**
- 36. Rig down move out plugging rig**
- 37. Cut off service unit anchors and clean location**

