

OCD EXHIBIT NO. 4

CASE NO. 12792

Kelly H. Baxter
State FP # 1
Plugging Procedure

13 3/8 csg set at 300 ft cement circulated 300 sx
8 5/8 csg set at 4500 ft cemented with 500 sx, estimated TOC 1905 feet
5 1/2 csg set at 11540 ft cement with 375 sx, TOC 9634FT
Perfs 10710-10768, 11254-11270,

- 1) Move in rig up service unit
- 2) Nipple up BOP
- 3) Run sinker bar by wireline to check PBTB
- 4) Run Gauge ring to 10660 feet
- 5) Run and set CIBP at 10660 feet
- 6) Cap CIBP with 35 foot of cement by dump bailer
- 7) Run tubing to 10610 feet displace well with mud laden fluid
- 8) Pull tubing
- 9) Weld on pull nipple and stretch 5 1/2" casing
- 10) Cut and pull 5 1/2" casing from freepoint
- 11) Run tubing to 50 feet inside casing stub
- 12) Spot 35 sx cement at casing stub
- 13) Pull tubing and WOC
- 14) Run tubing and tag cement plug
- 15) Pull tubing to 8000 feet and spot 25 sx cement
- 16) Pull tubing to 5991 feet and spot 25 sx cement
- 17) Pull tubing to 4550 feet and spot 35 sx cement
- 18) Pull tubing and WOC
- 19) Run tubing and tag cement plug, maximum depth 4450 feet
- 20) Pull tubing
- 21) Weld on pull nipple and stretch 8 5/8" casing
- 22) Cut and pull casing from freepoint
- 23) Run tubing to 50 feet inside of 8 5/8" casing stub
- 24) Spot 60 sx cement
- 25) Pull tubing and WOC
- 26) Run tubing and tag cement plug
- 27) Pull tubing to 350 feet
- 28) Spot 60 sx cement
- 29) Pull tubing and WOC
- 30) Run tubing and tag cement plug, maximum depth is 250 feet
- 31) Pull tubing to 60 feet and circulate cement to surface
- 32) Cut off wellhead and install PA marker
- 33) Rig down move out service unit
- 34) Cut off anchors 1 foot below ground level and clean location