

**Kelly H. Baxter  
Plugging Procedure  
Speight SWD #2**

- 1) Move in rig up plugging unit
- 2) Nipple up BOP
- 3) Release packer and pull tubing and packer
- 4) Run sinker bar with wireline and tag PBTD
- 5) Run gauge ring to 11800 feet
- 6) Run and set cast iron bridge plug at 11800ft
- 7) Cap CIBP with 35 feet of cement with dump bailer
- 8) Run tubing to 11760 feet and displace well with mud laden fluid
- 9) Pull tubing to 9600 feet and spot 40 sx cement across perfs
- 10) Pull tubing and WOC
- 11) Run tubing and tag cement plug, maximum depth 9518 feet
- 12) Pull tubing
- 13) Run 4" casing guns and perforate 7" casing at 7950 feet with 4 shots
- 14) Pull wire line and perf guns
- 15) Run cement retainer and set at 7850 feet
- 16) Squeeze perfs with 60 sx cement
- 17) Sting out of retainer and pull tubing
- 18) Run 4" casing guns and perforate 7" casing at 6050 feet with 4 shots
- 19) Pull wire line and perf guns
- 20) Run cement retainer and set at 5950 feet
- 21) Squeeze perfs with 60 sx cement
- 22) Sting out of retainer and pull tubing
- 23) Run tubing open ended to 4348 feet
- 24) Spot 60 sx cement
- 25) Pull tubing and WOC
- 26) Run tubing and tag cement plug, maximum depth 4248 feet
- 27) Pull tubing to 2383 feet Spot 60 sx cement
- 28) Pull tubing to 410 feet and spot 60 sx cement
- 29) Pull tubing and WOC
- 30) Run tubing and tag cement plug, maximum depth 310 feet
- 31) Pull tubing to 60 feet and circulate cement to surface
- 32) Cut off well head and install PA marker
- 33) Rig down and move out service unit
- 34) Cut off anchors 1 foot below ground level and clean location

BEFORE EXAMINER CATANACH	
OIL CONSERVATION DIVISION	
<u>OCD</u>	EXHIBIT NO. <u>25</u>
CASE NO. <u>12792</u>	