Submit 1 Copy To Appropriate District Office	State of New Mexico		CD-REC'D 10/29/2020 Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-015-44407
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		 Lease Name or Unit Agreement Name Striker 3 	
PROPOSALS.) 1. Type of Well: Oil Well	Type of Well: Oil Well Gas Well Other: Saltwater Disposal		8. Well Number 001
2. Name of Operator: NGL Water Solutions Permian, LLC		9. OGRID Number 372338	
3. Address of Operator: 3773 Cherry Creek N. Drive, Suite 1000, Denver, CO 80209		10. Pool name or Wildcat: Devonian	
4. Well Location	m the South line and 207 fact from th	a East line	<u> </u>
	m the South line and 897 feet from th Township 23S		NMPM 6 County Eddy
Section 33	Township23SRange28ENMPM6CountyEddy11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	11. Elevation (Snow whether DR, R		
12. Check A	Appropriate Box to Indicate Nat	ture of Notice,	Report or Other Data
NOTICE OF IN		SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	ERFORM REMEDIAL WORK 🔄 PLUG AND ABANDON 📃 🛛 REMEDIAL WORK 🖾 ALTERING CASIN		
TEMPORARILY ABANDON			
PULL OR ALTER CASING		CASING/CEMEN	T JOB
CLOSED-LOOP SYSTEM		OTHER:	
13. Describe proposed or compl	leted operations. (Clearly state all per ork). SEE RULE 19.15.7.14 NMAC.	rtinent details, an	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
Pressure found on	tubing casing annulus.		
Shut well in and sta	arted workover.		
Found leak in tubin	ng cross-over sub (i.e. swedge from 5	-1/2" to 4-1/2").	
Replace cross-over	r sub and re-run tubing.		
Performed mechan	ical integrity test and return to injecti	on.	
Tune 9, 2020		June 26 20°	20
pud Date: June 9, 2020	Rig Release Date	June 26, 202	20
hereby certify that the information a	above is true and complete to the best	t of my knowledg	e and belief.
	above is true and complete to the best		
hereby certify that the information a	above is true and complete to the best	t of my knowledg	e and belief. DATE 10/30/2020

