# SITE INFORMATION

#### Cleaning Banart pMI P1011252606 Donort T

Report Type: Closure Report NVLB1011352696						
General Site Info	ormation:					
Site:		James A Battery				
Company:		ConocoPhillips				
Section, Township and Range		Unit Letter J	Sec. 2	T 22S	R 30E	
Lease Number:		Associated API No.	30-015-25699		·	· · · ·
County:		Eddy				
GPS:		3	2.418694			-103.849278
Surface Owner:		State			-	
Mineral Owner:		N/A				
Directions:		Depart from Loving. H Carter Rd (CR-712) for right onto Jal Hwy (NM Turn slightly left onto Arrive at location. Site	Depart from Loving. Head toward Amy Ave on N 8th St (US-285) for 0.4 mi. Turn right onto Carter Rd (CR-712) for 1.4 mi. Turn right onto Potash Mines Rd (NM-31) for 6.5 mi. Turn right onto Jal Hwy (NM-128) for 8.7 mi. Turn left onto Cimarron Rd (CR-796) for 2.6 mi. Turn slightly left onto Cimarron Rd (CR-796) for 3.9 mi. Turn right onto CR-796A for 1.9 mi. Arrive at location. Site is on the right			
Release Data:						
Date Released:		4/22/2010				
Type Release:		Produced Water				
Source of Contar	mination:	Transition Line				
Fluid Released:		12 bbl				
Fluids Recovered	d:	0 bbl				
Official Commun	nication:					
Name:	Marvin Soriwei				Christian M	Л. Llull
Company:	Conoco Phillips - F	RMR			Tetra Tech	1
Address:	935 N. Eldridge Pk	WV.			8911 North	n Capital of Texas Hwy.
	Ŭ	, ,			Building 2	Suite 2310
City:	Houston Texas 77	070				vas
Olly. Dhana numhari		019			Austin, 16.	2004
	(032) 400-2730				(512) 336-	2001
Fax:		1.111				
Email:	Marvin.Soriwei@	conocophillips.com			christian.	lull@tetratech.com
	-					
Site Characteriz	ation					
Depth to Groundv	water:		262' below surfac	ce		
Impact to ground	water or surface wa	ter:	No			
Extents within 30	0 feet of a watercou	rse:	No			
Extents within 200 feet of lakebed, sinkhole, or playa lake:			No			
Extents within 300 feet of an occupied structure:			NO			
Extents within 1000 foot of any water well or spring:			No			
Extents within incorporated municipal well field:			No			
Extents within 30	0 feet of a wetland:		No			
Extents overlying	a subsurface mine	:	No			
Karst Potential:			High			
Extents within a 100-year floodplain:			No			

Impact to areas not on a production site: No				
Recommended I	Remedial Action Le	vels (RRALs)		
Benzene	Total BTEX	TPH (GRO+DRO)	TPH (GRO+DRO+MRO)	Chlorides
10 mg/kg	50 mg/kg		100 mg/kg	600 mg/kg



March 30, 2021

Mike Bratcher District Supervisor Oil Conservation Division, District 2 811 S. First St. Artesia, NM 88210

Re: Closure Report ConocoPhillips James A Battery Line Release Unit Letter J, Section 2, Township 22 South, Range 30 East Eddy County, New Mexico 2RP-406 Incident ID nMLB1011352696

Dear Mr. Bratcher:

Tetra Tech, Inc. (Tetra Tech) was contacted by ConocoPhillips (COP) to assess a release that occurred from a transition line at the James A Battery. The release point is located on the James A Battery production pad, which is shared with the plugged and abandoned James A #002 well (API No. 30-015-25699). The release footprint is located in Public Land Survey System (PLSS) Unit Letter J, Section 2, Township 22 South, Range 30 East, in Eddy County, New Mexico (Site). The approximate release point occurred at coordinates 32.418694°, -103.849278°, as shown on Figures 1 and 2.

### BACKGROUND

According to the State of New Mexico C-141 Initial Report, on April 22, 2010 a release occurred from a 1inch hole on a 3-inch transition line at the James A Battery due to internal corrosion. The release consisted of approximately 12 barrels (bbls) of produced water, of which none were recovered. The release reportedly affected a 741-ft by 3-ft area of caliche pad and pasture. The New Mexico Oil Conservation District (NMOCD) approved the initial C-141 on April 23, 2010 and subsequently assigned the release the Remediation Permit (RP) number 2RP-406 and the Incident ID nMLB1011352696. The initial C-141 form is included in Appendix A. The 2RP-406 release is included in an Agreed Compliance Order-Releases (ACO-R) between COP and the NMOCD signed on May 7 and 9, 2019, respectively.

### SITE CHARACTERIZATION

A site characterization was performed and no lakebeds, sinkholes, playa lakes, residences, schools, hospitals, institutions, churches, springs, private domestic water wells, springs, wetlands, incorporated municipal boundaries, subsurface mines, or floodplains are located within the specified in 19.15.29 New Mexico Administrative Code (NMAC). However, the site is in a high karst potential area.

The Site is within a New Mexico oil and gas production area. According to the New Mexico Office of the State Engineers (NMOSE) reporting system, there are no water wells within 800 meters (approximately <sup>1</sup>/<sub>2</sub>

mile) of the Site. Based on available data from one (1) water well located within 5,600 meters (approximately 3.5 miles) of the Site, the average depth to groundwater is 262 ft below ground surface (bgs). The site characterization data is included in Appendix B.

### **REGULATORY FRAMEWORK**

Based upon the release footprint and in accordance with Subsection E of 19.15.29.12 NMAC, per 19.15.29.11 NMAC, the site characterization data was used to determine recommended remedial action levels (RRALs) for benzene, toluene, ethylbenzene, and xylene (collectively referred to as BTEX), total petroleum hydrocarbons (TPH), and chlorides in soil.

Based on the site characterization (high potential for karst), the RRALs for the Site are as follows:

Constituent	RRAL
Chloride	600 mg/kg
ТРН	100 mg/kg
BTEX	50 mg/kg

### RECORDS REVIEW AND VISUAL SITE INSPECTION

A file search on the NMOCD Online Imaging web application revealed no records of investigation, assessment, or remediation activities taken at the Site, nor communications between agencies regarding the 2RP-406 release. The reported release point from the C-141 is in the pasture east of the battery pad. Based on a review of available historical aerial imagery, the approximate release point occurred approximately 515 ft west-northwest of the coordinates provided on the initial C-141. A cursory review of aerial imagery from October 2010 indicated an approximate footprint that matched the extent described in the initial C-141 (Figure 3).

On behalf of COP, on June 11, 2020 Tetra Tech personnel conducted a visual Site inspection at the 2RP-406 release area to evaluate current conditions at the Site. Photographic documentation from the visual inspection (with GPS coordinates) is included as Appendix C. A list of field observations describing the Site follow:

- No evidence of soil staining was noted in the pasture southwest of the battery.
- No odor was noted in soils on the production pad or in the pasture southwest of the battery.
- Vegetation was noted to be in various stages of growth throughout the pasture area southwest of the battery.

### SITE ASSESSMENT ACTIVITIES

On March 2, 2021, Tetra Tech returned to the Site to conduct field screening of soils to assess the identified release extent for salinity, which would infer the presence of chloride in soil. Soil screening locations were chosen based on the release extent dimensions reported in the C-141 and within the release footprint identified through aerial imagery review. Soils were collected from 0-1 ft bgs at twelve (12) locations (SS-1 through SS-12) within the identified release footprint and screened for salinity using an ExTech EC400 ExStik. Locations SS-1 through SS-5 were located on the caliche production battery pad, SS-6 was located on the caliche lease road west of the battery pad, and SS-7 through SS-12 were located in the pasture southwest of the production battery pad. Figure 3 depicts the approximate release extent and the 2021 soil screening locations. Photographic documentation of the site and the soil screening activities is included in Appendix C.

### SUMMARY OF SOIL SCREENING RESULTS

Results from the March 2021 field soil screening event are presented in Table 1. Salinity concentrations measured in soils associated with three (3) production pad locations (SS-1 through SS-3) ranged from 800

parts per million (ppm) to 850 ppm. Salinity concentrations measured in soils associated with the remaining nine (9) production pad and pasture locations (SS-4 through SS-12) ranged from 100 ppm to 228 ppm. The field screening results from locations SS-4 through SS-12 indicate salinity concentrations which could be inferred as concentrations below the Site RRAL of 600 mg/kg. The field screening results in this area are likely attributed to undocumented remedial actions conducted in the off-pad portions of the former release footprint. Conversely, the salinity concentrations in SS-1 through SS-3 potentially indicate chloride concentrations slightly above the Site RRAL on the battery production pad.

However, the Site is located in an area with abundant potash reserves, and so naturally occurring soluble mineral salts such as sylvite (KCI) would lead to natural variations of chloride in the soils of the region. Given the age of the release and the naturally occurring mineral salts in soil concentrations at depth, there is no evidence that the elevated salinity concentrations on the active battery production pad are attributable to the 2RP-406 release.

### CONCLUSION

ConocoPhillips respectfully requests closure of this release based on the age of the occurrence, depth to groundwater, recent visual inspection, and soil screening data at the formerly impacted surface area. As mentioned, the James A Battery Line Release (2RP-406/ nMLB1011352696) is included in an Agreed Compliance Order-Releases (ACO-R) between COP and the NMOCD signed on May 7 and 9, 2019, respectively. The final C-141 forms are enclosed in Appendix A. If you have any questions concerning the Site, please call me at (512) 338-2861 or Greg at (432) 682-4559.

Sincerely, Tetra Tech, Inc.

Christian M. Llull, P.G. Project Manager

cc: Mr. Marvin Soriwei, RMR – ConocoPhillips

Mr. Charles Beauvais, GPBU - ConocoPhillips

Greg W. Pope, P.G. Program Manager

## Figures:

Figure 1 – Overview Map

Figure 2 – Topographic Map

Figure 3 – Approximate Release Extent & Field Screening Locations

### Tables:

Table 1 – Summary of Soil Screening Results

## Appendices:

Appendix A – C-141 Forms

Appendix B – Site Characterization Data

Appendix C – Photographic Documentation

# FIGURES





JAMESA IAMES A BATTERY/FIGURE 2 TOPO DOCUMENT PATH: D:\CONOCOPHILLIPS\MXD\2RP-406\_



DOCUMENT PATH: D:\CONOCOPHILLIPS\MXD\2RP-406\_JAMES A BATTERY\FIGURE 3 RELEASE\_JAMESA\_BATTE

# TABLES

# TABLE 1 SUMMARY OF SOIL SCREENING RESULTS 2RP-406 CONOCOPHILLIPS JAMES A BATTERY LINE RELEASE EDDY COUNTY, NM

Comula ID	Comula Data	Sample Depth	Field Screening Results	Field Observations
Sample ID	Sample Date		Chloride	Field Observations
		ft. bgs	ppm	
SS-1	3/2/2021	0-1	820	No Staining, No Odor
SS-2	3/2/2021	0-1	850	No Staining, No Odor
SS-3	3/2/2021	0-1	800	No Staining, No Odor
SS-4	3/2/2021	0-1	155	No Staining, No Odor
SS-5	3/2/2021	0-1	145	No Staining, No Odor
SS-6	3/2/2021	0-1	125	No Staining, No Odor
SS-7	3/2/2021	0-1	200	No Staining, No Odor
SS-8	3/2/2021	0-1	228	No Staining, No Odor
SS-9	3/2/2021	0-1	100	No Staining, No Odor
SS-10	3/2/2021	0-1	125	No Staining, No Odor
SS-11	3/2/2021	0-1	155	No Staining, No Odor
SS-12	3/2/2021	0-1	135	No Staining, No Odor

NOTES:

ft. Feet

bgs Below ground surface

ppm Parts per million

APPENDIX A C-141 Forms

RECEIVED APR 2 3 2010

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

# State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-25699

## **Release Notification and Corrective Action**

$\mathcal{T}\mathcal{A}\mathcal{S}\mathcal{A}\mathcal{O}\mathcal{A}\mathcal{S}\mathcal{A}\mathcal{O}\mathcal{O}\mathcal{O}$	PERATOR A	Initial Report	Final Report
Name of Company ConocoPhillips Company 217817 Conta	ntact Jesse A. Sosa		
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5 Telep	lephone No. (505)391-3126		
Facility Name James A Battery Facili	cility Type Oil		

Surface Owner NMOCD

Mineral Owner BLM

Lease No. 3001525699

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	02	228	30E	1652	South	1980	East	Eddy

Latitude N32 25.112' Longitude W103 50.857'

## NATURE OF RELEASE

Source of Release 3" steel line connection adapter       Date and Hour of Occurrence4/22/ (DAtamed Hour of Discovery 4/22/10         Was Immediate Notice Given?       If YES, To Whom?         Mike Bratcher       Mike Bratcher         By Whom? Jesse Sosa       Date and Hour 4/22/10 2:50 pm         Was a Watercourse Reached?       If YES, Volume Impacting the Watercourse.         If a Watercourse was Impacted, Describe Fully.*       If Watercourse was Impacted, Describe Fully.*         Describe Cause of Problem and Remedial Action Taken.*       MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid.         Describe Area Affected and Cleanup Action Taken.*       Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be the defined beneficied Spile provision equivalence of the spill, and the area will	Type of Release Produced Water	Volume of Release 12 BBL Volume Recovered 0 BBL			
Was Immediate Notice Given?       If YES, To Whom?         Mike Bratcher       Mike Bratcher         By Whom? Jesse Sosa       Date and Hour 4/22/10 2:50 pm         Was a Watercourse Reached?       If YES, Volume Impacting the Watercourse.         If a Watercourse was Impacted, Describe Fully.*       If a Watercourse was Impacted, Describe Fully.*         Describe Cause of Problem and Remedial Action Taken.*       MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid.         Describe Area Affected and Cleanup Action Taken.*       Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will have been to be called for the supervision upon discovery of the spill, and the area will have been to be called a called on the back of the supervision upon discovery of the spill, and the area will have been to be called be in the back of the supervision upon discovery of the spill, and the area will have been to be called be added of a line prevision upon discovery of the spill, and the area will have been to be prevent to be added for the supervision upon discovery of the spill have the order of the supervision upon discovery of the spill have the order of the supervision upon discovery of the spill have the order of the supervision upon discovery of the spill have the order of the supervision upon discovery of the spill have the order of the supervision	Source of Release 3" steel line connection adapter	Date and Hour of Occurrence4/22/ (Datarand Hour of Discovery 4/22/10			
X Yes       No       Not Required       Mike Bratcher         By Whom? Jesse Sosa       Date and Hour 4/22/10 2:50 pm         Was a Watercourse Reached?       If YES, Volume Impacting the Watercourse.         If a Watercourse was Impacted, Describe Fully.*       If a Watercourse was Impacted, Describe Fully.*         Describe Cause of Problem and Remedial Action Taken.*       MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid.         Describe Area Affected and Cleanup Action Taken.*       Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will here a will doct the two defined Second	Was Immediate Notice Given?	If YES, To Whom?			
By Whom? Jesse Sosa       Date and Hour 4/22/10 2:50 pm         Was a Watercourse Reached?       If YES, Volume Impacting the Watercourse.         If a Watercourse was Impacted, Describe Fully.*       If YES, Volume Impacting the Watercourse.         Describe Cause of Problem and Remedial Action Taken.*       MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid.         Describe Area Affected and Cleanup Action Taken.*       Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will how conditioned and the tarea will how conditioned and how conditioned and the tarea will how conditioned and the tarea will how conditioned and how conditend and ho	🕅 Yes 🗌 No 🗌 Not Required	Mike Bratcher			
Was a Watercourse Reached?       If YES, Volume Impacting the Watercourse.         If a Watercourse was Impacted, Describe Fully.*       If YES, Volume Impacting the Watercourse.         Describe Cause of Problem and Remedial Action Taken.*       MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid.         Describe Area Affected and Cleanup Action Taken.*       Affected was 741'x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be remericed in the new of the her was new on the metal was new of the spill her there is up and the metar will be remericed in the new of the her was new of the spill, and the area will	By Whom? Jesse Soca	Date and Hour 4/22/10 2:50 nm			
Image: A state of the indext of the index	Was a Watercourse Reached?	If VFS Volume Impacting the Watercourse			
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will here edited in the DEOCOMPT on the field of and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will here edited in the DEOCOMPT on the field of and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will here edited in the DEOCOMPT on the field of and pasture land. So is a supervision upon discovery of the spill, and the area will here edited in the DEOCOMPT on the field of and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will here edited in the DEOCOMPT on the field of and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will here edited in the DEOCOMPT on the field of and pasture land.	Ves X No	If TES, volume impleting the watercourse.			
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be readilited in the DMOCD mean up and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be readilited in the totage to up and appreciate the second section of the spill of the spill.					
Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be readily of the spill of the spill.	If a Watercourse was Impacted, Describe Fully.*				
Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be readily of the spill of the spill.					
Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be readilited in the DEOCOMPONENT of the spill of the spill.					
Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be readilited in the MOCD mean up of a sture land. Notifications were made to supervision upon discovery of the spill, and the area will be readilited in the MOCD mean up of a sture land. Notifications were made to supervision upon discovery of the spill, and the area will be readilited in the MOCD mean up of a sture land. So if a stude of and pasture land will be taken to variable date and the area will be taken to variable date and the stude of a stude of a stude of a stude and be accessed for the spill be taken to variable date and the stude of a stude o					
Describe Cause of Problem and Remedial Action Taken.* MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be removed for a spill be taken to wrife place and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be removed for a spill be taken to wrife place and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be removed for the spill be taken to wrife place and pasture the balance of Scill complex prime will be taken to wrife place and pasture to be an explored for the spill be taken to wrife place and place and the spill be taken to wrife place and p					
MSO located a 1" hole on a 3 inch metal male poly adapter in transition line. The release was due to internal corrosion. The MSO called in a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be removed for a spill of the spill.	Describe Cause of Problem and Remedial Action Taken.*				
a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal component has been removed from service to prevent future corrosion issues. Total spill volume was 12 BPW with 0 bbls recovered fluid. Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will be taken to up of the spill, and the area will be taken to up of the spill.	MSO located a 1" hole on a 3 inch metal male poly adapter in trans	sition line. The release was due to internal corrosion. The MSO called in			
Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will	a vacuum truck, but the remaining produced water could not be picked up prior to soaking in. The line was isolated, and the metal				
Describe Area Affected and Cleanup Action Taken.* Affected was 741' x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will	component has been removed from service to prevent future corros	sion issues. Total spill volume was 12 DF w with 0 0015 recovered link.			
Affected was 741'x 3' of caliche pad and pasture land. Notifications were made to supervision upon discovery of the spill, and the area will	Describe Area Affected and Olegener Action Takes #				
Affected was 741 x 3 of cance pad and pasture rand. Notifications were made to supervision upon discovery of the spin, and the area win	Describe Area Anecieu and Cleanup Action Taken."				
- of redealated to made invalid to was noticed. Not to be danged out and reduced. Noti satisfies with delaker to verify clean on and set in $-1$					
NMOCD (Mike Bratcher) for finalization.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	regulations all operators are required to report and/or file certain release no	otifications and perform corrective actions for releases which may endanger			
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.					
OIL CONSERVATION DIVISION		OIL CONSERVATION DIVISION			
Signature: / (NN) 0 00	Signature: / XUN W / OV	and Alika Kung in			
Approved by District Superviser:	Approved by Protect Supervision				
Printed Name: Jesse A. Sosa	Printed Name: Jesse A. Sosa				
APR 2 3 2010		APR 2 3 2010			
Title: HSER Lead Approval Date: Expiration Date:	Title: HSER Lead	Approval Date: Expiration Date:			
E-mail Address: Jesse. A. Sosa (a) conocophillips.com	E-mail Address: Jesse. A. Sosa(a) conocophillips.com	Conditions of Approval:			
REMEDIATION per OCD Rules and	D . 04/02/010	REMEDIATION per OCD Rules and			
Date: 04/22/2010 Phone: (303)391-3120 Guidelines. SUBMIT REMEDIATION	Date: 04/22/2010 Phone: (505)591-5126 Guid	elines. SUBMIT REMEDIATION			
Attach Additional Sheets It Necessary	Attach Additional Sheets If Necessary	POSAL BY: 5/23/10)			

AMLB1011353322

Form C-141 Page 3 State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

# Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)
Did this release impact groundwater or surface water?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	🗌 Yes 🗌 No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	🗌 Yes 🗌 No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	🗌 Yes 🗌 No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	🗌 Yes 🗌 No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of a wetland?	🗌 Yes 🗌 No
Are the lateral extents of the release overlying a subsurface mine?	🗌 Yes 🗌 No
Are the lateral extents of the release overlying an unstable area such as karst geology?	🗌 Yes 🗌 No
Are the lateral extents of the release within a 100-year floodplain?	🗌 Yes 🗌 No
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	🗌 Yes 🗌 No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

### Characterization Report Checklist: Each of the following items must be included in the report.

	Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
	Field data
	Data table of soil contaminant concentration data
	Depth to water determination
	Determination of water sources and significant watercourses within 1/2-mile of the lateral extents of the release
	Boring or excavation logs
	Photographs including date and GIS information
Ц	Photographs including date and GIS information

- Topographic/Aerial maps
- Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Form C-141	State of New Mexico	Incident ID
Page 4	Oil Conservation Division	District RP
		Facility ID
		Application ID
I hereby certify that the inf regulations all operators ar public health or the enviror failed to adequately investi addition, OCD acceptance and/or regulations. Printed Name: Signature:	formation given above is true and complete to the b- re required to report and/or file certain release notifi nment. The acceptance of a C-141 report by the OC igate and remediate contamination that pose a threa of a C-141 report does not relieve the operator of re	Set of my knowledge and understand that pursuant to OCD rules and cations and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have to groundwater, surface water, human health or the environment. In seponsibility for compliance with any other federal, state, or local laws Title: Date: Telephone:
OCD Only		
Received by:		Date:

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

<b><u>Closure Report Attachment Checklist</u>:</b> Each of the following in	Closure Report Attachment Checklist: Each of the following items must be included in the closure report.					
A scaled site and sampling diagram as described in 19.15.29.11 NMAC						
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)						
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)						
Description of remediation activities						
I hereby certify that the information given above is true and comple and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and ren human health or the environment. In addition, OCD acceptance of a compliance with any other federal, state, or local laws and/or regula restore, reclaim, and re-vegetate the impacted surface area to the con accordance with 19.15.29.13 NMAC including notification to the O Printed Name:	te to the best of my knowledge and understand that pursuant to OCD rules in release notifications and perform corrective actions for releases which a C-141 report by the OCD does not relieve the operator of liability mediate contamination that pose a threat to groundwater, surface water, a C-141 report does not relieve the operator of responsibility for tions. The responsible party acknowledges they must substantially inditions that existed prior to the release or their final land use in CD when reclamation and re-vegetation are complete. 					
OCD Only						
Received by:	Date:					
Closure approval by the OCD does not relieve the responsible party remediate contamination that poses a threat to groundwater, surface party of compliance with any other federal, state, or local laws and/o	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.					
Closure Approved by:	Date:					
Printed Name:	Title:					

# APPENDIX B Site Characterization Data

2RP-406 - Water Bodies



NM OCD Oil and Gas Map. http://nm-emnrd.maps.arcgis.com/apps/webappviewer/index.html?id=4d017f2306164de29fd2fb9f8f35ca75: New Mexico Oil Conservation Division





# New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)	(R=P been O=or C=the close	OD has replacec phaned, e file is d)	l,	(qua (qua	rter	rs a rs a	re 1: re sr	=NW : malles	2=NE 3	3=SW 4= rgest)	=SE) (N∕	) AD83 UTM in me	eters)	(1	n feet)	
		POD Sub-		Q	Q	Q		_						Depth	Depth	Water
POD Number	Code		Count	ty 64	16 2	4	Sec		Rng	6076	<b>X</b>	¥	Distance	Well 410	Water (	Column
C 03003		CUB	ED	3	2	3	31	21S	30E	6105	95 11	3588970*	2780	650		
C 02749		CUB	ED	1	1	1	18	22S	31E	6105	56	3585146* 🌍	3280	640		
C 02750		CUB	ED	1	1	1	18	22S	31E	6105	56	3585146* 🌍	3280	741		
<u>C 02751</u>		CUB	ED	1	1	1	18	22S	31E	6105	56	3585146* 🌍	3280	637		
<u>C 02723</u>		CUB	ED	2	2	3	15	22S	30E	6062	82	3584363* 🌍	3613	651		
<u>C 03002</u>		CUB	ED	4	2	4	06	22S	31E	6119	33	3587375* 🌍	3735	668		
C 03773 POD1	С	CUB	ED	4	2	2	32	21S	30E	6040	39	3589799 🌍	4788	55		
C 03774 POD1	С	CUB	ED	2	4	2	32	21S	30E	6040	39	3589799 🌍	4788	32		
C 02950 EXPL		CUB	ED	4	2	4	23	22S	30E	6087	40	3582576* 🌍	4881	845		
C 03772 POD1	С	CUB	ED	2	4	2	32	21S	30E	6038	59	3589714 🌍	4904	30		
C 03772 POD2	С	CUB	ED	4	2	2	32	21S	30E	6038	50	3589707 🌍	4910	30		
C 03772 POD3	С	CUB	ED	4	2	2	32	21S	30E	6038	40	3589699 🌍	4914	30		
C 03772 POD5	С	CUB	ED	4	2	2	32	21S	30E	6038	23	3589681 🌍	4922	30		
C 03772 POD6	С	CUB	ED	4	2	2	32	21S	30E	6038	14	3589666 🌍	4923	30		
C 03772 POD8	С	CUB	ED	4	2	2	32	21S	30E	6037	97	3589636 🌍	4924	30		
C 03772 POD7	С	CUB	ED	4	2	2	32	21S	30E	6038	05	3589655 🌍	4925	30		
C 03772 POD4	С	CUB	ED	4	2	2	32	21S	30E	6038	24	3589692 🌍	4925	30		
<u>C 02637</u>		CUB	ED	1	3	3	24	22S	30E	6089	50	3582377* 🌍	5105	759		
<u>C 02748</u>		CUB	ED	1	2	3	17	22S	31E	6125	76	3584364* 🌍	5343	3856		
C 03015		CUB	ED	1	4	3	22	22S	30E	6060	99	3582353* 🌍	5491	1316	262	1054

#### \*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

Average Depth to Water: 262 feet Minimum Depth: 262 feet Maximum Depth: 262 feet

Record Count: 21

### UTMNAD83 Radius Search (in meters):

Easting (X): 608198

Northing (Y): 3587427

Radius: 5600

# APPENDIX C Photographic Documentation



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	View facing northeast of former release area on production pad from visual Site inspection. Release Location: 32.418694°, -103.849278°	1
	SITE NAME	James A Battery Line Release	6/11/2020



TETRA TECH, INC. PROJECT NO.	DESCRIPTION	View facing southwest of flowlines in the former release area in the pasture. No stained or odorous soils observed during the visual Site inspection.	2
212C-IMD-02355	SITE NAME	James A Battery Line Release	6/11/2020



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	View facing NE of SS-1 soil screening location on production pad.	3
	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC.	DESCRIPTION	View facing SW from SS-1 soil screening location of production pad.	4
212C-MD-02355	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	Oblique view of SS-1 soil screening location.	5
	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	View facing NE of SS-5 soil screening location on production pad.	6
	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	View facing SW of SS-7 soil screening location in pasture near SW of production pad.	7
	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC.	DESCRIPTION	View facing NE of SS-8 soil screening location in pasture, note production pad in background.	8
212C-MD-02355	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	View facing SE of SS-12 soil screening location in pasture near SW of production pad.	9
	SITE NAME	James A Battery Line Release	3/1/2021



TETRA TECH, INC. PROJECT NO. 212C-MD-02355	DESCRIPTION	View facing NW of SS-12 soil screening location in pasture near SW of production pad.	10
	SITE NAME	James A Battery Line Release	3/1/2021