Submit 1 Copy To Appropriate District Office District I – (575) 393-6161	State of New Mexico Energy, Minerals and Natural	Form C-103 Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	Resources	30 - 015 - 26575 5. Indicate Type of Lease
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	STATE X FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	NM - 0557371
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AT (DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)		7. Lease Name or Unit Agreement Name Gaines – WDW - 3
	ell 🗌 Other: Injection Well	8. Well Number WDW - 3
2. Name of Operator HollyFrontier Navaio Refining Ilc.		9. OGRID Number: 15694
3. Address of Operator P.O. Box 159, Artesia, NM. 88211	; 501 E. Main, Artesia, NM. 88210	10. Pool name or Wildcat: Navajo Permo- Penn
4. Well Location	COLUTIL 2250	N/FOF
	m the SOUTH_line and 2250_feet to 271	
Section 1	Township 18S Range 271 levation (Show whether DR, RKB, RT, GR, etc.	
	GL, RKB	·

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF	INT	FENTION TO:	SUBSEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		CHANGE PLANS	COMMENCE DRILLING OPNS.	P AND A
PULL OR ALTER CASING		MULTIPLE COMPL	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:			OTHER:	X_X

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Aug. 24, 2016; Wednesday, Subsurface personnel travel to Artesia.

Thursday, August 25, 2016

 Install bottom hole memory gauges in all three wells and continue normal injection for 48 hours. Gauges need to be in wells by 12:00 pm. Install surface pressure recorder on Gaines Well No. 3. Gauges to be set at the top of the perforations in all three wells as follows; Mewbourne Well No. 1 7924 feet Chukka Well No. 2 7570 feet Gaines Well No. 3 7660 feet Subsurface personnel will return to Houston.

Friday, August 26, 2016

Continue normal injection into the wells.

Saturday, August 27, 2016

1. At 12:00 pm, Navajo personnel will shut-in offset wells, Chukka Well No. 2 and Mewbourne Well No. 1, start the 30-hour injection period for Gaines Well No. 3. The Chukka Well No. 2 and Mewbourne Well No. 1 will have to be isolated at the wing valve, MOV, and at the main pipeline valve.

2. Navajo Refining is to maintain a constant injection rate at approximately 160 GPM into the Gaines Well No. 3 for a minimum of 30 hours prior to shutting in the well. The 30 hours was the agreed upon time interval by the OCD and Navajo in the approved test plan.

3. The rate should be constant at 160 GPM during the 30-hour injection period. This might be best accomplished by opening the pipe line and wellhead valves wide open allowing full flow to the well. Record the rate and wellhead pressure in the control room on a minimum of 15 second intervals during the injection period. Do not exceed 1200 psig wellhead pressure.

4. Plant personnel will record rate, volume, and pressure during the injection period for all wells to confirm that a constant pre-falloff injection rate is maintained.

5. Collect a grab sample of the injection fluid every 10 hours; analyze the fluid for pH and Specific Gravity.

Sunday, August 28, 2016

6. Continue constant injection into Gaines Well No. 3. The offset wells Mewbourne and Chukka will remain shut-in.

7. At 6:00 pm, Navajo personnel will shut in Gaines Well No. 3 for the 30-hour falloff period. Chukka Well No. 2 and Mewbourne Well No. 1 will remain shut-in during the 30-hour falloff period. The Gaines No. 3 will need to be isolated at the wing valve, MOV, and at the main pipeline valve.

Monday, August 29, 2016

8. Continue to monitor pressure falloff in Gaines Well No. 3.

Tuesday, August 30, 2016

9. At 7:00 am, acquire downhole pressure memory gauges from all three wells.

10. Tag bottom of fill and come out of hole very slowly (no faster than 30 feet per minute), making 7-minute gradient stops while coming out of Gaines Well No. 3 every 1000 feet (7000 feet, 6000 feet, 5000 feet, 4000 feet, 3000 feet, 2000 feet, 1000 feet, Surface).

11. Turn well over to Navajo personnel. Subsurface personnel to return to Houston, TX.

This procedure date is subject to change due to weather conditions or Refinery needs.

Spud Da	ate
---------	-----

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE: Env. Spec. ____ DATE: 08/23/2016

Type or print name: Lewis R. Dade PHONE: 575-746-5281 For State Use Only

E-mail address: Lewis.Dade@hollyfrontier.com

APPROVED BY:	love A.	Ukawa	TITLE	Environmental	Engineer	DATE	8/25/16	
Conditions of Approv	val (if any):	2			5			

WSP	PRESSURE FALLOFF	TESTING WORK PLAN	Project No	. 50904A
	HOLLY FRONTIER NAV	Date:	08/23/16	
PARSONS BRINCKERHOFF	ARTESIA,	Page:	2 of 2	
opening the pipe lin	e and wellhead valves wide on htrol room on a minimum of t	he 30-hour injection period. The open allowing full flow to the we 15 second intervals during the	ell. Record th	e rate and wellhe
	I record rate, volume, and principal record rate is maintained.	essure during the injection per	iod for all we	alls to confirm that
5. Collect a grab samp	ble of the injection fluid every	10 hours; analyze the fluid for p	H and Specifi	ic Gravity.
Sunday, August 28, 20	016			
6. Continue constant	injection into Gaines Well No.	3. The offset wells Mewbourne	e and Chukka	will remain shut
Mewbourne Well N	-	Well No. 3 for the 30-hour fallo g the 30-hour falloff period. T pipeline valve.		
Monday, August 29, 20	016			
8. Continue to monitor	pressure falloff in Gaines We	II No. 3.		
Tuesday, August 30, 2	2016			
9. At 7:00 am, acquire	downhole pressure memory	gauges from all three wells.		
	out of Gaines Well No. 3 ev	ly (no faster than 30 feet per r ery 1000 feet (7000 feet, 6000		
11. Turn well over to Na	avajo personnel. Subsurface	personnel to return to Houston,	TX.	

WSP	PRESS	SURE FALLOFF TESTING WORK PLAN	Project No	. 50904A
	HOLLY F	RONTIER NAVAJO REFINING (NAVAJO) WDW-3 GAINES	Date:	08/23/16
PARSONS BRINCKERHOFF		ARTESIA, NEW MEXICO	Page:	1 of 2
INTRODUCTION				
The following work pla	n has been de	eveloped to conduct the annual pressure fallo	ff testing on W	VDW-3 Gaines
		n the validity of the reservoir model in the well	-	
thickness.				
Note: This procedure for	ollows the guid	lance in the approved 2012 Falloff Test Plan.		
WORK PROGRAM				
Wednesday, August	24. 2016			
reunesuay, August				
Subsurface personnel		esia, NM		
	to travel to Arte	esia, NM		
Subsurface personnel Thursday, August 25,	to travel to Arte			
Subsurface personnel Thursday, August 25, 1. Install bottom hole	to travel to Arte , 2016 memory gaug	es in all three wells and continue normal injec		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0	to travel to Arte , 2016 memory gaug 00 pm. Install	ges in all three wells and continue normal injec surface pressure recorder on Gaines Well No.		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole	to travel to Arte , 2016 memory gaug 00 pm. Install	ges in all three wells and continue normal injec surface pressure recorder on Gaines Well No.		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells	ges in all three wells and continue normal injec surface pressure recorder on Gaines Well No.		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well N	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2	ges in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet		-
Subsurface personnel Thursday, August 25 , 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2	ges in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well N	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2 Io. 3	tes in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet 7660 feet		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well N Gaines Well N	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2 Io. 3 will retum to H	tes in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet 7660 feet		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well M Gaines Well M Subsurface personnel	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2 Io. 3 will return to H	ges in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet 7660 feet		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well N Gaines Well N Subsurface personnel Friday, August 26, 20	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2 Io. 3 will return to H 16	ges in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet 7660 feet		-
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well M Gaines Well M Subsurface personnel Friday, August 26, 20 Continue normal inject Saturday, August 27, 1. At 12:00 pm, Nava	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2 Io. 3 will return to H 16 ion into the we 2016 ajo personnel v	yes in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet 7660 feet Nouston.	. 3. Gauges to	o be set at the to Well No. 1, star
Subsurface personnel Thursday, August 25, 1. Install bottom hole be in wells by 12:0 the perforations in Mewbourne W Chukka Well M Gaines Well M Subsurface personnel Friday, August 26, 20 Continue normal inject Saturday, August 27, 1. At 12:00 pm, Nava 30-hour injection p	to travel to Arte , 2016 memory gaug 00 pm. Install all three wells /ell No. 1 No. 2 Io. 3 will return to H 16 ion into the we 2016 ajo personnel to period for Gain	tes in all three wells and continue normal inject surface pressure recorder on Gaines Well No. as follows; 7924 feet 7570 feet 7660 feet	. 3. Gauges to	o be set at the to Well No. 1, star

PREPARED BY	DATE	REVIEWED BY	DATE
Ted Jose	8/23/16	Tim Jones	8/23/16




FIGURE 3