



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

POST OFFICE BOX 2088
STATE LAND OFFICE BUILDING
SANTA FE, NEW MEXICO 87504
(505) 827-5800

March 24, 1994

CO₂, Inc.
1809 S. Midkiff Rd.
Midland, TX 79701

Attention: Mr. Randy Decker

**RE: *Minimum Plugging Procedures for Five
CO₂ Wells, Harding County, New Mexico.***

Dear Mr. Decker:

Upon review of CO₂, Inc.'s well file information, the following procedures for plugging and abandonment of your wells are as follows:

- 1) Gonzales Well No. 2, P-9-21N-30E
400' FSL & 675' FEL, T.D. 928'
20 sacks @ T.D., circulate hole with 9.6#/gal mud,
5 sacks @ surface, dry-hole marker placement.
- 2) Gallagher Well No. 1, N-9-21N-30E
660' FSL & 1980' FWL, T.D. 814'
25 sacks @ T.D., circulate hole with 9.6#/gal mud,
5 sacks @ surface, dry-hole marker placement.
- 3) Minerals Well No. 1, B-16-21N-30E
960' FNL & 1930' FEL, T.D. 847'
30 sacks @ T.D., circulate hole with 9.6#/gal mud,
7 sacks @ surface, dry-hole marker placement.
**** upon visual inspection to determine if possible 1" 10 sacks in cellar
around 8 5/8" casing.
- 4) State Well No. 1, L-27-21N-30E
1980' FSL & 1320' FWL, T.D. 965'
30 sacks @ T.D., W.O.C. for 18 hours, circulate hole with 9.6#/gal mud,
pressure up to 300 psi and attempt to circulate other annular spaces,
7 sacks @ surface, dry-hole marker placement.

CO₂, Inc.
Attention: Randy Decker
March 24, 1994
Page 2

- 5) Gonzales Well No. 1A, H-32-21N-30E
1980' FNL & 660' FEL, T.D. 900'
30 sacks @ T.D., circulate hole with 9.6#/gal mud,
7 sacks @ surface, dry-hole marker placement.
**** upon visual inspection to determine if possible 1" 15 sacks in cellar
around 8 5/8" casing.

Should you have any questions pertaining to these procedures, please contact me at (505) 827-5810.

Sincerely,



Roy E. Johnson
Senior Petroleum Geologist

REJ/amg

Enclosure