

Submit 1 Copy To Appropriate District Office

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources

Revised August 1, 2011

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

HOBBS OCD

OIL CONSERVATION DIVISION

FEB 19 2013

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-39582

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Bertha Barber

8. Well Number 024

9. OGRID Number

873

10. Pool name or Wildcat

Monument; Paddock (47080)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Apache Corporation

3. Address of Operator

303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705

4. Well Location

Unit Letter E : 2130 feet from the North line and 330 feet from the West line

Section 05 Township 20S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3561' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: Complete Well

☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER:

☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache would like to complete this well in the Paddock as per the attached completion procedure.

Spud Date:

01/11/2010

Rig Release Date:

01/27/2010

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Regulatory Tech I

DATE 01/24/2013

Type or print name Fatima Vasquez

E-mail address: Fatima.Vasquez@apachecorp.com

PHONE: (432) 818-1015

For State Use Only

APPROVED BY:

TITLE

Petroleum Engineer

DATE

FEB 20 2013

Conditions of Approval (If any):

FEB 20 2013

GL=3561'  
KB=3572'  
Spud: 1/11/10

## Apache Corporation – Bertha Barber #24

### Wellbore Diagram – Proposed Status

Date: 1/17/2013

API: 30-025-39582

#### Surface Location

R. Taylor



2130' FNL & 330' FWL, Unit  
Sec 5, T20S, R37E, Lea County, NM

#### Surface Casing

9-5/8" 24# K-55 @ 1145' w/ 388 sx to surface

Hole Size  
=12-1/4"

Hole Size  
=8-3/4"

Maker Jt @  
1978'

DV Tool @ 2887' cmt w/ 630 sxs cmt

Good cmt to 3740'. FREE pipe from 3740-surface

Well drilled directionally from 1408' to 4504'.  
Fight loss returns from 3843 to TD. Loss a total at 17,075 BBLS.  
Suspend drilling due to losses.

TBD: Perf UPR Paddock @ 5180-82; 5187-88; 5222-24; 5226-29;  
5231-34; 5238-40; 5270-74; 5281-85; 5311-16; 5326-30 w/ 2 jspf (60  
holes). Acidize w/ 3000 gal 15% NEFE

TBD: Perf LWR Paddock @ 5469-71; 5475-78; 5483-86; 5489-92;  
5503-09; 5562-65; 5570-74; 5576-80; 5622-24; 5631-39; 5644-51;  
5658-63 w/ 2 jspf (100 holes). Acidize w/ 4500 gal 15% NEFE

DV Tool @ 5771' w/ 785 sxs w/ 16 MCF N2

#### Production Casing

5-1/2" 17# L-80 @ 5888'

PBTD = 5776'  
TD = 5888'

Bertha Barber #24

API #30-025-39582

Sec 5, T20S, R37E

Elevation: 3572' KB, 3561' GL

TD: 5,888'

PBTD: 5,771'

Casing Record: 9-5/8" 24# K-55 @ 1145' w/ 388 sxs

5-1/2" 17# L-80 @ 5888' w/ 785 sxs

Perfs: No Existing Perforations

Objective: Perforate and acidize the Paddock in two stages.

AFE: PA-13-3250

1. MIRU unit. Check pressure on well.
2. ND WH. NU BOP. PU and RIH w/ 4-3/4" bit, bit sub, and drill collars on 2-7/8" J-55 tubing to be used as work string to PBTD @ 5,771'. RU reverse unit and break circulation. Circulate new fluid in the hole. Test casing to 500 psi. POOH.
3. MIRU WL. RIH w/ 3-3/8" csg gun or available perforator and perforate the Paddock at 5469-71; 5475-78; 5483-86; 5489-92; 5503-09; 5562-65; 5570-74; 5576-80; 5622-24; 5631-39; 5644-51; 5658-63 w/ 2 jspf 60° phasing (100 holes). TOH with perf guns. **Correlate to Weatherford Compensated Neutron Gamma Ray/CCL log dated 2/9/2010.**
4. TIH w/ SN and PKR on WS. Spot 200 gallons acid across perforations. Set PKR just above new perforations at  $\pm$  5,420. Test backside to 1000 psi.
5. MIRU acid services. Acidize the LWR Paddock (5469-5663) down the tubing with 4500 gallons 15% NEFE w/ additives using 200 ball sealers to divert evenly spaced throughout the job as a max rate but do not exceed 6,000 psi surface treating pressure. Displace to bottom perf with 32 bbls of flush. Surge balls.
6. RU swab equipment and recover load and swab test for fluid entry and oil cut. Report results to Midland. RD swab equipment.
7. RIH w/ 3-3/8" csg gun or available perforator w/ CIBP on bottom. Set CIBP at 5,420'. Perforate the UPR Paddock at 5180-82; 5187-88; 5222-24; 5226-29; 5231-34; 5238-40; 5270-74; 5281-85; 5311-16; 5326-30 w/ 2 jspf 60° phasing (60 holes). TOH with perf guns and rig down WL. **Correlate to Weatherford Compensated Neutron Gamma Ray/CCL log dated 2/9/2010.**
8. TIH w/ SN and PKR on WS. Spot 200 gallons acid across perforations. Set PKR just above new perforations at  $\pm$  5,130'. Test backside to 1000 psi.
9. MIRU acid services. Acidize the UPR Paddock (5180-5330) down the tubing with 3000 gallons 15% NEFE w/ additives using 120 ball sealers to divert evenly spaced throughout the job as a max rate but do not exceed 6,000 psi surface treating pressure. Displace to bottom perf with 31 bbls of flush. Surge balls.
10. RU swab equipment and recover load and swab test for fluid entry and oil cut. Report results to Midland. RD swab equipment. *If unproductive, Set CIBP above perfs. TA well.*

11. Kill well if necessary. Release PKR and TOH w/ 2-7/8" work string and PKR.

12. RU reverse unit and swivel. PU and RIH w/ 2-7/8" bit subs, DC on 2-7/8" WS and tag CIBP at 5,420'. Break circulation and drill out CIBP or push to PBTD at 5,771'. Circulate bottoms up once. POOH w/ WS.

13. RIH w/ production tubing and rods as per the Monument office specifications. RDMOPU.

14. Set pumping unit. Connect electrical service. Construct and tie in flow-line to well. Place well into production and place into test for 10 days. Have a chemical rep test fluid sand put well on the appropriate chemical maintenance program.