Submit 1 Copy To Appropriate District State C	of New Mexico	Form C-103
Office District 1 – (575) 393-6161 Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 HOBBS OCDOIL CONSERVATION DIVISION 811 S. First S., Artesia, NM 88210		WELL API NO. 30-025-20785
		5. Indicate Type of Lease
		STATE X FEE
1000 Rio Brazos Rd., Aztec, NW 87410 District IV – (505) 476-3460 Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-1608
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Vacuum Glorieta East Unit Tract 22
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other		8. Well Number 003
2. Name of Operator		9. OGRID Number
ConocoPhillips Company		217817
3. Address of Operator P. O. Box 51810		10. Pool name or Wildcat
Midland, TX 79710		Vacuum; Paddock
4. Well Location		
Unit Letter A : 860 feet from the North line and 660 feet from the East line Section 33 Township 17S Range 35S NMPM County Lea		
	7S Range 35S whether DR, RKB, RT, GR, etc.	
3939' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		T JOB 🔲
DOWNHOLE COMMINGLE		·
OTHER: isolate and repair leak	☑ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
ConocoPhillips wishes to isolate leak found during BH test. We will isolate and repair. ConocoPhillips will notify the OCD 24 before running MIT.		
Objective: Is to isolate a leak between the production casing and the surface casing. The surface valve when opened had a steady flow		
of oil coming from it.		
Diagon and attached was a larger		
Please see attached procedures:		
		·
	÷	
Spud Date: Rig	g Release Date:	
	L	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
Thereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE DATE 03/06/2013 TITLE Staff Regulatory Technician DATE 03/06/2013		
Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: (432)688-9174		
Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: (432)688-9174 For State Use Only		
APPROVED BY TIME	TLELJTJI MYZ	DATE 3-12-2013
Conditions of Approval (if any):	- •	· · · · · · · · · · · · · · · · · · ·

VGEU 22-03

APD #30-025-20785 Location: 860' FNL & 660' FEL Sec 33, 17S, 35S BH failure

Objective: Is to isolate a leak between the production casing and the surface casing. The surface valve when opened had a steady flow of oil coming from it.

Proposal is to notify the NMOCD of intent to RU on well. MI rig, review JSA, RU WSU, NDWH, NUBOP, TOOH laying down tubing and ESP, scan tubing COOH. MO production tubing. Send ESP to Centrilift to be cleaned, inspected and bench tested. Notify Simon Choi (432-368-1232) to view inspection of pump. MI work string and tally. Pressure test GIH with bite, scrapper and tubing to 6118', clean out if needed. TOOH with tubing, scrapper and bit. TIH with RBP, packer and tubing, set RBP @ 4000', pull up 1jt, set packer and test packer/RBP to 500 psi, if test passes, RU pump truck on casing and pressure test casing/ packer to 500 psi, if test fails, come up hole and isolate leak, engineer for possible change in job scope.

After repairs have been made, RU pump truck to casing, with a 1000 psi chart and pressure test casing to 550 psi for 30 mins. Notify the NMOCD prior to the test, give chart to Production Specialist. TIH and retrieve RBP. COOH laying down work string and RBP. MO work string. MI production tubing, TIH with ESP and tubing as to Wellview Tubing Design. NOTE: WILL NOT RUN CAP STRING BACK. Land ESP, NDBOP, NUWH, test ESP, check to make sure ESP is turning the right direction. RD, clean up location.