811 S. First St., Artesia, NM 88210	State of New Mexico BS OCE Energy, Minerals and Natural Resources 10 5 2019 IL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30- 5. Indicate Type of 1 STATE 6. State Oil & Gas L B-2863-1	FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection well			7. Lease Name or Unit Agreement Name East Vauum GB_SA Unit Tract 3374 8. Well Number 002 9. OGRID Number	
3. Address of Operator P. O. Box 51810 Midland, TX 79710			217817 10. Pool name or Wildcat Vacuum; Grayburg-San Andres	
4. Well Location Unit Letter L : 2681 feet from the North line and 1092 feet from the West line Section 33 Township 17S Range 35E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3949' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PLULL OR ALTER CASING MULTIPLE OF DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operation	TO: ABANDON	SUBS MEDIAL WORK MMENGE DRIL SING/CEMEN 11.6 C P HER: feet of th	BEQUENT REPORT AND	ORT OF: LITERING CASING AND Program Manual thin or less than 100 on perfs or open hole.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Job proposal is to review JSA prior to RU. MI RU WSU. NDWH, NUBOP, TOOH with tubing, on/off tool and packer, lay all down. MO injection tubing. MI and tally work string. TIH with sand line bailer and TFF. Notify engineer on findings. TIH with bit, scrapper and tubing to 4360'. COOH lay down bit and scrapper, TIH with RBP, packer and tubing. Set RBP @ +/- 4200'. Pull up 1jt and set packer. RU pump truck to tubing and pressure test RBP/Packer to 600 psi. If RBP/Packer test holds, RU pump truck to casing and pressure test casing/packer to 550 psi. If test fails, Come up hole and isolate leak. Get injection rate and notify engineer for possible change in job scope. Once repairs are made or no repairs were needed, TIH and retrieve RBP and COOH with RBP, packer and tubing. If fill was observed during the bailer run, TIH with bit and tubing and CO to TD. COOH laying down work string and bit. MO work string. MI injection tubing and tally. TIH with packer, on/off tool and tubing as to Wellview Tubing-Design, pressure test tubing of GIH. Set packer@+/- 4287'. RU pump truck to casing and pressure test casing/packer to 550 psi. If test passes, get off on/off tool and circulate packer to surface. Get back on on/off tool. NDBOP, NUWH. RU pressure recorder and pressure test casing/packer to 550 psi for 35 mins. Notify the NMOCD of impending test. RD. Clean up location. Notify projects to hook up piping to injector wellhead. During this procedure we plan to use the Closed-Loop System and haul content to the required disposal The Oil Conservation Division				
Prior to the beginning of operations	Rig Release Date:		ndition of Appro CD Hobbs office	
I hereby certify that the information above is true and SIGNATURE Type or print name Rhonda Rogers For State Use Only	TITLE Staff Regula E-mail address: ros	my knov priter	DATE hillips.com PHON	Test & Chart E
APPROVED BY: Conditions of Approval (if any):	TITLE SS	WEFF	DATE NOV	11-6-2013 07 2013