Submit I Copy To Appropriate District	State of New Mexico	Form C-103
District $1 - (575) 393-6161$	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	-0D	WELL API NO.
<u>District II</u> – (575) 748-1283 HOBBS	OUL CONSERVATION DIVISION	30-005-20685
811 S. First St., Artesia, NM 88210		5. Indicate Type of Lease
$\frac{District III}{1000 \text{ Right Brazos Rd}} = (505) 334-6178$	A 2013 1220 South St. Francis Dr.	STATE 🗌 FEE 🖂
District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505	en/FD	
SUNDRY NORIGI	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
PROPOSALS.)	HONTOKTERMIT (FORM C-101) FOR SOCH	Southard "A"
1. Type of Well: Oil Well 🛛 G	as Well 🔲 Other	8. Well Number 2
2. Name of Operator		9. OGRID Number 286614
Cross Border Resources, Inc.		· · · · · · · · · · · · · · · · · · ·
3. Address of Operator		10. Pool name or Wildcat
2515 McKinney Avenue Suite 900, D	Dallas TX 75201	Tom Tom (San Andres)
4. Well Location		/
Unit Letter 1 : <u>19</u>	280 feet from the <u>North</u> line and <u>660</u> feet fro	om the <u>East</u> line
Section 26	Township 7S Range 31E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:	
	PLUG AND ABANDON	Ц		Ц
	CHANGE PLANS	Ц		
PULL OR ALTER CASING	MULTIPLE COMPL			
		-		_
UTHER:				

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attached procedure

/

		APR 17 2013 NMOCD ARTESIA
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true	and complete to the best of my	v knowledge and belief.
SIGNATURE / MAC	Agent TITLE	DATE
Type or print name <u>Tommy W. Folsom</u> For State Use Only APPROVED BY <u>APPROVED BY</u> Conditions of Approval (if any)	E-mail address: <u>tommy@</u> <u>TITLE</u> Complu	ance Office DATE 1/28/2014
		JAN 28 2014 T

Cross Borders Resources, Inc.

Southard A #2 Sec 26,7-S, 31-E 1980'FN & 660'FEL Chaves Co, New Mexico Tom Tom Field API No: 30-005-20685

Workover procedure for well remediation and recompletion

Casing

Surf	8.625"	J-55	24#	1653'	cmt circ to surf
Prod	4.500"	K-55	10.5#	4 177'	TOC @ 2322' (calc)
Tbg	2.375"	J-55	4.7#	?'	

Logs

Gamma Ray Neutron Log: 8/26/67

PERFORATIONS

San Andres Interval - (4,010' - 4,136') 1 SPF

(4,010' – 4,057') – 47' (14 Holes) *Existing Perfs (4,101' – 4,136') – 35' (17 Holes) *Existing Perfs

<u>Objective</u>

Research and evaluate opportunities for increased production and optimization potential for well

Discussion

A geological review of the Southard A #2 was performed by Earl Sebring and reviewed by Tommy Folsom. The subject well is offset due south of the Southard A #3 (37,652 BO, 31,416 MCF, 31,333 BW Completed only in P3) and shows pay similar to that of the Southard A #3. Recommendations for this well are to perform a cleanup of the existing perforations and wellbore and put well on production.

Pre Work-over

- Shoot Fluid level and run Dyno on well if available
- If well is pumping, hot water casing w/ 75 bbls to clean up paraffin and salt
- An oil sample should be collected and sent to stimulation company to be analyzed to insure emulsion is not created during stimulation.
- Notify BLM 24 hours before starting work over

Remediation and Optimization Procedure

1. MIRU PU

2. POH w/ rods and pump

Note:

- While POH, look for rod pitting, wear, and fatigue, If scale or paraffin are observed take samples to be analyzed, lay down any damaged equipment or any equipment not deemed fit for service
- With pump on surface make note of any material in pump and report any general observations about the pump. Send pump into shop for a complete teardown and report
- 3. ND wellhead, NU 4.5" x 2 3/8" BOP (3,000 psi)
- 4. Release TAC, RIH and tag for fill, report tag depth
- 5. POH and tally out

Note:

- While POH, look for pitting and wear, If scale or paraffin are observed take samples to be analyzed, lay down any damaged equipment or any equipment not deemed fit for service
- With tbg on surface make note of any material in or on the tbg and report any general observations about the tbg
- RIH w/ bailer and clean out to PBTD if necessary
- 6. RIH w/ 3 ¾" bit and scraper
- 7. RIH to TD, testing in hole to 4000 psi above slips
- 8. POH and lay down tools
- 9. TIH w/ AS1 packer set packer @ 3,995' +
- 10. Load csg w/ 40 bbls produced water and pressure test annulus to 300 psi Note:
 - If test fails, POH w/ tools , RIH w/ pkr and RBP to isolate breakdown in csg, a squeeze procedure will be prepared .
 - If test passes, continue on w/ procedure
- 11. Release pkr, POH lay down tools
- 12. RU wireline and junk basket and gauge ring, run CBL log from TD 100' above cement top. Look for perforated intervals and cmt top.
- 13. TIH w/ AS1 packer and set pkr @ 4,085'+
- 14. Acid treat down tbg into perfs at 4,100' 4,136' with 2000 gals 15% HCL NEFE, acid treat at 3 to 4 bpm with 3000 psi max pressure. Flush w/ produced water double the tbg capacity. Record 5, 10, 15 minute shut in pressures
- 15. Release pkr, pull up hole and set pkr @ 3,995'
- 16. Acid treat down tbg into perfs at 4,010' 4,057' with 2000 gals 15% HCL NEFE, acid treat at 3 to 4 bpm with 3000 psi max pressure. Flush w/ produced water double the tbg capacity. Record 5, 10, 15 minute shut in pressures
- 17. Swab test for potential, ensure live acid is not being produced
- 18. Release pkr, POH and lay down tools
- 19. RIH w/ 2 3/8" production tbg and BHA
- 20. Run tbg as follows
 - Slotted tapped BP MA

SN

ç

- 6 jts 2 3/8 J-55 tbg
- TAC
- Remaining 2 3/8" tbg required to set EOT at 4,130'
- 21. Set TAC w/ 15k tension @ 3,944' +
- 22. Set SN at 4,099' +
- 23. ND BOP and NU well head
- 24. RIH w/ rods and pmp
- 25. Run rods and pmp as follows
 - PR
 - 1 ¾" rod
 - Required ¾"space out rods
 - 157 ¾" Rods
 - 6 7/8" Rods
 - 2" pump (pump will be sized from swab test)
- 26. Space out rods and pmp, check for pmp action
- 27. Hang on horse head and rods
- 28. Put well back on production and report production daily
- 29. RD PU, clean up location

Post Work-over

.

- Track production daily
- Check and report fluid level on weekly basis following work over until fluid level is pumped off then continue monitoring on schedule.
- Follow up on production at 1 month, 3 month, and 6 month, make applicable changes to ensure well is producing at optimal efficiency

Procedure Written By: Casey Satterfield, _____

Approved By: _____



ب ب س

> DATE: 3/20/2013 Updated: 4/1/2013

OFFICE: FAX: