Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-37122	1 0000
District III	1220 South St. Francis Dr.		5. Indicate Type of STATE	. — '
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas	
1220 S. St. Francis Dr., Santa Fe, NM	·		o. state on a cus	Dougo Ivo.
87505			7 1	luit A No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name South Vacuum	
1. Type of Well: Oil Well	Gas Well Other HOBBS OCD		8. Well Number 2	274
2. Name of Operator	#IODB3 OOD		9. OGRID Number	
Paladin Energy Corp.			164070	
3. Address of Operator		EC 2 3 2013	10. Pool rame or	रिषेद्रभा ५५ हिम्
10290 Monroe Drive, Suite 301, Dallas, Texas 75229			Vaetruin, Devonian	South 60218 (963)
4. Well Location		RECEIVED		
Unit LetterP_:_	_960_feet from theSouth		feet from theF	Eastline
Section 27	Township 18-S	Range 35-E	NMPM	Lea County
	11. Elevation (Show whether D. 3887' GR	R, RKB, RT, GR, etc.,)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK				ALTERING CASING 🗌
TEMPORARILY ABANDON			_	AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲	
OTHER:		OTHER: Re-	completion to SWD	\boxtimes
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. R/U pulling unit, N/D tree. Pull 2-7/8" tubing. R/U E-line, GIH and squeeze cement in 7" casing from 10,930-11,700'. (Leave existing Mississippian perforations from 10,858-78', 10.890-900', 10,920-30'open and Devonian				
perfs from 11,760-900'.) Drill out to PBTD @ 13,500'. Perforate Devonian from 12,300-400'. Run CBL.				
2. R/D E-line, GIH with 2-7/8" workstring and packer, set packer. Acidize Miss/Devonian perforations with total of				
10,000 gallons of 15% NEFE acid. Swab back acid. POOH with workstring and packer. GIH with 4-1/2" coated				
tubing and packer. Set packer at 10,786'. N/U tree, test casing to 540 psi for 30 minutes. Held OK. Place well on				
SWD operations as per Order SWD-1444.				
Clased Logo	System-Dap		5	WD-1444
<u></u>				7
Spud Date: 8/28/2013	Rig Release I	Date: 11/14/2013		
	J			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print name David Plaisance E-mail address: dplaisance@paladinenergy.com Telephone No. 214-654-0132 For State Use Only				
APPROVED BY: Mal Whiteh TITLE Compliance Officer DATE 12/26/2017				
Conditions of Approval (if any):		ı		•

OHOVA

