Office Office		New Mex				m C-103
<u>District 1</u> – (575) 393-6161	Energy, Minerals	and Natur	al Resources	CWD. ADVAGO	Octol	per 13, 2009
1625 N. French Dr., Hobbs, NM 88240	BBS OCD		•	WELL API NO.		
District 11 – (575) 748-1283 <b>HO</b> 811 S. First St., Artesia, NM 88210	OIL CONSERV	ATION	DIVISION	30-025-01535 5. Indicate Type	of Lease	• • •
District III – (505) 334-6178	1220 South	St. Fran	cis Dr.		FEE	
1000 Rio Brazos Rd., Aztec, NM 87444 District IV – (505) 476-3460	Santa Fe	e, NM 87	505	6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM 87505	and the same				45 24454 1161	
	THEES AND REPORTS OF	N WELLS		7. Lease Name of	or Unit Agreeme	nt Name
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVOIR. USE "APF						
PROPOSALS.)	· · · · · · · · · · · · · · · · · · ·	W C-101) FO	K SUCH .	CAPROCK MA		
1. Type of Well: Oil Well	Gas Well 🔽 Other			8. Well Number	: 092	
2. Name of Operator LINN OPERATING, INC.				9. OGRID Num	ber 269324	
3. Address of Operator				10. Pool name o	r Wildcat	
600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002				MALJAMAR;GRAYBURG-SAN		
				ANDRES		
4. Well Location				J	· · · · · · · · · · · · · · · · · · ·	
Unit Letter G;	1980 feet from the	<u>N</u>	line and	1980 feet fro	om the <u>E</u>	line
Section 28	Township	17S	Range 33	E NMPN	M LEA	County
For the Man Control	11. Elevation (Show wh					
Maria Cara Cara Cara Cara Cara Cara Cara	. 4173'	•		, Alexander	Addition of the second	
12. Checl	k Appropriate Box to In	idicate Na	ature of Notice,	Report or Other	r Data	
NOTICE OF	INTENTION TO	ı	OLID	OF OUT NE	TOODT OF	
	INTENTION TO:			SEQUENT RE		
PERFORM REMEDIAL WORK			REMEDIAL WOR		ALTERING CA	
TEMPORARILY ABANDON	CHANGE PLANS	닏ㅣ		ILLING OPNS.	PANDA	$\boxtimes$
	MULTIPLE COMPL		CASING/CEMEN	I JOB		
DOWNHOLE COMMINGLE [						
		I				
OTHER:	•		OTHER:			
13. Describe proposed or co	work). SEE RULE 19.15.7	y state all p	ertinent details, an			
13. Describe proposed or co of starting any proposed proposed completion or	work). SEE RULE 19.15.7 recompletion.	y state all p	ertinent details, an			
13. Describe proposed or co of starting any proposed	work). SEE RULE 19.15.7 recompletion.	y state all p .14 NMAC	ertinent details, an E. For Multiple Co	mpletions: Attach	wellbore diagra	m of
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg	work). SEE RULE 19.15.7 recompletion.  t. g and tagged CIBP @ 4090'. Circ	y state all p .14 NMAC	pertinent details, an L. For Multiple Co ud laden fluid. Spott	mpletions: Attach	wellbore diagra	m of . Set pkr @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl	work). SEE RULE 19.15.7 recompletion.  t. g and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & c	y state all p .14 NMAC c hole w/ mo	pertinent details, and . For Multiple Co ud laden fluid. Spotterfs. RIH w/ tbg & sp	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w	m of . Set pkr @ //tbg.
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl	work). SEE RULE 19.15.7 recompletion.  t. g and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & c	y state all p .14 NMAC c hole w/ mo	pertinent details, and . For Multiple Co ud laden fluid. Spotterfs. RIH w/ tbg & sp	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w	m of . Set pkr @ //tbg.
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well	y state all p .14 NMAC c hole w/ mo red up on po displaced to wn moved c	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. RIH w/ tbg & spotterfs.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POF	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well	y state all p .14 NMAC c hole w/ mo red up on po displaced to wn moved c	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. RIH w/ tbg & spotterfs.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POF	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci 4/25/14 – Moved in welder and help removed deadmen. Cleaned locatio	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.	y state all p .14 NMAC  c hole w/ mu ired up on podisplaced to wn moved c	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POF	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.	y state all p .14 NMAC c hole w/ mo red up on po displaced to wn moved c	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POF	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci 4/25/14 – Moved in welder and help removed deadmen. Cleaned locatio	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.	y state all p .14 NMAC  c hole w/ mu ired up on podisplaced to wn moved c	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POF	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci 4/25/14 – Moved in welder and help removed deadmen. Cleaned locatio Spud Date:	work). SEE RULE 19.15.7 recompletion.  g and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p .14 NMAC  c hole w/ mared up on policy and to with moved color with the color with	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POH nd Dry Hole Marker".	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci 4/25/14 – Moved in welder and help removed deadmen. Cleaned locatio	work). SEE RULE 19.15.7 recompletion.  g and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p .14 NMAC  c hole w/ mared up on policy and to with moved color with the color with	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POH nd Dry Hole Marker".	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci 4/25/14 – Moved in welder and help removed deadmen. Cleaned locatio Spud Date:	work). SEE RULE 19.15.7 recompletion.  g and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p .14 NMAC  c hole w/ mared up on policy and to with moved color with the color with	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach ed 25 cmt @ 4090-38 potted 25 sx cmt @ 2 d plug @ 1420'. POH nd Dry Hole Marker".	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of . Set pkr @ //tbg. erf'd csg @
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx ci 4/25/14 – Moved in welder and help removed deadmen. Cleaned locatio Spud Date:	work). SEE RULE 19.15.7 recompletion.  t.  g and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig I	y state all p .14 NMAC  c hole w/ mored up on per displaced to wn moved co lhead. Welco  Release Da	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. WOC. Tagge off.	mpletions: Attach  ed 25 cmt @ 4090-38  potted 25 sx cmt @ 2  d plug @ 1420'. POH  nd Dry Hole Marker".	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe	m of  Set pkr @  //tbg.  erf'd csg @  Cut off and
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx cr 4/25/14 – Moved in welder and help removed deadmen. Cleaned location Spud Date:	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p. 14 NMAC  c hole w/ mored up on per displaced to wn moved collhead. Welcon Release Da  ete to the beachest to th	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. RIH w/ tbg & spotterfs. WOC. Tagger off.  ded on "Above Ground te:	mpletions: Attach  ed 25 cmt @ 4090-38  potted 25 sx cmt @ 2  d plug @ 1420'. POH  nd Dry Hole Marker".  ge and belief.	wellbore diagram 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe Backfilled cellar.  _DATE May	m of  Set pkr @  //tbg.  erf'd csg @  Cut off and
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx cd 4/25/14 – Moved in welder and help removed deadmen. Cleaned location Spud Date:	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p. 14 NMAC  c hole w/ mored up on per displaced to wn moved collhead. Welcon Release Da  ete to the beachest to th	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spots. 1450'. WOC. Taggeoff. Hed on "Above Groundte:	mpletions: Attach  ed 25 cmt @ 4090-38  potted 25 sx cmt @ 2  d plug @ 1420'. POH  nd Dry Hole Marker".  ge and belief.	wellbore diagra 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe Backfilled cellar.	m of  Set pkr @  //tbg.  erf'd csg @  Cut off and
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx cr 4/25/14 – Moved in welder and help removed deadmen. Cleaned location Spud Date:	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p. 14 NMAC  c hole w/ mored up on per displaced to wn moved collhead. Welcon Release Da  ete to the beachest to th	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. RIH w/ tbg & spotterfs. WOC. Tagger off.  ded on "Above Ground te:	mpletions: Attach  ed 25 cmt @ 4090-38  potted 25 sx cmt @ 2  d plug @ 1420'. POH  nd Dry Hole Marker".  ge and belief.	wellbore diagram 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe Backfilled cellar.  _DATE May	m of  Set pkr @  //tbg.  erf'd csg @  Cut off and
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx cd 4/25/14 – Moved in welder and help removed deadmen. Cleaned location Spud Date:	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p. 14 NMAC  c hole w/ mored up on per displaced to wn moved collhead. Welcon Release Da  ete to the beachest to th	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. RIH w/ tbg & spotterfs. WOC. Tagger off.  ded on "Above Ground te:	mpletions: Attach  ed 25 cmt @ 4090-38  potted 25 sx cmt @ 2  d plug @ 1420'. POH  nd Dry Hole Marker".  ge and belief.	wellbore diagram 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe Backfilled cellar.  _DATE May	m of  Set pkr @  //tbg.  erf'd csg @  Cut off and
13. Describe proposed or co of starting any proposed proposed completion or 4/22/14 – MIRU plugging equipment 4/23/14 – Dug out cellar. RIH w/ tbg 34' & pressure tested csg. Held 500 4/24/14 – Perf'd csg @ 1550'. Set pl 405'. Set pkr @ 34' & sqz'd 115 sx cold 4/25/14 – Moved in welder and help removed deadmen. Cleaned location Spud Date:  I hereby certify that the information of the proposed set of the	work). SEE RULE 19.15.7 recompletion.  and tagged CIBP @ 4090'. Circ psi. Perf'd csg @ 2600'. Pressu kr @ 1250'. Sqz'd 45 sx cmt & cmt & circ to surface. Rigged do per. Dug out cellar. Cut off well n and moved off.  Rig 1	y state all p. 14 NMAC  c hole w/ mored up on per displaced to wn moved collhead. Welcon Release Da  ete to the beachest to th	pertinent details, and a laden fluid. Spotterfs. RIH w/ tbg & spotterfs. RIH w/ tbg & spotterfs. WOC. Tagger off.  ded on "Above Ground te:	mpletions: Attach  ed 25 cmt @ 4090-38  potted 25 sx cmt @ 2  d plug @ 1420'. POH  nd Dry Hole Marker".  ge and belief.	wellbore diagram 843'. POH w/ tbg 650-2403'. POH w H w/ tbg & pkr. Pe Backfilled cellar.  _DATE May	m of  Set pkr @  //tbg.  erf'd csg @  Cut off and

