### District I

1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210

Phone: (575) 748-1283 Fax: (575) 748-9720 \_\_\_\_\_14

Phone: (3/3) ....

<u>District III</u>

1000 Rio Brazos Road, Aztec, NM 87410

Phone: (505) 334-6178 Fax: (505) 334-6170

RECEIVED

1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

### **State of New Mexico**

Form C-101 Revised July 18, 2013

# Energy Minerals and Natural Resources HOBBS OCD

Oil Conservation Division

☐AMENDED REPORT

1220 South St. Francis Dr. MAY 0 5 2014

**Santa Fe, NM 87505** 

	CATIO	TTOK	1. Operator Nam	e and Address	9	ER, DEEPEN	, I LUGDAC	OGRID Numb	er ZONE	
		:	VANGUARD PI 5847 SAN FELIP	ERMIAN LLO E, SUITE 300	00 00					
			HOUSTON, TE	EXAS 77057	1			258350 3 API Number 30-025-378	227	
4. Prop	erty Code				<sup>2</sup> Property Nam COLE STATE	ne		30-025-37827 • Well No.		
30	1544				COLE STATE  7. Surface Loca				18	
UL - Lot	Section	Township	Range	Lot Ide		N/S Line	Feet From	E/W Line	County	
Α	16	22S	37E		330	NORTH	990	EAST	LEA	
	1	T	1 .		posed Bottom I	<del></del>	7		1	
UL - Lot	Section	Township	Range	Lot Idi	n Feet from	N/S Line	Feet From	E/W Line	County	
					9. Pool Informa	tion	· · · · · · · · · · · · · · · · · · ·		T	
			PENROSI	E SKELLY	Pool Name GRAYBURG S	ANANDRES >			Pool Code 50350	
·· ·						<u> </u>				
11.117	ork Type	<del></del>	12. xx - 11 m	Add	itional Well Info		<sup>14.</sup> Lease Type	15. C	and Lored Electric	
	P		OIL	, ,				I	15. Ground Level Elevation 3403 GL	
<sup>16.</sup> N	lultiple		<sup>17.</sup> Proposed Dep	· · · · · · · · · · · · · · · · · · ·			19. Contractor		<sup>20</sup> . Spud Date	
epth to Gro	und water	<u> </u>			carest fresh water wel					
1887		.1		- 612 4 24		·				
]we wiii d	e using a c	ciosea-ioop	system in lieu	•						
m		0:				ement Program	6.1.64		E C L TOO	
Type	FIOR	e Size	Casing Size		ng Weight/ft	Setting Depth	Sacks of (	ement	Estimated TOC	
		<u>.</u>		+				· · · · · · · · · · · · · · · · · · ·		
·										
			Coo	ing/Comor	at Duoguami Ad	ditional Commo	nts			
			Cas	ing/Cemer	it Frogram; Au	ditional Comme	nus			
<u></u>				2 D	d Dlamant Duan	antian Duagnam		· · ·		
Type Working Pressure						Test Pi	ressure	Manufacturer		
1,700				Working 11	Costile	103011	i cosui c	Triantifacture:		
					<u></u>		<del></del>		*****	
			on given above i	s true and co	mplete to the	ſΩ	L CONSERVA	LION DIVIS	ION	
	nowledge ar rtify that I		ied with 19.15.1	4.9 (A) NMA	AC 🗌 and/or		ECONSERVA	TION DIVIS		
		∏, if applic	able.		_	Approved By:	Also I	/_		
	<u>لاهن</u>	lien'	Derma	sup		Dotrolesm	Angineer .	\$		
Printed name: COLLEEN GERMANY						Approved Date: 05/12/14 Expiration Date: 05/16/16				
	Title: AGENT						2116/14	xpiration Date:	05/16/11	
itle:							•		•	
Γitle:		any@oilrep		5-393-272		Conditions of Approv			· · · · · · · · · · · · · · · · · · ·	



### Cole State #18

## P. Skelly/Graygurg/San Andres - 30-025-37827

# Lea County, New Mexico PROPOSED COMPLETION - 4/2014

			PRUP	OSED COM	FLETION .	4/2014					
KB: 3413'							INO PROS				
GL: 3403'				<u>Depth</u>	<u>Size</u>	<u>CAS</u> <u>Weight</u>	ING PROG Grade	<u>I.D.</u>	Collapse	Burst	
TOC @ surf				<u>Deptii</u>	Size	weight	Graue	<u>1.D.</u>	Collapse	Duist	
330 sxs		ŀ		862	8 5/8"	24#	K-55	8.097	1,370	2,950	
		1 1		4250	5 1/2"	17#	J-55	4.892	4,910	5,320	
8 5/8"csg @ 862	4										
		1 1		<b>5</b> 41	0.		UCTION T				
<u> </u>		1 1		<u>Depth</u> 4024.00	<u>Size</u> 2 7/8"	<u>Weight</u> 6.5#	<u>Grade</u> J-55	Threads EUE			
		1 1		4024.00	2 110	0.51	3-33	LOL			
[]		1 1									
		1 1									
		1 1									
		1 1									
		1 1									
		_									
		1 1									
<u> </u>		1 1									
TOC @ aurfage		1 1									
TOC @ surface 1000 sxs											
1000 323		1 1		•							
		1 1									
1											
1											
						rations 18 hol					
				3,470' - 3,476' (6', 120°, 12 holes) 3,512' - 3,515' (3', 120°, 6 holes)				PROPOSED			
		<b></b>		3,512 - 3,5	15" (3", 12	u*, 6 noies)			PROPOSED	,	
		286									
						(	60'				
1				Grayburg Perforations 24 holes:				Frac'd 7/2006			
				3,684' - 3,6			77,148# 16/30 sand				
		=		3,768' - 3,7	'72' (12 ho	les)		40,792# F	RC sand		
				San Andres Perforations 141 holes:				Δcidizad	Acidized in 6/2006		
					3,815' - 3,872' (57 holes)				4000 gal 15 % NEFE acid		
				.,	,	,		- 3		•	
1		•		3,916' - 4,0	00' (84 ho	les)		4500 gal	15% NEFE a	cid	
}		•									
			K	PBTD = 4,2	205' FC						
				1010 - 4,2							
5 1/2"csg @ 4250		al de									
J 5 - 24		Note: This s	schematic is	not to scale. Fo	or display pu	ırposes only.					
II .					- •	-					

#### VANGUARD PERMIAN LLC

#### **COLE STATE #18**

### A 16 T22S R37E 30-025-37827

### Procedure:

- 1. MIRU completion rig and test anchors.
- 2. Unseat pump and POOH w/ rods and pump.
- 3. ND WH and NU BOP. Kill well with 2% KCL water, if necessary. Release TAC and POOH w/ tubing.
- 4. PU, strap and TIH with 4-3/4" bit, 5-1/2" casing scrapper & 2-7/8" tubing.
- Clean out hole to ~4200' until clean returns, POOH and rack back 2-7/8" tubing.
- 5. MI wireline w/ packoff. RIH w/ CBP and GR/CCL & correlate to the Halliburton Gamma/Neu/Den Log dated 3-Jul-2006.
- Set CBP @ ~3650'. Test CBP and casing to 1000 psi.
- 7. MU 3-1/8" slick casing guns set at 2 spf, 120° phasing (0.40" hole, 21" penetration).
- Perforate as follows:
- a. 3470' 3476' (6', 2 spf, 12 shots)
- b. 3512' 3515' (3', 2 spf, 6 shots) for a total of 18 shots
- 9. RD wireline.
- 10. PU a 5-1/2" Arrowset packer and RIH with tubing to ~3450' and prepare to set packer. Test tubing going in the hole to 3500 psi.
- 11. MIRU pump truck (with 2000 gals acid) and test lines to 3500 psi.
- a. Spot 500 gals of acid across perforations. Load tubing with 2 % KCl and set packer at 3450'.
- b. Pump 1000 gals 15% NEFE acid with 30 ball sealers.
- c. Pump 500 gal then drop 30 balls over next 500 gals.
- d. Pump last 500 gals and flush to 3515'.
- e. Record ISIP, 5 min, 10 min and 30 min.
- 12. RU swabber and swab well in to test acid job. Recover load and report fluid/gas entry, if possible. If well is on vacuum, continue to Step 13.
- 13. Release packer and POOH, lay out tubing to prepare for frac job.
- 14. RDMO completion rig.
- 15. Call out 3-500 bbl tanks & fill with 2% KCl water. Install frac valve in preparation for frac job down 5-1/2" casing.
- 16. RU frac Co. and test lines & pump as per frac schedule.
- 17. Monitor ISIP, 5 min, 10 min, 15 min. Flowback until well dies.
- 18. Rig down frac valve and release frac tanks.
- 19. MIRU completion rig.
- 20. PU a 4-3/4" bit and 2-7/8" tubing and RIH to confirm perfs are open, POOH.
- 21. RU and bail sand if necessary.
- 22. RIH w/ 5-1/2" TAC, SN and 2-7/8" tubing.
- 23. RIH w/ rods and pump.
- 24. RD & MO.
- 25. Turn well on to production and test.