State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	C(0)11.	CONSERV.	ATION DIVISION		
DISTRICT I	HOBBS OCCUPA	1220 South	ATION DIVISION St. Francis Dr.	WELL API NO.	
1625 N. French Dr. , Hobbs, NM 88240	. 0018		NM 87505	30-025-37446	
<u>DISTRICT II</u>	JUN 2 6 2014			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210	9.5	•		STATE X	FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	RECEIVED			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE	"APPLICATION FOR P	ERMIT" (Form C-1	01) for such proposals.)	Section 19	
1. Type of Well: Oil Well	Gas Well	Other In	iector	8. Well No. 633	
Name of Operator Occidental Permian Ltd.		-		9. OGRID No. 157984	
3. Address of Operator				10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City,	TX 79323				
4. Well Location					
Unit Letter G: 2290 Feet From The North Line and 1410 Feet From The East Line					
Section 19	Township		Range 38-)	E NMPM	Lea County
	11. Elevation (<i>Sk</i> 3668' KB	ow whether DF, RF	KB, RT GR, etc.)		
Pit or Below-grade Tank Application or Closure					
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
E-PERMITTING - CSNG SUBSEQUENT REPORT OF:					
PERFORI P&ATA 1 REMEDIAL WORK				X ALTERING	G CASING
TEMPOR COMPNEW WELL COMMENCE DRILLING OPNS. PLUG & ABANDONMENT					
PULL OR LOC CHG PERFS CASING TEST AND CEMENT JOB					
OTHER: CHART OTHER:					
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any					
		ate all pertinent de	etails, and give pertinent dates	s, including estimated date of s	starting any
13. Describe Proposed or Completed proposed work) SEE RULE 110	Operations (Clearly sta				starting any
13. Describe Proposed or Completed proposed work) SEE RULE 110	Operations (Clearly state) 3. For Multiple Comp	letions: Attach w			starting any
13. Describe Proposed or Completed proposed work) SEE RULE 110	Operations (Clearly state) 3. For Multiple Comp	letions: Attach w			starting any
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injections.	Operations (Clearly stands) 3. For Multiple Computubing @4168'. RD	letions: Attach wwire line.	vellbore diagram of proposed	completion or recompletion.	
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injection of the second	Operations (Clearly stands). For Multiple Computubing @4168'. RD ection packer. Tag @4427'. NU stands.	wire line.	vellbore diagram of proposed	completion or recompletion. ulfide. Push CIBP from 435	52' to 4427'. Drill on
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory of the second	Operations (Clearly stands). For Multiple Computubing @4168'. RD etion packer. Tag @4427'. NU stands of the stands	wire line. tripper head & por a Drill on CIBP	ower swivel. Drill on iron so from 4436-4438'. Drill on	completion or recompletion. ulfide. Push CIBP from 435 float collar from 4438-4439	52' to 4427'. Drill on
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory of the second	Operations (Clearly sta 03. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well cle well @4390-4403', 4	wire line. tripper head & portion of the control o	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC 12', 4427-32', 4437-43', 444	ulfide. Push CIBP from 435 float collar from 4438-4439 OOH w/bit & drill collars. 49-51', 4456-64', 4468-77'.	32' to 4427'. Drill on or
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new TIME) 6. RU wire line & perforate 7. RIH w/treating packer set	Operations (Clearly sta 03. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clearly well @4390-4403', 4 @4387'. RU Warrie	wire line. tripper head & portion of the proper of the pr	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC 12', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF.	ulfide. Push CIBP from 435 float collar from 4438-4439 OOH w/bit & drill collars. 49-51', 4456-64', 4468-77'. E acid with 1000# of rock sa	32' to 4427'. Drill on or
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new Times) 6. RU wire line & perforate 7. RIH w/treating packer set Communicated and did new results.	Operations (Clearly sta)3. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warried ot break down lower	wire line. tripper head & portion of the properties of the proper	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC2', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF tacker to 4446'. Spotted 1000	ulfide. Push CIBP from 435 float collar from 4438-4439 OOH w/bit & drill collars. 49-51', 4456-64', 4468-77'.	32' to 4427'. Drill on or
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new TIME) 6. RU wire line & perforate 7. RIH w/treating packer set	Operations (Clearly sta)3. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warried ot break down lower	wire line. tripper head & portion of the properties of the proper	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC2', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF tacker to 4446'. Spotted 1000	ulfide. Push CIBP from 435 float collar from 4438-4439 OOH w/bit & drill collars. 49-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go	32' to 4427'. Drill on or
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new Times of the communicated and did not break. Flush csg with 10	Operations (Clearly sta)3. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warricot break down lower of the start of the	wire line. tripper head & period of the per	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC purp 500 gal of 15% NEF tacker to 4446'. Spotted 1000 uck. POOY w/packer. See attached sheet for additional property of the purp 500 gal of 15% NEF tacker to 4446'. Spotted 1000 uck. POOY w/packer.	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 49-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Gotonal information***	52' to 4427'. Drill on by and drill on cement RD wire line. Alt block. On lower perfs to
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new Times) 6. RU wire line & perforate 7. RIH w/treating packer set Communicated and did no break. Flush csg with 10	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD ction packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrico to break down lower possible brine water. RE	wire line. tripper head & period of the per	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC2', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF tacker to 4446'. Spotted 1000 tuck. POOY w/packer. See attached sheet for additional dedge and belief. I further certify	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go ional information***	52' to 4427'. Drill on by and drill on cement RD wire line. Alt block. On lower perfs to
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new Times of the communicated and did not break. Flush csg with 10	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD ction packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrico to break down lower possible brine water. RE	wire line. tripper head & period of the per	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC purp 500 gal of 15% NEF tacker to 4446'. Spotted 1000 uck. POOY w/packer. See attached sheet for additional property of the purp 500 gal of 15% NEF tacker to 4446'. Spotted 1000 uck. POOY w/packer.	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go ional information***	52' to 4427'. Drill on by and drill on cement RD wire line. Alt block. On lower perfs to
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory 5. RIH w/bit & drill collars. CIBP from 4427-4428 and from 4439-4485' (new Times) 6. RU wire line & perforate 7. RIH w/treating packer set Communicated and did no break. Flush csg with 10	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD ction packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrico to break down lower possible brine water. RE	wire line. tripper head & period of the per	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC 122', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF tacker to 4446'. Spotted 1000 tuck. POOY w/packer. See attached sheet for additional dedge and belief. I further certify or an (attached) alternative	ulfide. Push CIBP from 435 float collar from 4438-4439 OOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go fonal information*** that any pit or below-grade tank I e OCD-approved	22' to 4427'. Drill on or and drill on cement RD wire line. alt block. ot lower perfs to
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory of the second	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrie ot break down lower of the state of t	wire line. tripper head & period of the period of truck and perfs. Moved particles of the best of my known all permit	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC2', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF tacker to 4446'. Spotted 1000 tuck. POOY w/packer. See attached sheet for additional dedge and belief. I further certify or an (attached) alternative plan	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go donal information*** that any pit or below-grade tank is e OCD-approved	52' to 4427'. Drill on or and drill on cement RD wire line. alt block. on lower perfs to the mas been/will be But the description of the descrip
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory of the second of the	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrie ot break down lower of the state of t	wire line. tripper head & portion of the properties of the proper	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC 12', 4427-32', 4437-43', 444' pump 500 gal of 15% NEF 100cker to 4446'. Spotted 1000 uck. POOY w/packer. See attached sheet for additional ledge and belief. I further certify or an (attached) alternative plan	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go donal information*** that any pit or below-grade tank is e OCD-approved	52' to 4427'. Drill on or and drill on cement RD wire line. alt block. on lower perfs to the mas been/will be But the description of the descrip
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory of the second	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrie ot break down lower of the state of t	wire line. tripper head & portion of the properties of the proper	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC 12', 4427-32', 4437-43', 444' pump 500 gal of 15% NEF 100cker to 4446'. Spotted 1000 uck. POOY w/packer. See attached sheet for additional ledge and belief. I further certify or an (attached) alternative plan	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go onal information*** that any pit or below-grade tank I to OCD-approved Associate DATE TELEPHONE NO.	52' to 4427'. Drill on or and drill on cement RD wire line. alt block. on lower perfs to the mas been/will be But the description of the descrip
13. Describe Proposed or Completed proposed work) SEE RULE 110 1. RUPU & RU. 2. RU wire line & perforate 3. ND wellhead/NU BOP. 4. POOH w/tubing and injectory of the second of the	Operations (Clearly sta 23. For Multiple Comp tubing @4168'. RD etion packer. Tag @4427'. NU sta d push down to 4436 D). Circulate well clean well @4390-4403', 4 @4387'. RU Warrie ot break down lower of the state of t	wire line. tripper head & portion of the properties of the proper	ower swivel. Drill on iron so from 4436-4438'. Drill on head and power swivel. PC 122', 4427-32', 4437-43', 444 pump 500 gal of 15% NEF tacker to 4446'. Spotted 1000 tuck. POOY w/packer. See attached sheet for additional and belief. I further certify or an (attached) alternative plan TITLE Administrative mendy johnson@oxy.com	ulfide. Push CIBP from 435 float collar from 4438-4439 DOH w/bit & drill collars. 19-51', 4456-64', 4468-77'. E acid with 1000# of rock sa 0 gal of 15% NEFE acid. Go onal information*** that any pit or below-grade tank I to OCD-approved Associate DATE TELEPHONE NO.	22' to 4427'. Drill on and drill on cement RD wire line. It block. The perfs to the

NHU 19-633 API #30-025-37446


- 8. RIH w/bit. Tag @4468'. RU power swivel and stripper head. Clean out salt from 4468-4485'. Circulate clean. POOH w/bit. RD power swivel and stripper head.
- 9. RIH w/PPI packer. RU Warrior wire line and perform PPI acid job with 700 gal of 15% NEFE acid. Flush with brine water and circulate clean. RD Warrior. POOH w/PPI packer.
- 10. RIH w/dual injection packers set on 129 jts of 2-7/8" tubing. Arrowset 1-X Double grip packer set @4227' KTC Hydraulic Tandem packer set @4360'.
- 11. ND BOP/NU well head.
- 12. Test casing to 540 PSI for 30 minutes and chart for the NMOCD.
- 13. RDPU & RU. Clean location and return well to injection.


RUPU 04/05/2014 RDPU 04/23/2014

Found packers were set at incorrect depths.

- 1. RUPU & RU.
- 2. RU wire line & perforate tubing @4165'. RD wire line.
- 3. ND wellhead/NU BOP.
- 4. POOH w/tubing.
- 5. Latched onto packers and reset on 126 jts of 2-7/8" tubing. Arrowset 1-X Double grip set @4239'. KTC Hydraulic Tandem packer set @4308'.
- 6. ND BOP/NU wellhead.
- 7. Test casing to 620 PSI for 30 minutes and chart for the NMOCD. Witnessed by Mark Whitaker w/NMOCD.
- 8. RDPU & RU. Clean location and return well to injection.


RUPU 05/08/2014 RDPU 05/13/2014





June 5, 2014

Work Plan Report for Well:NHSAU 633-19



Survey Viewer