

Submit I Copy To Appropriate District Office	State of New Mexico			Form C-103		
District I - (575) 393-6161	Energy, Minerals and Natural Resources			LWELL AD		evised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283				WELL AP 30-025-2		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION				Type of Lease	•
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd, Aztec, NM 87410	1220 South St. Francis Dr.			STA	TE 🔲	FEE X
District IV - (505) 476-3460	Santa Fe, NM 87505			6. State Oi	l & Gas Lease	No.
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK (DE)				7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG-BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				South H	obbs (GSA) Ui	nit _
PROPOSALS.)				8. Well Number 128		
1. Type of Well: Oil Well Gas Well X Other WIW JJ 10 2015						
Name of Operator Occidental Permian Ltd.				9. OGRID Number 157984		
3. Address of Operator RECEIVED				10. Pool name or Wildcat		
P.O. Box 4294 Houston, TX 77210				Hobbs (GSA)		
4. Well Location				<u> </u>		
Unit Letter D :	335 feet from the	North	line and	520 fe	eet from the	West line
Section 3	Township 195	S Range	38E	NMPM	Lea Count	y
	11. Elevation (Show whe)	l	
	3632' KB			··		
			• •			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☒ ALTERING CASING ☐						
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐						
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB						
DOWNHOLE COMMINGLE						•
CLOSED-LOOP SYSTEM OTHER:		ПОТ	HER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or recompletion.						
Soo Attached Page						
See Attached Page						
						
Spud Date: 04/15/15 (RUPU)	Rig Re	lease Date:	05/30/15	(RDPU)		
3 1/23/23 (1.6. 3)			03,20,22			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
$\Omega \cdot / k / l = l$						
SIGNATURE / SIGNATURE	VOOOL TITLE	Regulator	y Coordinator		DATE 0	6/17/15
SIGNATURE 1500 C	1116	<u>,g</u>	,		DATL	
Type or print name April Hood	E-mai	l address: A	(o @booH_Hrid	cy.com	PHONE: _	713-366-5771
For State Use Only	<u> </u>					
R-DD	1	~ _	LH M		D Amm	912.1.
APPROVED BY: Conditions of Approval (if any):	QualmatiTLE		taff Ma	noger	DATE	1/05//)

SHU No. 128 API No. 30-025-28332

04/15/15 - 04/29/15

MI x RUPU. Killed well x ND WH x NU BOP. Release pkr x POOH 126 jts. RIH 4 3/4" shoe x 1jts of 4 1/2" wp x SION. RIH 4 3/4" wp x tag @ 4282'. Killed well x POOH 4 3/4" shoe x 1jts of 4 1/2" wp x 127 jts x tag @ 4286'. RUPS x cleaned well 4286' - 4290' x RDPS. RUWL shoot drain hole @ 3665' x RDWL. POOH tubing x 4 3/4" shoe x 1jts of 4 1/2" wp x CICR was stuck inside shoe.RIH again 4 3/4" bit x tubing x tag @ 4290'.RUPS x drill from 4290' - 4360' x RDPS x SION. RUPS x drill from 4360' to TD @4420' x RDPS. RUWL shoot perfs 4350' - 4385 x RDWL.RIH 5 1/2" pkr x tubing x set pkr @ 3952'. Run acid job with 6500 gal 15% pap acid x 1500 lbs rock salt. POOH tubing x pkr. RIH with 5 1/2" injection pkr x set @ 3950'. RUWL x log 3900' to surface x RDWL. RIH 5 1/2 rbp x set @ 990' x POOH 30 jts. ND BOP x RD x MO location.

05/28/15 - 05/30/15

MI x RU pulling unit x ND WH x NU BOP. RIH tubing and release rbp @ 992' x POOH tubing and rbp. RIH 121 jts 2 7/8 production tubing. Ran MIT test. Well in need of new injection line hookup. ND BOP x NUWH. RD X MO location. Log is attached.

