Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103 Revised July 18, 2013
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO. 30-005- 62819
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit 8. Well Number 121
Type of Well: Oil Well Name of Operator	Gas Well Other	9. OGRID Number
State of New Mexico formerly	Canyon E&P Company	9. OOKID Number
3. Address of Operator		10. Pool name or Wildcat
811 South 1st Street Artesia, 1 4. Well Location	NM 88210	Twin Lakes, San Andres (Assoc)
Unit Letter F : Section 5	Township 9S Range 29E 11. Elevation (Show whether DR, RKB, RT, GR, e	1405 feet from the W line NMPM County Chaves
	PLUG AND ABANDON IXI	MITTING <swdinjection> ERSION RBDMS_ RN TO TA ENVIROCHG LOC</swdinjection>
	See Attached Procedure and Schematic The	
Spud Date:	Rig Release Date:	
I hereby certify that the information	above is true and complete to the best of my knowled	edge and belief.
SIGNATURE	TITLE	DATE
Type or print name For State Use Qnly APPROVED BY:	Brown TITLE Dist Sug	PHONE:
Conditions of Approval (if any)	V	, ,

NOV 0 4 2015

my

Canyon E&P Company
Twin Lakes San Andres Unit No. 121
30-005-62819
UL – F, Sec. 5, T9S, R29E

8 5/8" csg at 556' w/ 345 sx cmt. Circ. 5 ½" 15.5# csg at 3090' w/ 1105 sx cmt, (7 7/8" hole) Circ. TD – 3100' Perfs 2837' – 2892' CIBP set at 2800'.

- 1. MIRU plugging equipment.
- Tag CIBP at 2800', circulate hole w/ mud laden fluid, and pressure test csg to 500 psi.
- 3. Spot 25 sx cement on CIBP.
- 4. POOH to 2100'. Spot 25 sx cmt.
- 5. POOH to 1000'. Spot 25 sx cmt.
- 6. POOH to 606'. Fill to surface w/ cmt.
- 7. Cut off wellhead 4 feet below ground level.
- 8. Verify cement to surface on all strings.
- 9. Install upright P&A marker and cut off anchors.

NOTES: Mud laden fluid consists of 9.5 ppg with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to preceding with P&A.

TWIN LAKES SAN ANDRES UNIT #121



CUT OFF WELLHEAD & INSTALL DRY HOLE MARKER

8 5/8" @ 556' w/ 345 sx. Circ.

POOH TO 606'. FILL TO SURFACE W/ CMT.

SPOT 25 SX CMT AT 1000'.

SPOT 25 SX CMT AT 2100'.

CIRCULATE MUD LADEN FLUID

TAG CIBP AT 2800'. CAP WITH 25 SX

Perfs 2837'-2892' 5 1/2 " 15.5# @ 3090' w/ 1105 sx.