Office HORRS OCD Engrave N	State of New Me		ac.	Rey	Form C-103 vised July 18, 2013
625 N. French Dr., Hobbs, NM 88240 <u>vistrict II</u> – (575) 748-1283 11 S. First St., Artesia, NN 88240 11 S. First St., Artesia, NN 882401 1220 South St. Francis Dr.		WELL AP	WELL API NO.		
		30-025-030 5 Indicate	Type of Lease		
			STATE FEE		
505 No. 10 Blazos No., Agree, No. 1710 505 No. 10 Blazos No., Santa Fe, NM 87505 505 Santa Fe, NM 87505 506 Santa Fe, NM 87505 507 Santa Fe, NM 87505			6. State O	il & Gas Lease N	Vo.
SUNDRY NOTICES AND REP (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERI	R TO DEEPEN OR PL	UG BACK TO A		lame or Unit Ag	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well G	Other SWD		8. Well No		ii Oilit
2. Name of Operator Roswell Operating, LLC	Other SWD		9. OGRID	Number 270	575
3. Address of Operator			10. Pool n	ame or Wildcat	
PO Box 351, Midland, TX 79702			Crossroads	; Siluro Devonia	an
4. Well Location					
Unit LetterA:660feet from		line and		theEast	_line
	ownship 9S	Range	2.00.77.11812	MPM	County LEA
	(Show whether DR, 27' GR	, RKB, RT, G	R, etc.)		
102	or or	Ty F F		THE RESERVE OF THE PERSON NAMED IN	
12. Check Appropriate B	ox to Indicate N	lature of No	tice Report or	Other Data	
NOTICE OF INTENTION T			SUBSEQUEN	The state of the s	
PERFORM REMEDIAL WORK PLUG AND A	The state of the s	REMEDIAL			NG CASING
TEMPORARILY ABANDON			E DRILLING OPNS	S. P AND A	
DOWNHOLE COMMINGLE	OWIFE L	CASING/CE	INICIAI JOB		
CLOSED-LOOP SYSTEM					
OTHER:		and the second second second			
William V.			iled MIT, Fished re	placed tbg/pkr a	ind returned to
		swd	The state of the s		
13. Describe proposed or completed operations.	. (Clearly state all p	swd pertinent deta	ls, and give pertine	ent dates, includi	ing estimated date
	. (Clearly state all p	swd pertinent deta	ls, and give pertine	ent dates, includi	ing estimated date
Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion.	. (Clearly state all p	swd pertinent deta	ls, and give pertine	ent dates, includi	ing estimated date
Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion.	. (Clearly state all p	swd pertinent deta	ls, and give pertine	ent dates, includi	ing estimated date
Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15	. (Clearly state all p E 19.15.7.14 NMAC	swd pertinent detai C. For Multip	ls, and give pertine le Completions: A	ent dates, includi	ing estimated date
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg wa luck. Ran free point. Cut tbg @ 11,200'. LE	. (Clearly state all p E 19.15.7.14 NMAC s parted. PU new th D 2 7/8" J-55 tbg. P	swd pertinent detai C. For Multip og. Latched or U spear and 2	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st	ent dates, includi ttach wellbore d string was stuck.	ing estimated date liagram of Worked tbg. No free. TOH w/ OS.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg wa luck. Ran free point. Cut tbg @ 11,200'. LE PU plug & pkr. Tested csg for leaks. Leaks	. (Clearly state all p E 19.15.7.14 NMAC s parted. PU new th D 2 7/8" J-55 tbg. Pl in 5 1/2", 4617' do	pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi	ent dates, including trach wellbore destring was stuck. Tring. Work tbg for, squeezed w/ 2	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do:	pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basic aned out RBP. Ret	ent dates, including trach wellbore destring was stuck. Tring. Work tbg in the control of the c	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8	Is parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for B" L-80 tbg. Circ w/	pertinent detail. C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes 30 mins. Cle / 3 drums of p	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Cha	pertinent detail. C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes 30 mins. Cle / 3 drums of p	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Cha	pertinent detail. C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes 30 mins. Cle / 3 drums of p	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Cha	pertinent detail. C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes 30 mins. Cle / 3 drums of p	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Cha	pertinent detail. C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes 30 mins. Cle / 3 drums of p	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Cha	pertinent detail. C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes 30 mins. Cle / 3 drums of p	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11	s parted. PU new the 2 2 7/8" J-55 tbg. Plants 1/2", 4617' down 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Chall.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11	s parted. PU new the 2 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Cha	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11	s parted. PU new the 2 2 7/8" J-55 tbg. Plants 1/2", 4617' down 450#. Held good for 8" L-80 tbg. Circ w/00# for 35 min. Chall.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095°. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11 pud Date:	cs parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 150#. Held good for 3" L-80 tbg. Circ w/00# for 35 min. Chall 1.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki O.K. RD JWS. Cl	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095°. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11.	cs parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 150#. Held good for 3" L-80 tbg. Circ w/00# for 35 min. Chall 1.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki O.K. RD JWS. Cl	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095′. MIT on 11.10.15, 4	cs parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do: 150#. Held good for 3" L-80 tbg. Circ w/00# for 35 min. Chall 1.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basi aned out RBP. Ret acker fluid. Set pki O.K. RD JWS. Cl	ent dates, including trach wellbore destring was stuck. Tring. Work the factor of the control o	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095°. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11.	cs parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do 150#. Held good for 3" L-80 tbg. Circ w/00# for 35 min. Chall.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" test 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work sted good. RU Basicaned out RBP. Retacker fluid. Set pkr O.K. RD JWS. Cl	ent dates, including trach wellbore destring was stuck. The string was stuck.	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set a on-off tool. Test witnessed
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg was luck. Ran free point. Cut tbg @ 11,200°. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095°. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11.	cs parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do 150#. Held good for 3" L-80 tbg. Circ w/00# for 35 min. Chall.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" tes r 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work sted good. RU Basicaned out RBP. Retacker fluid. Set pkr O.K. RD JWS. Cl	ent dates, including trach wellbore destring was stuck. The string was stuck.	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set on-off tool.
13. Describe proposed or completed operations of starting any proposed work). SEE RULE proposed completion or recompletion. 0.5.15 – 11.10.15 RU JWS. NU BOP. TOH w/ 64 jts. Tbg wa luck. Ran free point. Cut tbg @ 11,200'. LE PU plug & pkr. Tested csg for leaks. Leaks WOC, drilled out squeeze. Tested same to 4 inj. pkr AS1, nickel coated w/ new PC 2 7/8 Perfs: 12,089-12,095'. MIT on 11.10.15, 4 by NMOCD (George). Returned to SWD 11 pud Date:	cs parted. PU new the D 2 7/8" J-55 tbg. Plin 5 1/2", 4617' do 150#. Held good for 3" L-80 tbg. Circ w/00# for 35 min. Chall.11.15	swd pertinent detail C. For Multip og. Latched or U spear and 2 wn. 9 5/8" test 30 mins. Cle / 3 drums of p art attached	ls, and give pertine le Completions: A to fish. Injection s 7/8", L-80 work st ted good. RU Basic aned out RBP. Retacker fluid. Set pkr. O.K. RD JWS. Cl	ent dates, including trach wellbore destring was stuck. The string was stuck.	ing estimated date liagram of Worked tbg. No free. TOH w/ OS. 00 sxs. After H w/ Arrow-Set i on-off tool. Test witnessed

