Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-103 June 19, 2008				
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO. 30-025-09387				
1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Pa, NM 87505	5. Indicate Type of Lease				
District IV	STATE     Image: State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505	23267				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Langlie Lynn Queen Unit				
1. Type of Well:       Oil Well       X       Gas Well       Other	8. Well Number 4				
2. Name of Operator	9. OGRID Number				
Energen Resources Corporation 3. Address of Operator	162928 10. Pool name or Wildcat				
3510 N. "A" St., Bldgs A & B, Midland, TX 79705	Langlie Mattix 7 RVRS/Queen/GB				
4. Well Location					
Unit Letter K : 1650 feet from the South line and	2310 feet from the West line				
Section 23 Township 23S Range 36E	NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, e 3370' GR	etc.)				
12. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data				
NOTICE OF INTENTION TO: SUI	BSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK D PLUG AND ABANDON I REMEDIAL WORK	ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	ЈОВ 🔲 ІНТ ТО РА 🚣 🗡				
	P&A NR				
	P&A R				
OTHER: OTHER:					
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>					
Energen Resources submits Plug and Abandon procedure for the LLQU #4. See attached:					
Thank you!	- 70				
	A HOURS PRIOR TO				
NOTIFY OCD	24 HOURS PRIOR TO PLUGGING OPERATIONS				
BEGINNING					
Spud Date: Rig Release Date:					
I hereby certify that the information above is true and complete to the best of my knowled	ge and belief.				
Bar 1 W					
SIGNATURE / Menda Kiabyer TITLE Regulatory Analyst DATE 09/06/2017 Brenda.rathjen@energen.com					
Type or print name Brenda F. Rathjen E-mail address:PHONE 432-688-3323					
For State Use Only					
APPROVED BY Mallititation TITLE Etro leum E	Engr. Specific DATE 09/07/2017				
Conditions of Approval (if any):					

#### **ENERGEN RESOURCES CORPORATION** Langlie Lynn Queen Unit #4, API # 30-025-09387

1650' FSL,2310' FWL Sec. 23, T-23-S, R-36-E Lea County, NM

The LLQU #4 was completed as a 7Rivers-Queen producer. There is no known uphole potential. The well is not currently economic to produce. Following an attempt to TA the well, the liner top was was leaking and would not hold pressure, so the well will not pass the required MIT test and needs to to plugged and abandoned.

For scope changes during work, stop and discuss with engineering before proceeding

API:	30-025-09387	KB:	3380'	PBTD: 3740'
Spud Date:	8/18/1949	GLE:	3370'	TD: 3750'

**Temporary Abandon Procedure** 

#### SAFETY CONSIDERATIONS

**Observe all Energen Guidelines for PPE and H2S Safety** Observe perforation and contractor safety guidelines Wireline and explosives on location while perforating Workstring should be in good condition and tested to 5000 psi. BOP should be in good working condition and tested Rig anchors will need to be tested prior to MIRU Keep a TIW valve open and on the rig floor at all times

Notify the NM OCD 24 hours prior to starting P&A operations Notify the BLM prior to starting P&A operations Meet with engineer, superintendents, and consultant prior to beginning the job, to assure that everyone is agreement with the procedure.


- 1 MIRU Well Service Unit.
- 2 Bleed well down.
- 3 NDWH
- 4 NU adapter flange and BOP for 7-5/8" csg and 2-3/8" tubing. Test to 500 psi above working pressure.
- 5 POOH and LD production string.
- 6 Use production tubing as workstring or:
- 7 Unload and rack 3600' 2-3/8" workstring. Maintain kill truck w/10 ppg brine on location.
- 8 RIH, tag cement @3338' above CIBP @ 3358'
- 9 RIH w/ workstring and circulate hole to 10 ppg mud SPOT CMT FROM TAG TO 2650. (40 SX Class'L') 10 Perf and squeeze 100 sx Class "C" cement at 3030-3700' (Yates and liner top), WOC and tag. WOC TAG
- 11 Pressure test casing to 500 psi.
- 12 Perf and squeeze 50 sx "C" 1433'-1333' (top salt), WOC and tag
- 13 Perf and squeeze 50 sx "C" 1285-1185' (shoe), WOC and tag,
- 14 Perf and squeeze cement from 400' to surface.
- 15 ND BOP. Top off well with cement. Verify cement to surface, all strings.
- 16 RD and clean location.
- 17 Cut off all casing strings at base of cellar or 3' below restored ground level.
- 18 Cover wellbore with metal plate welded in place or with cement cap.
- 19 Erect capped abandonment marker inscribed with well information.
- 20 Cut off dead man anchors and fill in cellar. RDMO.
- 21 Clean and restore location to natural condition and fulfill any and all regulatory requirements.

H:\Central Basin Platform\LLQU\Well Data (all wells)\LLQU #4 P&A.xlsx

# ENERGEN RESOURCES, INC.

Langlie Lynn Unit #4 Lea County, NM

None



### GL Elevation: 3370'

KB Elevation: 3380'


Location: 1650' FSL, 2310' FWL, Sec 23, T-23-S, R-36-E

9/5/2017

H:\Central Basin Platform\LLQU\Well Data (all wells)\LLQU #4 P&A.xlsx

## ENERGEN RESOURCES, INC.

Langlie Lynn Unit #4 Lea County, NM



### PBD: 3740'

TD = 3750'

H:\Central Basin Platform\LLQU\Well Data (all wells)\LLQU #4 P&A.xlsx

GL Elevation: 3370'

KB Elevation: 3380'

Location: 1650' FSL, 2310' FWL,