Office	f New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.
		30-015-05587
811 S. First St., Artesia, NM 88210 OIL CONSER	VATION DIVISION	5. Indicate Type of Lease FEDERAL
1000 Pio Brazos Pd Aztec NM 87410	th St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 Santa F 1220 S. St. Francis Dr., Santa Fe, NM	Fe, NM 87505	6. State Oil & Gas Lease No.
87505		NM 014102
SUNDRY NOTICES AND REPORTS ((DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		North Shugart Queen Unit
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	HOBBS OCD	8. Well Number o
2. Name of Operator	FFD 0 4 0040	9. OGRID Number
State of New Mexico formerly Tom R Cone	FE3 012018	188152
3. Address of Operator	DEOFILIEN	10. Pool name or Wildcat
1625 N. French Drive Hobbs, NM 88240	RECEIVED	Shugart; Yates-7rs-Qu-GB
4. Well Location Unit Letter P : 990 feet from the South line and 660 feet from the East line		
	whether DR, RKB, RT, GR, etc.	<u>,</u>
11. Elevation (Snow whether DA, RRD, RT, OK, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		
PERFORM REMEDIAL WORK PLUG AND ABANDO		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING DULTIPLE COMPL		т јов
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
SEE ATTACHMENTS		
SEE ATTACHMENTS		
'LPC'AREA		
LF	LAKEA	
03/01 the 06/15		
05/01 1110 00/15		
	*	
Spud Date: Rig	Release Date:	
I have her earlier that the information above is true and some	ato to the heat of my knowledge	a and haliaf
I hereby certify that the information above is true and compl	ete to the best of my knowledg	e and beller.
MA OFFICE 21.1-12		
SIGNATURE Marken TIT	TLE Petroleum Engr Specialis	t DATE 2/1/2018
Type or print name Mark Whitaker E-r	nail address:	PHONE: 575-393-6161
For State Use Only		
VVI AL MERCUM ADDI 211000		
APPROVED BY: DATE 2018		
Conditions of Approval (if any):		
v		

Tom R Cone North Shugart Queen Unit No. 9 30-015-05587 UL – P, Sec. 20, T18S, R31E 990' FSL & 660' FEL BLM Serial #: NM – 014102

7" 20# @ 855' w/ 350 sx cmt 4 1/2" 9.5# @ 3749' w/ 450 sx cmt TD 3750' Perfs 3224' – 3246'

- 1. MIRU. POOH w/ production equipment.
- 2. Set CIBP at 3124'. Circulate hole with mud laden fluid. Pressure test casing to 500 psi. Spot 25 sx cement on CIBP.
- 3. Spot 30 sx cement at 1900'.
- 4. Spot 25 sx cement @ 905'. WOC & Tag.
- Perf at 100'. Circulate cement to surface inside/outside 4 ½" casing.
- 6. Cut off wellhead 3' below ground level and verify cement to surface all strings.
- Install below ground P&A marker. Photos should be taken prior to and after welding on plate. Record GPS reading. BLM should be notified prior to cut off so it can be witnessed.

NOTES: Mud laden fluid consists of brine water with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.



Tom R Cone North Shugart Queen Unit No. 9

7" 20# @ 855' w/ 350 sx. Top Salt 858'

Base Salt 1840'

Perfs 3224 -46'

CIBP @ 3440' w/ 50' cmt

Perfs 3666'-3720' 4 1/2" 9.5# set at 3749' w/450 sx. TD 3750'



Tom R Cone North Shugart Queen Unit No. 9 CUT OFF WELLHE

CUT OFF WELLHEAD 3' BELOW GL INSTALL BELOW GROUND MARKER PERF AT 100'. CIRC CMT TO SURFACE.

7" 20# @ 855' w/ 350 sx. Top Salt 858'

SPOT 25 SX CMT AT 905'. WOC & TAG.

Base Salt 1840'

SPOT 30 SX CMT AT 1900'

SPOT 25 SX CMT ON CIBP SET CIBP AT 3124'. CIRC MLF. PRESSURE TEST CSG

Perfs 3224 -46'

CIBP @ 3440' w/ 50' cmt

Perfs 3666'-3720' 4 1/2" 9.5# set at 3749' w/450 sx. TD 3750'