Submit 1 Copy To Appropriate District	State of New Me	xico	Form C-103
Office  District I – (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-10784
<u>District III</u> – (505) 334-6178	1220 South St. Fran	icis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	<b>'</b> 505	STATE FEE XX
1220 S. St. Francis Dr., Santa Fe, NM	·		6. State Oil & Gas Lease No.
87505			
	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	SALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FOR MEC. 1615 Fe	JG BACK TO A NR SLICH	77 0
,		a.ocd	E.L. Steeler  8. Well Number 002
7 4	Gas Well Other SED 10	10010	
2. Name of Operator	9E/	ZU <b>18</b>	9. OGRID Number
Yarbrough O			025504 /
3. Address of Operator	RECENT 769, Eunice, NM 88231	VED	10. Pool name or Wildcat Langlie Mattix SR-QU-GB
	703, Eunice, NW 88231		Langue Mattix SR-QU-GB
4. Well Location			
Unit Letter A : 660 feet from the North line and 660 feet from the East line			
Section 17 Township 23S Range 37E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO SUBS			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK [ REMEDIAL WOR			
TEMPORARILY ABANDON [ INT TO PA COMMENCE DR		LLING OPNS.□ P AND A XX	
PULL OR ALTER CASING [			JOB 🗌
DOWNHOLE COMMINGLE [	P&A R		
			_
OTHER:	loted exerctions. (Clearly state all s	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
SEE ATTACHED			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
aludia.			
7/1918			
SIGNATUREDATEDATE			
Type or print nameJohn R. Stearns, Jr E-mail address: bobbystearns1@yahoo.com PHONE: 575-760-2482			
For State Use Only			
Conditions of Approval (if any):			

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By 02-28-2019

## Plugging Report E.L. Steeler #2 30-025-10784

- 2/19/2018 Move in rig up and install BOP. RIH with gauge ring and tag tubing in the hole at 198'. Picked up 5 3/4" overshot with a grapple to catch a 2 3/8" body break. Could not get grapple to grab tubing. POOH with overshot and SION.
- 2/20/2018 RIH with 5 ¾" overshot with a 32' wash pipe extension dressed to catch the collar below the top of the fish. Caught collar and worked tubing free. POOH with overshot and laid down. Fish was a 2 3/8" tubing pin. Laid down 124 joints 3 3/8" tubing, a seating nipple, and a 4' perforated sub with no collar on the bottom. Picked up 6 ¼" drill bit, 6 collars, and started in the hole with the work string. RIH with 71 joints and SION.
- 2/21/2018 Finished picking up work string and tagged up at 3613'. Picked up swivel and caught circulation with 80 bbls. Drilled soft fill from 3613' to 3713'. Made another 3' of hard drilling. Getting back large pieces of metal. SION at a depth of 3716'.
- 2/22/2018 Continued drilling out. Made 1 foot in 6 hrs. Getting small metal shavings in the returns. POOH with tubing and stood back collars. Bit was worn out. Called OCD to report conditions.
- 2/23/2018 RIH with new bit and continued to drill out junk in the hole. Made another 8" in 4 hrs. Called OCD. Got permission to plug from current depth of 3718'. POOH with bit and collars. Rigged down reverse unit and SION.
- 2/26/2018 RIH with tubing and circulated MLF. Spotted 25 sx cement at 3718'. POOH to 2889' and spotted 50 sx cement with CaCl to cover the existing perforations. WOC and did not tag cement. Spotted another 25 sx cement at 1889' with CaCl and SION.
- 2/27/2018 Tagged cement at 2861'. POOH to 2445'. Established circulation and pressured up on the wellbore to 450# and held. Bad casing from 2300' to 2391 will not take fluid. Spotted 45 sx with CaCl across bad casing from 2445'. WOC and tagged cement at 2238'. POOH to 1682' and spotted 25 sx of cement. ETOC at 1493'. POOH with tubing and perforated 7 " casing at 1168'. Set packer at 889' and pressured up on perfs to 500#. Held pressure with no drop. POOH with packer and RIH with tubing to 1238' and spotted 30 sx cement. POOH and SION.
- Tagged cement at 1079'. Perforated 7" casing at 305'. Closed BOP and pressured up on wellbore to 500#. Perforations will not take fluid. RIH with tubing to 355' and filled up 7" casing with 60 sx cement. Rigged down and cut off wellhead. Cement was to surface inside 7" casing. Filled up 7" x 13 3/8" annulus to surface with 75 sx. Installed marker and cut off anchors. Moved equipment off location.

All fluids circulated to at steel pit.