

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Stevens
8. Well No. 3
9. Pool name or Wildcat Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Charles B. Gillespie, Jr.
3. Address of Operator P. O. Box 8 Midland, Texas 79702
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>14S</u> Range <u>33E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4214 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☒
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cast iron bridge plug above perforations at 9750'.
Dump 4 sx cement on top of bridge plug, WOC.
2. Set 25 sx plug at 7700', across top of ABO.
3. Set 50 sx plug across liner top at 4108', Tag.
4. Cut off and pull 7 5/8" casing from approximately 2650'.
5. Set 50 sx plug across 7 5/8" casing stub and across base 9 5/8" casing shoe at 2617'.
6. Set 25 sx plug at 1600' across top of salt.
7. Set 25 sx plug at 1100' across top of 9 5/8".
8. Set 25 sx plug at 424' across base of 13 3/8" casing shoe.
9. Set 10 sx plug at top of surface casing.
10. Weld 4" marker to surface pipe, and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David W. Hastings TITLE Production Manager DATE 6/1/89

TYPE OR PRINT NAME David W. Hastings TELEPHONE NO.

(This space for State Use) **ORIGINAL SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OIL FIELD RECORD BOOK

JUN 5 1989

71 2