orm 3160-5 lovember 19 formerly 9-3	331) DEPAR	UNITED STA RTN 'T OF THI REAU OF LAND MA	E INTERIOR	SUBMIT IN TRIPLICATI (Other instruct on i verse side)	Expir	er Dureau No. es August 31, Esignation and	1985	
(Do no	SUNDRY NO	OTICES AND RE	PORTS ON epen or plug back i	WELLS to a different reservoir.		W, ALLOTTEE OR	TRIBE NAME	
OIL X						7. UNIT AGREEMENT NAME		
2. NAME OF O			<del></del>	TOP STEE	8. FARM OF	LEASE NAME		
Phillips Petroleum Company						Wyatt Federal "A"		
3. ADDRESS OF	OPERATOR	<b>-</b>		V	9. WELL H	),		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface						3 10. FIRLS AND POOL, OR WILDCAT  Molicipana CD /CD		
					Sec.	33, 17 <b>-</b> S	, 33 <b>-</b> E	
14. PERMIT NO.	<del></del>	15. ELEVATIONS (SI	now whether DF, RT,	GR, etc.)	12. COUNTY	OR PARISE 18	. STATE	
_Api 30-	-025-01366	4068'	RKB		Lea		NM	
16.		Appropriate Box To	Indicate Natur	e of Notice, Report, or	Other Data			
NOTICE OF INTENTION TO:						OF:		
TEST WAT	ER SHUT-OFF	PULL OR ALTER CASIN		WATER SHUT-OFF		REPAIRING WELI		
FRACTURE		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASIN	1	
SHOOT OR	ACIDIZE	ABANDON*	x	SHOOTING OR ACIDIZING		*THE WOODNAGE		
REPAIR WE	:LL	CHANGE PLANS		(Other)(Norm: Report result	ts of multiple	completion on '	Wall	
(Other)	DOMINES OF COUNTY PECO	onen enove (Clearly sta	to all postingus, dos	Completion or Recor	pietion Report	and Log form.)		
proposed	work. If well is dir his work.) *	ectionally drilled, give s	ubsurface locations	ails, and give pertinent date and measured and true vert	ical depths for	all markers an	d sones perti	
1.	Test all ar	nchors. MI RU	DDU. NU BO	P's.				
2.	Fish stuck	2-3/8" 4.7# J-	55 tubing (	(4317') from 5-1/	2" casing			
3.	Set 4" CIBF PBTD 4300'.	P at 4300'. Ci	rculate hol	e with 9.5 ppg m	ud-laden	fluid fro	om	
4.		No. 1 (25 sx. c						
5.	Spot Plug N	lo. 2 (25 sx. c	ement) <b>340</b> 0	1' - 3600'. TAG	PUG:			
6.	Plug No. 3	perforate and	squeez <b>e (45</b>	sx. cement) 238	5' - 2485	TAG PI	uc.	
7.	Plug No. 4	perforate and	squeeze (45	sx. cement) 138	5' - 1485	1. TAG	PLUC	
8.	Freepoint a	ind pull 5-1/2"	casing. N	leed to pull 1050	+.			
9.	Spot Plug N	lo. 5 (20 sx. c	ement) 975'	- 1100'. Tag p	lug.			
	with Plug N	lo. 6 (150 sx.	O'. Set EZ cement) 3'	SV at 800'. Circ - 900'.	culate to		(Over)	
18. I bereby ce	rtify that the foregoin							
SIGNED	X M. Ola. L. M. Sander		TITLE Super	visor, Reg. Affai	rs DAT	11/9/92 915/368-1	488	
	for Federal or State	office use)						
APPROVEI	NS OF APPROVAL, I	FANT:	TITLE	· · · · · · · · · · · · · · · · · · ·	DAT	1117	192	
			612 PRio	R TO COMMENCIA	ic pàn	OPERATI	on.	

- 11. Spot Plug No. 7 (140 sx. cement) 3' 800'.
- 12. Cut off casing 3' below GL, install monument marker. Perform reclamation work.