Form 3150-5

| (August 1999) | DEPARTME OF THE I | INTERIOR | OMB No. 1004-0135 Expires November 30, 2000 |
|---------------------|--|---|--|
| | BUREAU OF LAND MANA | AGEMENT | 5. Lease Serial No. |
| S | UNDRY NOTICES AND REPO | ORTS ON WELLS | NM- 0424 2 9 9146 |
| Do not abando | use this form for proposals to ned well. Use Form 3160-3 (API | drill or to re-enter an D) for such proposals. | 6. If Indian, Allottee or Tribe Name |
| SUBMIT | IN TRIPLICATE - Other instru | uctions on reverse side | 7. If Unit or CA/Agreement, Name and/or No. |
| 1. Type of Well | | | |
| 🛛 Oil Well 🚨 Gas | Well Other | 8. Well Name and No. | |
| 2. Name of Operator | | | Denius Federal # 2 |
| Southwestern E | nergy Production Compan | ıy | 9. API Well No. |
| 3a. Address 2350 N. | Sam Houston Pkwy. E., | 3b. Phone No. (include area code) | 30-025-01375 |
| Suite 300, Hous | | 281-618-4739 | 10. Field and Pool, or Exploratory Area |
| | tage, Sec., T., R., M., or Survey Description | n) | Corbin (Abo) |
| 1980' FSL & 198 | | | 11. County or Parish, State |
| Sec. 33-17S-33E | | | Lea |
| 12. CHE | CK APPROPRIATE BOX(ES) T | O INDICATE NATURE OF NOTICE, | REPORT, OR OTHER DATA |
| TYPE OF SUBMISS | ION | TYPE OF ACTION | |
| | Acidize | Deepen Production (St | art/Resume) |
| Notice of Intent | ☐ Alter Casing | Fracture Treat Reclamation | ☐ Well Integrity |
| | Casing Repair | New Construction Recomplete | Other |
| Subsequent Report | Caoing Repair | | |

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon Plug Back

Temporarily Abandon

■ Water Disposal

Please see attached procedure.

Change Plans

Convert to Injection


| 4. I hereby certify that the foregoing is true and correct Name (Printed/Typed) | | | | |
|---|---------------------------------------|-------------------------------------|--|--|
| Vonnie J. Cermin | Title Drilling / Pro | Title Drilling / Production Analyst | | |
| Signature // WMU A | Date 11/25/02 | | | |
| APPROVED THIS SPACE FOR FELL | DERAL OR STATE OFFICE US | E | | |
| Approved by (ORIG. SGD.) DAVID R. GLASS | Title | Date | | |
| Conditions of approval, it has a stacked Approval of this notice does no certify that the applicant holds legal or equitable title to those rights in the swhich would entitle the applicant to conduct operations thereon. | ot warrant or subject lease Office | | | |

Title 18 U.S.C. Section F00 and Title 43 U.S.C. Section 212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictuious or fraudulent statements or representations as to any matter within its jurisdiction.


Final Abandonment Notice

Denius Federal No. 2 Corbin Abo Field P&A Procedure

- 1. MIRU rig. NU BOPs.
- 2. RU EL and RIH w/ gauge ring and junk basket. RIH and set through tubing bridge plug at 8550'. Dump 35' cement on top of bridge plug.
- 3. TIH w/ workstring. Tag TOC on bridge plug. Circ well with 9.5# salt gel mud (9.5# brine mixed w/ 25 lbs gel/bbl). POOH.
- 4. RU WL and cut 4-1/2" casing at 4814'. Pull casing. TIH and spot 35 sx cement plug from 4714'-4864'. POOH.
- 5. RU WL and RIH. Tag TOC. Cut 8-5/8" casing at 370'. RD WL. TIH and spot 90 sx cement plug from 270'-420'. POOH.
- 6. RU WL and RIH. Tag TOC. TOOH and RD WL. Spot 45 sx surface plug from 0'-60'.
- 7. Cut casing off 5' below ground level and install dry hole marker.
- 8. RDMO rig.



| Revised | PRESENT COMPLETION | | | | Drawn | WKB |
|---------|----------------------|--|-----------|----|----------|----------|
| | LEASE: | Denius Federal | WELL: | 2 | | 8/6/2002 |
| | LOCATION: | Corbin Abo | | | Approved | |
| | COUNTY: | Lea | STATE: | NM | | |
| | PRODUCING FORMATION: | Abo | Formation | | Date | |
| | | Southwestern Energy Production Company GOPET | | | | |



| Revised | | PROPOSED COM | PLETION | | Drawn | WKB |
|---------|------------------------------------|-----------------------|-----------|---------------|----------|----------|
| | LEASE: | Denius Federal | WELL: | 2 | | 8/6/2002 |
| | LOCATION: | Corbin Abo | | | Approved | |
| | COUNTY. | Lea | STATE: | NM | | |
| | PRODUCING FORMATION: Abo Formation | | | Date | | |
| | S | Southwestern Ener | gy Produc | ction Company | | |