

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN FR. DATE
(Other instructions on re-
verse side)

Budget Bureau No. 1-04-
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

1C 032233 (a)

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface UNIT LTR P, 330' FSL & 330' FEL

7. UNIT AGREEMENT NAME

N. HOBBS (G/SA) UNIT

8. FARM OR LEASE NAME

SECTION 30

9. WELL NO.

441

10. FIELD AND POOL, OR WILDCAT

HOBBS (G/SA)

11. SEC., T., R., X., OR BLE. AND SURVEY OR AREA

SEC. 30, T18S-R38E

14. ~~XXXXXXX~~ API NO.

30-025-07473

15. ELEVATIONS (Show whether DF, RT, CL, etc.)

3646' DF

12. COUNTY OR PARISH

LEA

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) LOG & RUN 5" LNR

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Pull production equipment.
2. Run a GR log, capacitance survey & a temp survey.
3. Take crossflow checks from 3965' - 4190'.
4. Log w/caliper tool from PBDT to surf.
5. Deepen well to ±4275'.
6. Run 5" lnr from 3770' - 4274'. Note: Cmt design to be determined at a later date.
7. CO to TOL.
8. CO to FS. Pull tbg to 4250'. Pmp 500 gals 15% HCl around end of tbg tail. Reverse out acid.
9. Run GR/CBL/CCL from PBDT to TOL.
10. Perf San Andres 4113' - 4201' (2 JSPF, 36 holes).
11. Acidize perfs 4113' - 4201' w/1800 gals 15% HCl.
12. Install production equipment and return well to production.



18. I hereby certify that the foregoing is true and correct

SIGNED A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE NOVEMBER 19, 1986

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 11 24 86

*See Instructions on Reverse Side