

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OCCUPY OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL GAS WELL OTHER
Name of Operator: **Chevron U.S.A. Inc.**
Address of Operator: **P.O. Box 670 Hobbs, NM 88240**
Location of Well:
UNIT LETTER **C**, **660** FEET FROM THE **North** LINE AND **1980** FEET FROM THE **West** LINE, SECTION **25**, TOWNSHIP **20S**, RANGE **36E** NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) **3553**
12. County **Lea**
7. Unit Agreement Name: **Eunice Monument S. Un**
8. Form or Lease Name:
9. Well No.: **104**
10. Field and Pool, or Wildcat: **Eunice Monument G/SA**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

<input type="checkbox"/> FORM REMEDIAL WORK	<input type="checkbox"/> PLUG AND ABANDON	<input type="checkbox"/> REMEDIAL WORK	<input type="checkbox"/> ALTERING CASING
<input type="checkbox"/> PARTIALLY ABANDON	<input type="checkbox"/> CHANGE PLANS	<input type="checkbox"/> COMMENCE DRILLING OPNS.	<input type="checkbox"/> PLUG AND ABANDON
<input type="checkbox"/> OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/> CASING TEST AND CEMENT JOBS	<input checked="" type="checkbox"/> OTHER dpn, log, acdz

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) 30Z RULE 1503.

TD: 4053' PB: 4053' Work performed 3-5-88 through 3-14-88

POOH w/production equipment. Change out wellhead to 7 1/16", NU BOP, test to 600psi, ok. TIH, tag at 3812'. Break circulation w/air mist. Drill f/3812-3906', circulate hole clean. Drill f/3906 to 4029' circ hole clean. Drill f/4029' to 4053'. Circ. hole clean, Run GR/CCL/CNL. Establish circulation and ream f/3841 to 4053'. Circ hole clean. TIH w/ 2 3/8" pkr at 3833 and top of ET @ 3959'. Swab. Reset pkr at 3838', swab dry, acidize w/500 gallons 15% NEFE, swab. TIH /w 2 3/8" to 3946'. SN at 3911'. ND BOP, NU tbg flange. Hang well on. Add 10 gallons corr. inhibitor prior to running pmp and rods. Load tbg and tst to 500#, ok. Pmp action ok, RDMO, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by: M. E. Abrin TITLE: Staff Drilling Engr. DATE: March 18, 1988
Signed by: Paul Kautz Geologist
DATE: MAR 24 1988

RECEIVED
MAR 23 1988
D-6
HOBBS OFFICE

11 11 11
11 11 11
11 11 11