

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-05639
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2656
7. Lease Name or Unit Agreement Name	NORTH MONUMENT GB/SA UNIT BLK. 5
8. Well No.	12
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
AMERADA HESS CORPORATION

3. Address of Operator  
POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location

Unit Letter L (3) 1980 Feet From The SOUTH Line and 660 Feet From The WEST Line

Section 19 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #512

MIRU pulling unit. ND wellhead. TOH w/rods. NU BOP. TOH w/tubing. TIH w/bit, drill collars, and tubing. Tag old plug at 3,890'. Note: If plug is not within 20' of 3,890' procedure will be modified. Clean out OH to 3,920'. TOH w/bit. RU cementers. TIH w/tubing OE and spot cement plug from 3,920' to 3,870'. (Use oyster shells to establish circulation if necessary.) WOC 24 hours. RU Schlumberger and perforate with 4" casing gun from 3,800'-3,824' w/2 SPF 180 Deg. phased (24 feet, 49 holes total). RD Schlumberger. RU acid co. TIH w/sonic hammer on tubing to TD. Acidize OH and perforations w/5,000 gals. 15% NEFE DI HCL w/3% DP-77MX. RD acid co. TOH w/tubing and tool. TIH w/packer and set at ±3,750'. Swab back acid load. TOH w/packer and tubing. TIH w/production tubing. ND BOP. NU wellhead. TIH w/rods and pump. Return well to producing status. RDMO pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 06-23-95

TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JUL 05 1995

1997 00 111

RECEIVED

JUL 03 1995

UCD HOBBS  
OFFICE