## Attachment - C-102

## Gulf Cil Corporation - F. W. Kutter "B" No. 2-E, 26-198-37E

## Propose to shock 5-1/2" casing as follows:

1. Pull rods, pump and tubing.

2. Bun tubing with hockwall packer and set packer in base of 5-1/2" easing.

3. Pressure above packer to determine if easing loak exists.

## If leak is indicated, propose to repair leak as follows:

1. Pull tubing and packer.

2. Bun wire line magnesium bridge plug and set in base of 5-1/2" casing.

3. Run HRC tool and locate leak interval.

A. Run magnesium coment retainer and set 50' above look interval.

5. Attempt to circulate sement to the surface of 5-1/2" - 7-5/8" annulus.

6. If leak is found near the surface, perforate 2 heles at 1347' and attempt to circulate sement to the surface (Base of intermediate sasing at 1347').

7. Wait on coment.

8. Drill out sement retainer and sement in 5-1/2" easing.

9. Pressure test 5-1/2" easing with 500# surface pressure for 30 minutes. 10. If pressure helds, drill out bridge plug and return well to production.