

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Aztec Oil & Gas Company		8. Farm or Lease Name Burke	
3. Address of Operator P.O. Box 837, Hobbs, New Mexico 88240		9. Well No. 1	
4. Location of Well UNIT LETTER P 990 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 19-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Eumont	
15. Elevation (Show whether DF, RT, GR, etc.) 3594' D.F.		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject Well was plugged 1-10-75 in the following manner.

The Commission was notified 24 hours prior to beginning plugging operations.

1. Circulated out Well fluids and loaded hole w/9# mud laden brine.
2. Set 100' Cement plug (30 sxs.) At casing shoe at 3539'
3. Pull tubing to 2100' and set 100' cement plug (30 sxs.) At top of salt using 9# mud laden brine. To spot
4. Cut off well head, set 10 Sx cement plug at surface and install dry hole marker.
5. Cut off dead men anchors, clean, clear & level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Petroleum Engineer** DATE **1-27-75**

APPROVED BY _____ TITLE _____ DATE **FEB 21 1975**

CONDITIONS OF APPROVAL, IF ANY: