

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator
Atlantic Richfield Company
3. Address of Operator
P. O. Box 1710, Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER **A** **330** FEET FROM THE **North** LINE AND **330** FEET FROM
THE **East** LINE, SECTION **33** TOWNSHIP **19S** RANGE **37E** NMPL.
10. Field and Pool, or Wildcat
Eunice Monument Grbg SA
7. Unit Agreement Name
8. Farm or Lease Name
James H. Williams
9. Well No.
1
12. County
Lea
15. Elevation (Show whether DF, RT, GR, etc.)
3587' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING OTHER CASING TEST AND CEMENT JOB
OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
TD 4152', PBD 3935'. Presently completed OH 3762-3935'.
15 1/2" OD 70# csg set @ 281' & cmtd w/250 sx.
9-5/8" OD 40# csg set @ 2613' & cmtd w/200 sx.
7" OD 24# csg set @ 3762' & cmtd w/65 sx.
This well is depleted in the present zone and no other recompletion prospects remain. Propose to P&A in the following manner:
1. Rig up, install BOP & POH w/completion assy.
2. RIH w/7" cmt retr on 2-3/8" tbg & set retr @ 3700'. Sting into retr & pump 35 sx Cl C cmt cont'g 4% gel thru retr @ 3700', pull up out of retr & spot 6 sx Cl C cmt on top.
3. POH w/tbg. Fill hole w/heavy gelled mud between all cmt plugs. POH w/tbg.
4. Cut 7" OD csg from free point. Free point estimated to be @ 3000' & pull.
5. Spot 45 sx Cl C cmt cont'g 4% gel across 7" OD csg stub @ 3000' (100' minimum plug).
6. Spot 45 sx Cl C cont'g 4% gel across 9-5/8" OD csg shoe @ 2613' (100' minimum plug).
7. Perforate 9-5/8" OD csg w/4 JS @ approx 1500'.
8. Set 9-5/8" cmt retr @ 1300' & pump 200 sx Cl C cmt cont'g 4% gel thru perms @ 1500', circ cmt to 15 1/2" csg shoe @ 281' or surface if possible.
9. Spot 10 sx Cl C cmt @ surface, install regulation dry hole marker @ surface, clean & level location.

Expires 10/1/76

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNED *L Roy Knott* TITLE Dist. Drlg. Supv. DATE 6/7/76
PROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: