

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3 - NMOCC
1 - File

JUL 20 9 35 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name East Esmont Unit
3. Address of Operator P. O. Box 249, Hobbs, New Mexico 88240	9. Well No. 90
4. Location of Well UNIT LETTER H 660 FEET FROM THE East LINE AND 1980 FEET FROM THE North LINE, SECTION 34 TOWNSHIP 19S RANGE 37E N.M.P.M.	10. Field and Pool, or Wildcat Esmont Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3595 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well presently completed through perforations in 5" liner from 3864-74, 3898-3904'. PHTD 3918'. It is proposed to run collar tie-in log, set 5" cast-iron bridge plug at 3860' and dump one sack cement on top. Perforate 5" liner 3723', 24, 25, 26, 28 29; 3757, 58, 59, 60, 61, and 62'. Treat with 500 gal. acid, 10,000 gal. gelled brine and 15,000 lbs. 20/40 sand. Run rods and tubing and put well back on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:
SIGNED C. L. Wade TITLE Area Supt. DATE 7-24-69

APPROVED BY John W. Runyan TITLE Geologist DATE 7-24-69

CONDITION OF APPROVAL, IF ANY: