

12. POOH to 50'. Spot 13 sx (50') surface plug. LD last of tubing.
13. Cut off casing 3' below GL.
14. Weld steel plate with well name and number on 13 3/8" casing. RD MO location.
15. Install dry hole marker with well name, number and location as required by BLM.
16. Backfill cellar and any pits. Clean up area.

* Acceptable cement is 1.32 cu.ft./sx and 14.8 ppg. Keep hole loaded and full w/ 10.0 ppg brine mixed w/ 25 sx of gel per 100 bbls.

**If 5 1/2" casing is not recovered or if economics so justify, cutting and pulling casing may be replaced with perforating and squeezing in Steps 8, 9, 10, and 11.

025/AA