

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
E-1782

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Jake L. Hamon	8. Form or Lease Name Union State
3. Address of Operator 611 Petroleum Building - Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER H 660 FEET FROM THE East LINE AND 1930 FEET FROM THE North LINE, SECTION 30 TOWNSHIP 20-S RANGE 36-E N.M.P.M.	10. Field and Pool, or Wildcat North Osudo Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3649' GR 3665' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in, rig up, install B. O. P.
2. Tubing stuck, cut tubing off at 7450'.. Unable to get cutter below 7450' Checked w/Dist. Engineer. O. K. to cut and set 200' plug @ 7450'. Tag 25 sacks plug @ 7450' and tag @ 7250'.
3. Run tubing and displace hole with mud.
4. Weld on to 5 1/2" casing and cut at 5210'
5. Pull 5 1/2" casing and set 100' plug, 50 sacks, @ 5210'. Tag plug @ 5082'
6. Weld on to 9 5/8", cut @ 728' and pull.
7. Set 75 sack plug at stub, 50' inside 9 5/8", tag plug at 657'.
8. Set 100', 75 sacks, plug at 423', tag plug at 323'.
9. Set 10 sack plug at surface, install P & A marker. Well P & A January 24, 1980
10. Clean location, ready to inspect.

Displaced hole and all plugs with mud. Plugged by Baber Well Service Co.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cecil H. Baber TITLE Petroleum Engineer DATE March 3, 1980

APPROVED BY Ronald M. Eastberry TITLE OIL & GAS INSPECTOR DATE NOV 8 1983

CONDITIONS OF APPROVAL, IF ANY: