

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-24494

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Perla

1. Type of Well:  
OIL WELL  GAS WELL  OTHER Dry

8. Well No. 1

2. Name of Operator  
Nearburg Producing Company

9. Pool name or Wildcat  
Wildcat

3. Address of Operator  
P. O. Box 823085 Dallas, Texas 75382-3085

4. Well Location  
Unit Letter J : 2310 Feet From The South Line and 1980 Feet From The East Line

Section 19 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon as follows:

1. Set CIBP @ 8,800'. Dump 35' cement on CIBP with bailer.
2. Load hole with mud, 25# gel per bbl.
3. Spot 40 sx plug from 5,100' to 4,980' (liner top 5,046').
4. Spot 40 sx plug from 1,774' to 1,670'.
5. Spot 10 sx surface plug.
6. Set dry hole marker.
7. Restore location.

Note: Procedure verbally approved by Mr. Paul Kautz (NMOCD Hobbs) on 5-5-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eddie J. Gelwick TITLE Operations Coordinator DATE May 6, 1992

TYPE OR PRINT NAME Eddie Gelwick TELEPHONE NO. 214-739-1778

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

MAY 12 '92

RECEIVED  
MAY 11 1992  
OCD HOBBAS OFFICE