Aug 3 3 up PM '67 Sunday Notices and Reports on Wells Orenation Sunday Notices and Reports on Wells Orenation Out of the properties Orenation Out of the properties of the	DISTRIBUTION SANTA FE NEW MEXICO OIL CONSER FILE U.S.G.S. AUG	ℨÅÅ℈℩ⅆ℀ℾ⅌Åℇℷⅆ℁ⅆΩⅆ	_	3
NEW MEXICO OIL CONSESSIONS. AUG. 3 3 41 PM '67 So. Indicate Type of Leader So. Detect Oil 5 500 Labour No. B-160-1 S	SANTA FE NEW MEXICO OIL CONSER FILE U.S.G.S. LAND OFFICE	3.03.5 (BRIF4 BENDS CO.C.		
Aug 3 3 11 PM '67 Solid Control Solid Con	U.S.G.S. AUG	MAJIMMHADIAMIK GIOTI.	-	
Aug 3 41 PM '67 Aug 3 41 PM '67 Aug 3 41 PM '67 State of Control of the Contro	U.S.G.S. AUG	THE COMMISSION	Effective 1	1-65
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHARGE FLANS	LAND OFFICE			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHARGE FLANS	LAND OFFICE	3 3 kg PM '67	5a. Indicate T	/pe of Lease
SUNDRY NOTICES AND REPORTS ON WELLS OTHER. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: OTHER. Indicate PLANS OTHER. OTHER. OTHER. OTHER. OTHER. OTHER. Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: OTHER. OTHER. OTHER. OTHER. OTHER. OTHER. OTHER. Indicate PLANS OTHER. OTHER. OTHER. OTHER. Indicate PLANS OTHER. OTHER. OTHER. OTHER. Indicate Nature of Notice, Report or Other Data ALTERING CASINE PLUG AND ABADDONNET TREMOMENT TRANSPORT OF: OTHER. OTHER. OTHER. Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: OTHER. OTHER. OTHER. OTHER. OTHER. OTHER. OTHER. OTHER. Indicate Nature of Notice, Report or Other Data ALTERING CASINE PLUG AND ABADDONNET TREMOMENT TRANSPORT OF: OTHER. OT	OPERATOR		State XX	Fee
SUNDRY NOTICES AND REPORTS ON WELLS ONLY DESCRIPTION OF THE PROPERTY OF THE P			5. State Oil &	Gas Lease No.
The control of the co			B-3h	80-1
The control of the co	SUNDRY NOTICES AND REPORTS ON WI	=I I S	HIIIII	
ONLY CASE OF THE STATE CASING CHARGE PLANS C	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH P	TO A DIFFERENT RESERVOIR.		
WELL OF ADDRESS OF THE PLANT ARRONDOMEST TOWNSHIP 22-8 NAMES 37-E NAME STORES OF THE PLANT ARRONDOMEST TOWNSHIP 22-8 NAMES 37-E NAME STORES OF THE PLANT ARRONDOMEST TOWNSHIP 22-8 NAME 37-E NAME STORES OF THE PLANT ARRONDOMEST TOWNSHIP 22-8 NAME 37-E NAME STORES OF THE PLANT ARRONDOMEST TOWNSHIP 22-8 NAME 37-E NAME STORES OF THE NOTICE OF INTENTION TO: THE WEST LINE, SECTION 16 TOWNSHIP 22-8 NAME 37-E NAME. 15. ELEVATION (Show whether DF, RT, GR, etc.) 12. COUNTY 15. ELEVATION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NOTICE OF INTENTION TO: PLUS AND ARANDOM PLANT OF THE NOTICE OF INTENTION TO: THE NAME OF THE NOTICE OF INTENTION TO: THE NAME OF THE N	1.		7. Unit Agreen	nent Name
S. Fern or Lesse None R. E. Cole (NCT-A) Address of Operation R. E. Cole (NCT-A) S. Address of Operation S. Address				
Sear 670, Kabba, Naw Maxico 882k0 10. Location of Well Line and 10. Flesh and Pool, or Waldest 10. Flesh and	2. Name of Operator		8. Form or Lec	ise Name
Sear 670, Kabba, Naw Maxico 882k0 10. Location of Well Line and 10. Flesh and Pool, or Waldest 10. Flesh and	Sulf Oil Composation		D P Co	La (MOR.A)
Box 670, Hebbs, New Mexico 88210 10. Feet room the Morth THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE WEST LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE WEST LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE WEST LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-8 AMPL. THE WEST LINE, SECTION 16 TOWNSHIP 22-8 RANGE AND SANDE 12. County 12	3. Address of Operator			LO (ACITA)
UNIT LETTER R. 2310 PEET PROM THE North LINE AND 990 PEET PROM THE West LINE, SECTION 16 TOWNSHIP 22-8 RANGE 37-E NAME. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PRICE AND ABANDON CHANGE PLUE 1103. CHANGE PLANS CHANGE BRILLING OPPS. CHANGE PLANS CHANGE BRILLING OPPS. PLUE AND ABANDON CHANGE BRILLING OPPS. CHANGE PLANS CHANGE BRILLING OPPS. PLUE AND ABANDON CHANGE BRILLING OPPS. ALTERING CASHNE ALTERING CASHNE PLUE AND ABANDON CHANGE BRILLING OPPS. ALTERING CASHNE ALTERING CASHNE ALTERING CASHNE ALTERING CASHNE ALTERING CASHNE PLUE AND ABANDON CHANGE BRILLING OPPS. ALTERIOR CHANGE BRILLING OPPS. ALTERIOR CHANGE BRILLING OPPS. ALTERIOR CHANGE BRILLING OPPS. ALTE				
THE Wast LINE, SECTION 16 TOWNSHIP 22-S RAIGE 37-E AMPAIL. 15. ELEVATION (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PENFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OFFI. PENFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OFFI. PENFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OFFI. PENFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OFFI. PENFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OFFI. PENFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS COMMENCE DRILLING OFFI. PENFORM REMEDIAL WORK PLUS AND ABANDON COMMENCE DRILLING OFFI. PLUS AND ABANDON COMMENT PLUS AND CHANGE PLANS COMMENCE DRILLING OFFI. PLUS AND ABANDON COMMENT PLUS AND CHANGE PLANS COMMENT PROPOSITION. PENFORM REMEDIAL WORK PLUS AND CHANGE PLANS COMMENT PROPOSITION. PENFORM REMEDIAL WORK PLUS AND CHANGE PLANS COMMENT PROPOSITION. PULS AND ABANDON COMMENT PLANS COMMENT PROPOSITION. PLUS AND ABANDON COMMENT PLANS COMMENT PLANS COMMENT PROPOSITION. PLUS AND ABANDON COMMENT PLANS COMMENT PROPOSITION. PLUS AND ABANDON COMMENT PLANS COMMENT PROPOSITION. PLUS AND ABANDON COMMENT PLANS COMMENT PLANS COMMENT PROPOSITION. PLUS AND ABANDON COMMENT PLANS	Logation of Well			D1 W1111
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORALITY ABANDON OTHER TO. Describe Proposed or Completed Operations (Clearly state all portinent details, and give pertinent dates, including estimated date of starting any propositions, Part of Song Service 1703. Subsequent on top of BP. Calculated PB 7268? Perforated 7° casing at 7224-26° with 7, 1/2° jet holes and at 7238-10° with 8, 1/2° jet holes. Tested BP with 1500°, 30 minutes with packers set at 7269°. BP held OK. Spotted 500 gallons of 15% HE acid ever new perforations 7224-26° and 7238-40°. Set packer at 7173° with 18,000° tension, Pumped acid into formation, Permation broke with 1500°. Sminutes 1500°, after 10 minutes Q°. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.	• •			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: REMEDIAL WORK PERFORM REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERIOS CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERIOS CASING PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET PLUS AND ABANDOMINET PLUS AND ABANDOMIN	UNIT LETTER R , 2310 FEET FROM THE NORTH	LINE AND FEET FR	Indesign	ated Silurian
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: REMEDIAL WORK PERFORM REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERIOS CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERIOS CASING PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET PLUS AND ABANDOMINET PLUS AND ABANDOMIN				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: REMEDIAL WORK PERFORM REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERING CASING PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERIOS CASING PLUS AND ABANDOMINET REMEDIAL WORK ALTERIOS CASING PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET PLUS AND ABANDOMINET ALTERIOS CASING PLUS AND ABANDOMINET PLUS AND ABANDOMINET PLUS AND ABANDOMIN	THE West LINE, SECTION 16 TOWNSHIP 22-8	RANGE 37-E NMI	()	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM BEMEDIAL WORK TEMPORARILY ABANDON THEMPORARILY ABANDON TOTHER T				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDONMENT REMEDIAL WORK ALTERING CASING PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS OTHER OTHER PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ALTERING CASING PLUG AND ABANDONMENT PLUG AND ABANDONMENT ALTERING CASING PLUG AND A	15, Elevation (Show whether DF	, RT, GR, etc.)	12. County	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDONMENT REMEDIAL WORK ALTERING CASING PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS OTHER OTHER PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ALTERING CASING PLUG AND ABANDONMENT PLUG AND ABANDONMENT ALTERING CASING PLUG AND A		39k 1 at.	T.es	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER TO Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rule 1103. Table 11 By 10 B	16		Deli Dise	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL ON ALTER CASING TOTHER THUGAND ABANDONMENT CASING TEST AND CEMENT JOB OTHER THUGAND ABANDONMENT COMMENCE CRILLING OPPS. CASING TEST AND CEMENT JOB OTHER TOTHER THUGAND ABANDONMENT COMMENCE CRILLING OPPS. CASING TEST AND CEMENT JOB OTHER TOTHER THUGAND ABANDONMENT COMMENCE CRILLING OPPS. TOTHER TOTH				_
TEMPORABILLY ABANDON PULL OR ALTER CASING OTHER Thuggad hack and recompleted in Silurian OTHER Pluggad hack and recompleted in Silurian Pluggad hack and recompleted in Silurian To Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rulle 1703. 7383' TD, 7268' PB. Ran CI BP on WL and set at 7280'. Dumped 2 sacks of cement on top of BP. Calculated PB 7268'. Perforated 7" casing at 7221-26' with 7, 1/2" jet heles and at 7238-10' with 8, 1/2" jet holes. Tested BP with 1500%, 30 minutes with packer set at 7263'. BP held CK. Spotted 500 gallons of 15% NE acid ever new perforations 7221-26' and 7238-10'. Set packer at 7173' with 18,000% tension, Pumped acid into formation, Formation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 100%, after 10 minutes Qf. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.	NOTICE OF INTENTION TO:	SUBSEQUE	NI REPORT O	⊢:
TEMPORABILLY ABANDON PULL OR ALTER CASING OTHER Thuggad hack and recompleted in Silurian OTHER Pluggad hack and recompleted in Silurian Pluggad hack and recompleted in Silurian To Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rulle 1703. 7383' TD, 7268' PB. Ran CI BP on WL and set at 7280'. Dumped 2 sacks of cement on top of BP. Calculated PB 7268'. Perforated 7" casing at 7221-26' with 7, 1/2" jet heles and at 7238-10' with 8, 1/2" jet holes. Tested BP with 1500%, 30 minutes with packer set at 7263'. BP held CK. Spotted 500 gallons of 15% NE acid ever new perforations 7221-26' and 7238-10'. Set packer at 7173' with 18,000% tension, Pumped acid into formation, Formation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 100%, after 10 minutes Qf. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.				_
OTHER OTHER OTHER TO DESCRIBE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. 7383' TD, 7268' FB. Ran CI BP on WL and set at 7280'. Dumped 2 sacks of cement on top of BP. Calculated PB 7268'. Perforated 7" casing at 7221-26' with 7, 1/2" jet heles and at 7238-40' with 8, 1/2" jet holes. Tested BP with 1500%, 30 minutes with packer set at 7263'. BP held CK. Spotted 500 gallons of 15% NE acid ever new perforations 7221-26' and 7238-40'. Set packer at 7173' with 18,000% tension. Pumped acid into formation. Formation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 400%, after 10 minutes Of. Plushed with 28 barrels of water. Swabbed and kicked off and placed well on production.	PERFORM REMEDIAL WORK PLUG AND ABANDON R	EMEDIAL WORK	ALT	ERING CASING
Plugged back and recompleted in Silurian 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rule 1703. 17. 7268¹ PB. Ran CI BP on W. and set at 7280¹. Dumped 2 sacks of coment on top of BP. Calculated PB 7268¹. Perforated 7* casing at 722½-26¹ with 7, 1/2* jet heles and at 7238-½0¹ with 8, 1/2* jet holes. Tested BP with 1500*, 30 mimutes with packer set at 7263¹. BP held OK. Spotted 500 gallons of 15% NE acid ever new perforations 722½-26¹ and 7238-½0¹. Set packer at 7173¹ with 18,000* tension, Pumped acid into formation, Formation broke with 1500*. Maximum treating pressure 1600*, minimum 1500*. Injection rate 1.5 bpm. ISIP 1300*, after 5 mimutes 400*, after 10 mimutes Of*. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.	TEMPORARILY ABANDON C	OMMENCE DRILLING OPNS.	PLU	S AND ABANDONMENT
Pluggad back and recompleted in Silurian 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions, SEE RULE 1103. 17. 7268 PB. Ran CI BP on ML and set at 7280 Dumped 2 sacks of coment on top of BP. Calculated PB 7268 Perforated 7" casing at 7224-26 with 7, 1/2" jet holes and at 7238-40 with 8, 1/2" jet holes. Tested BP with 1500%, 30 minutes with packer set at 7263 BP held OK. Spotted 500 gallons of 15% NE acid ever new perforations 7224-26 and 7238-40 Set packer at 7173 with 18,000% tension, Pumped acid into formation, Formation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 400%, after 10 minutes Of. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.	PULL OR ALTER CASING C.	ASING TEST AND CEMENT JOB		_
Plugged back and recompleted in Silurian 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions, such sets at 1280 and set at 7280. Dumped 2 sacks of coment on top of BP. Calculated PB 7268. Perforated 7" casing at 7221-26 with 7, 1/2" jet heles and at 7238-40 with 8, 1/2" jet heles. Tested BP with 1500%, 30 minutes with packer set at 7263. BP held OK. Spotted 500 gallons of 15% NE satis ever new perforations 7221-26 and 7238-40. Set packer at 7173 with 18,000 tension, Pumped said into formation, Fernation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 400%, after 10 minutes Of. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.		OTHER		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositors) SEE RULE 1703. 7383' TD, 7268' PB. Ran CI BP on WL and set at 7280'. Dumped 2 sacks of coment on top of BP. Calculated PB 7268'. Perforated 7" casing at 7221-26' with 7, 1/2" jet heles and at 7238-10' with 8, 1/2" jet holes. Tested BP with 1500%, 30 minutes with packer set at 7263'. BP held OK. Spotted 500 gallons of 15% NE acid ever new perforations 7221-26' and 7238-10'. Set packer at 7173' with 18,000% tension. Pumped acid into formation. Formation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 100%, after 10 minutes QV. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production.	OTHER			
7383' TD, 7268' FB. Ran CI BP on WL and set at 7280'. Dumped 2 sacks of cement on top of BP. Calculated PB 7268'. Perforated 7" casing at 7224-26' with 7, 1/2" jet heles and at 7236-10' with 8, 1/2" jet holes. Tested BP with 1500%, 30 minutes with packer set at 7263'. BP held CK. Spotted 500 gallons of 15% NE acid ever new perforations 7224-26' and 7238-10'. Set packer at 7173' with 18,000% tension. Pumped acid into formation. Formation broke with 1500%. Maximum treating pressure 1600%, minimum 1500%. Injection rate 1.5 bpm. ISIP 1300%, after 5 minutes 100%, after 10 minutes Of. Flushed with 28 barrels of water. Swabbed and kicked off and placed well on production. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY		lugged back and reco	mpleted in	Mlurian
ORIGINAL SIGNED BY	Ran CI BP on WL and set at 7280. Dumpe PB 7268. Perforated 7" casing at 7224-26 with	7, 1/2" jet heles a s with packer set at	nd at 7238-	P. Calculated O' with 8.
	1/2" jet holes. Tested BP with 1500#, 30 minute Spotted 500 gallons of 15% NE acid over new perf at 7173' with 18,000# tension. Pumped acid into Maximum treating pressure 1600#, minimum 1500#. 5 minutes 400#, after 10 minutes 0#. Flushed wi	orations 7224-26' an formation. Formati Injection rate 1.5 b	d 7238-40'. on broke with pm. ISIP 1	held OK. Set packer th 1500#. 300#. after
	1/2" jet holes. Tested BP with 1500#, 30 minute Spotted 500 gallons of 15% NE acid over new perf at 7173' with 18,000# tension. Pumped acid into Maximum treating pressure 1600#, minimum 1500#. 5 minutes 400#, after 10 minutes O#. Flushed wi off and placed well on production. [8. I hereby certify that the information above is true and complete to the best of more of the complete of the best of more of the complete to the best of more of the complete the complete to the best of more of the complete the complete to the best of more of the complete the	forations 7224-26' and formation. Formation Injection rate 1.5 b.th 28 barrels of water with the second sec	d 7238-40°. on broke wi opm. ISIP 1; er. Swabbe	held OK. Set packer th 1500#. 300#, after d and kicked

CONDITIONS OF APPROVAL, HE ANY: