In Lieu of Form 3160 (June 1990	DEPARTM	ted states ent of interior and management 2004 SEP 30 SE	11021	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993				
SUNDRY NOTICE AND REPORTS ON WELLS  RECEIVED  Received this form for proposals to deill or to deepen or sensitive to a different receiveir. Here "A PPI ICATION"				ease Designation and Serial No. F-078773				
SUNDRY NOTICE AND REPORTS ON WELLS  RECFIVE  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  TO DRILL" for permit for such proposals				Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE				Unit or CA, Agreement Designation				
1.	Type of Well Oil Well X Gas Well Other	00, \$ 3	1 -	ell Name and No. OSA UNIT #268A				
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	3004	t - ·	PI Well No. 0-039-27831				
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254			eld and Pool, or Exploratory Area ASIN FRUITLAND COAL				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  1975' FNL & 440' FWL, SW/4 NW/4 SEC 33-T31N-R05W				ounty or Parish, State IO ARRIBA, NM				
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
	TYPE OF SUBMISSION	FACTION						
Notice of Intent X Subsequent Report		Abandonment Recompletion Plugging Back Casing Repair	] ]	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off				
	Final Abandonment Altering Casing Other		i On	Conversion to Injection Dispose Water (Note: Report results of multiple completion Well Completion or Recompletion Report I Log form.)				
13.		Clearly state all pertinent details, and give pertinent dates, in and measured and true vertical depths for all markers and						
09-05-2004 MIRU, drill mouse hole, MU BHA. Spud well & drill 12 ¼" hole from 0' to 103'.								
casers, .25#sx c	run 9 5/8" surface csg & land @ 355'.	, TD of section. Circ hole clean, rig wireline To RD casers; RU cementers. Cmt 9 %" csg as slurry @ 14.5 ppg (Water GPS = 6.84/Yield = and cmt job. WOC.	follows: 200	sxs Type III cmt + 2% CaCl +				
QUADC 1500 ps	O BOP testers. Low test 250 psi – hi	well head. NU BOP & all related equipment. gh test 1500 psi @ 15 min each test. BOP & a BHA & RIH to top of cmt @ 304'. Re-drill mousew formation) from 365' to 485'.	all related eq	uip tested out good. Test csg to				

Continued on Back

14.	I hereby certify that the foregoing is true and correct  Signed	Title Sr. Production Analyst	Date	Septer	nber 23, 2004	
	Tracy Ross U				ACCEPTED FOR RECORD	
	(This space for Federal or State office use)					
	Approved by	Tide		Date	007 6 4 <b>2004</b>	
<del></del>	Conditions of approval, if any:				FARMINGTON FIELD OFFICE	
	U.S.C. Section 1001, makes it a crime for any person kno		ment or agency	of the U	nited States any false, fictitious or fraudu	ilent

09-11-2004 Drill 8 3/4" hole section from 485' to 1900'.

09-12-2004 Drill 8 3/4" hole section from 1900' to 2730'.

09-13-2004 Drill 8 %" hole section from 2730' to 3109'. Mud up @ 3000' -- 40 sec vis. Drill 8 %" hole section from 3109' to 3255'. There were no coal shows until 3255', 7" csg will be set @ 3240' to 3245'. Circ hole clean -- bring vis up to 60 sec. Wiper trip to drill collars, tight hole from 3255' back to 2000'.

<u>09-14-2004</u> Wiper trip to drill collars, tight hole from 2000' back to 1500'. Wiper trip back to 3165', ream from 3165' to bottom @ 3255' - 90'. Work bottom 30' of hole until smooth. Circ hole clean - hole unloaded a lot of shale cuttings. Raise vis from 60 sec to 80 sec. POH onto bank, lay out 6 ½" drill collars, shock sub & 8 ¾" bit. Jet cellar, change to 7" csg rams, hook up circulating & cmt return lines. RU casers, run 7" intermediate csg & land @ 3240' - 10' above the top of coal @ 3250' - 3255'. Run intocking pins on 7" casing hanger. Test hanger to 1500 psi - good test. RD casers, circulate 7" csg - circulate out 80 sec vis mud. Circulate hole clean to cmt, RU cementers while circ.

09-15-2004 Circ 7" csg, circ out 80 sec vis mud. Circ hole clean to cmt, RU cementers while circ. Cmt
7" intermediate csg – plug down @ 09:00. Lead: 600 sxs Premium light cmt + 8% gel + 1% CaCl + .25
lbs per sx cello flake + 165.81 bbls fresh water = 222.3 bbls slurry @ 12.1 ppg (Water GPS =
11.62/Yield = 2.08). Tail: 50 sxs Type 3 cmt + 1% CaCl + .25 lbs per sx cello flake + 8.12 bbls fresh
water = 12.48 bbls slurry @ 14.5 ppg (Water GPS = 6.82/Yield = 1.40). Displace w/ 125.7 bbls fresh
water. Bump plug to 1300 psi – 500 psi over 85 bbls cmt returns to reserve pit. Good cmt job, done
safely – no problems. RD cementers, wait on cement. Clean mud pit & refill with produced water,
prepare for next well section. Test BOP – pipe & blind rams. Choke & kill all related lines, valves &
equip. Test 250 psi low, 1500 psi high @ 30 min each. Test csg to 1500 psi for 30 min – everything
tested out good. Pick up 6 ¼" bit & drill string & RiH to top of cmt @ 3205'. Drill cmt, float & cmt shoe
from 3205' to 3240'. Clean out from 3240' to 3312'. Drill 6 ¼" hole from 3312' to TD of well @ 3512'.

09-16-2004 Circulate hole clean to trip out to surface. POH onto bank – lay out 6 ¼" bit. Pick up under-reamer & RiH w/ DC. Install rotating head & rubber. RiH w/under-reamer to 3250'. Under-ream from 3250' to 3414', TD of coal @ 3412'. Circulate hole clean. POH laying down, well is TD.

09-17-2004 POH laying down, well is TD. Set back pressure safety plug in well head. ND BOP, clean mud pit. Start rigging down to move. Rig released 00:00 hrs 09/17/2004. Rigging down – rig released.