Submit 1 Copy To Appropriate District State of New Mexico	0/15/2020 - NMOCD Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011
<u>District I</u> – (575) 393-6161 Energy, witherars and readural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283	30-025-07537
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE 6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	6. State Off & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Olit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	North Hobbs G/SA
1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator	431 9. OGRID Number: 157984
Occidental Permian Ltd.	y. Gents Ivamoer. 137701
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
Unit Letter I : 2310 feet from the South line and 330	
Section 32 Township 18S Range 38E	,
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3636' GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Papart or Other Data
•••	•
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WOR	
-	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	I JOB 🔲
DOWNHOLE GOWNNINGLE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	impletions: Attach wendore diagram of
proposed completion of recompletion.	
1) POOH with injection equipment 2) Isolate entire look @ 4010?	
2) Isolate casing leak @ 4010'	
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035'	alan to uso
 2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak gith ~ 100 sx of thix sotropic cement blend following 	g this procedure we plan to use
 2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 	osed-loop system with a steel
 Isolate casing leak @ 4010' Set CIBP @ 4085' cap with pea gravel and cement to 4035' RIH and set CICR at +/- 3930', Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite RIH with 4-1/4" bit and clean out to 4035, test sqz. 	osed-loop system with a steel and haul contents to the required
 Isolate casing leak @ 4010' Set CIBP @ 4085' cap with pea gravel and cement to 4035' RIH and set CICR at +/- 3930', Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite RIH with 4-1/4" bit and clean out to 4035, test sqz. 	osed-loop system with a steel and haul contents to the required
 Isolate casing leak @ 4010' Set CIBP @ 4085' cap with pea gravel and cement to 4035' RIH and set CICR at +/- 3930', Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite RIH with 4-1/4" bit and clean out to 4035, test sqz. 	osed-loop system with a steel
 Isolate casing leak @ 4010' Set CIBP @ 4085' cap with pea gravel and cement to 4035' RIH and set CICR at +/- 3930', Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite RIH with 4-1/4" bit and clean out to 4035, test sqz. 	osed-loop system with a steel and haul contents to the required
 Isolate casing leak @ 4010' Set CIBP @ 4085' cap with pea gravel and cement to 4035' RIH and set CICR at +/- 3930', Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite RIH with 4-1/4" bit and clean out to 4035, test sqz. 	osed-loop system with a steel and haul contents to the required
 2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment disposition 	osed-loop system with a steel and haul contents to the required
 2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment disposition 	osed-loop system with a steel and haul contents to the required
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date:	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
 2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment disposition 	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date:	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date:	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17 e and belief.
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE_Production Engineer	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17 The and belief. DATE 09/28/2020
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE_Production Engineer Type or print name Carlos Restrepo E-mail address: carlos_restrepo@oxy.e.	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17 The and belief. DATE 09/28/2020
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE_Production Engineer	osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17 The and belief. DATE 09/28/2020
2) Isolate casing leak @ 4010' 3) Set CIBP @ 4085' cap with pea gravel and cement to 4035' 4) RIH and set CICR at +/- 3930', 5) Cment Sqz leak qith ~ 100 sx of thixsotropic cement blend following with 300 sx of class C cement w / 2% calcium chlorite 6) RIH with 4-1/4" bit and clean out to 4035, test sqz. 7) Continue Co to PBTD @ 4270' POOH with bit 8) RIH with injection equipment Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE_Production Engineer Type or print name Carlos Restrepo E-mail address: carlos_restrepo@oxy.e.	osed-loop system with a steel and haul contents to the required isal per ODC Rule 19.15.17 e and belief. DATE 09/28/2020 DATE 19/28/2020 DATE 19/28/2020