Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 May 27, 2004		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, winterens and reaction resources	WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-22942   5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE $\boxtimes$ FEE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. 8055		
SUNDRY NOT	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		North Vacuum APO Unit		
PROPOSALS.)	· · · · · ·	North Vacuum ABO Unit 8. Well Number 128		
2. Name of Operator	Gas Well Other Injection well	9. OGRID Number		
Mobil Producing TX. & N.M. Inc.				
3. Address of Operator		10. Pool name or Wildcat		
P.O. Box 4358, Houston, TX 77210-4358		Vacuum;Abo, North		
4. Well Location				
	535feet from theEastline and			
Section 23	Township 17S Range 34E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM Lea County		
4032 GL				
Pit or Below-grade Tank Application 🗌 or Closure 🗌				
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water				
Pit Liner Thickness: mil	Below-Grade Tank: Volumebbls; Co	onstruction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN		SEQUENT REPORT OF:		
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DR MULTIPLE COMPL CASING/CEMEN			
OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellboor diagram of proposed completion or recompletion.				
-		1-1E 0E 6282112		
Summary Procedure - Repair Bradenhead leak and return to injection.				

MIRU WSU, bleed off pressure and/or kill well. Install BOPE. Release seal assembly, POOH. PU RIH 5-1/2" RBP Set @ 2900'. Test to 1000#, Dump 20' sand on top of RBP. MIRU WLU, RIH and perforate 5-1/2" production csg @ 2800'. POOH, RDMO. PU RIH w/cmt ret, set @ 2750'. MIRU BJ Services, pump and circ cmt to surf. SI 24-48 hrs. Drill out and test csg to 500#. PU RBP retrieving tool and RIH, circulate out sand & retrieve RBP @ 2900'. POOH. PU & RIH w/DHA – DHA: Baker SA, Set in Pkr @ +/- 8425''and test csg. to 600#. If OK, PU SA, Circulate out KWF. Circulate PKR fluid. Latch onto PKR. Press test csg 500 psi for 15 min. Land TBG, ND BOPE, NU Tree. Run MIT (Must give NMOCD 48 hours advance notice prior to testing.) RDMO WSU, clean and clear location. RU WLU, POOH with blanking plug. RDMO. RWTI.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE Liffang Stebbins	TITLEStaff Office Assistant	DATE6-20-05
Type or print name Tiffany Stebbins E-mail a	address: tiffany.a.stebbins@exxonmobil.com	Telephone No. J. S. 1624-2936 FF MANAGER JUN 624-292005
APPROVED BY: Kary W. Wink Conditions of Approval (if any):	TITLE	DATE