	DEPARTMENT OF			5. Lease Seria NM-404		
Do not use t	Y NOTICES AND this form for propo vell. Use Form 316	sals to drill or to	re-enter an		, Allottee or Tribe Name	
SUBMIT IN TR	RIPLICATE- Othe	r instructions on r	everse side.	7. If Unit or	CA/Agreement, Name ar	
1. Type of Well ☐ Oil Well □ □	Gas Well	Other		8. Well Nar	ne and No.	
2. Name of Operator NADEL AN	ND GUSSMAN HEYCO	,LLC	· · · · · · · · · · · · · · · · · · ·	Federal 9. API We	AF #02 /	
3a. Address PO BOX 1936 ~ ROSWELL NM 88202-1936		3b. Phone No. (include area code) 575/623/6601		30-025-	30-025-30606 10. Field and Pool, or Exploratory Are	
4. Location of Well (Footage, Sec.	, T., R., M, or Survey Desc	ription)	HOBBS OCD	North 1	oung; Delaware	
560' FSL & 1880' FWL, SE S	SW of Section 8, T18S, F	32E	DEC 27 2012		or Parish, State	
12. CHECK A	APPROPRIATE BOX(	ES) TO INDICATE N	ATURE OF NOTIC	TE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION			RECEIVED TYPE OF ACTIC	DN		
Notice of Intent	Acidize	Deepen Fracture Treat		on (Start/Resume) tion	Water Shut-Off	
Subsequent Report	Casing Repair	New Construe		lete arily Abandon	Other Completion	
Final Abandonment Notice	Convert to Injecti		Water D	•		
If the proposal is to deepen di Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is reac <b>BLM Bond No. NMB005</b> <b>Surety Bond No. B00423</b> 9/17/2012 MIRU Pu, tih 9/18/2012 Drill out CIBF	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400	prizontally, give subsurface or provide the Bond No. o peration results in a multiple shall be filed only after all r 175' 0'. Spot 25 sxs neat Class	n file with BLM/BIA. completion or recomp equirements, including	t and true vertical depth Required subsequent r pletion in a new interva greclamation, have bee	eports shall be filed withir l, a Form 3160-4 shall be	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is reac <b>BLM Bond No. NMB005</b> <b>Surety Bond No. B00423</b> 9/17/2012 MIRU Pu, tih	the work will be performed nvolved operations. If the of inal Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400 @ 9,350', set wireline CI spot 25 sxs neat Class H t @ 5,960', Displace well Delaware 5,400'-5,410' ( vater 2,350'. Dump bail 35' cm 2 Acid. t well well	brizontally, give subsurface or provide the Bond No. or peration results in a multiple shall be filed only after all r brief only after all r or the system of the system (bore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid.	ocations and measured n file with BLM/BIA. completion or recomp equirements, including of the cmt. <u>cmt. Tag top of cmt</u> 7,366'. pooh & spe dize with 1,000 gals ate 2nd Delaware 4,	and true vertical depth Required subsequent r pletion in a new interva reclamation, have bee <u>088,652'</u> . ot 25 sxs neat Class of s 15% NEFE Acid. .950'-4,979' (116 hol	eports shall be filed withir I, a Form 3160-4 shall be : n completed, and the open	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is read <b>BLM Bond No. NMB005</b> <b>Surety Bond No. B00423</b> 9/17/2012 <b>MIRU Pu, tih</b> 9/18/2012 Drill out CIBF 9/19/2012 Tag Cmt top (0 9/20/2012 TIH w/tbg & s 9/21/2012 Tag top of cmi 9/24/2012 Perforate 1st I 9/25-26/2012 Swab; all w 9/27/2012 <u>Set CIBP @ 5</u> , 2,500 gallons 15% NEFE 9/28-10/2/2012 Swab test 10/3/2012 Acidize 2nd D 10/4-12/2012 Frac 2nd Dels 14. I hereby certify that the for Name ( <i>Printed/Typed</i> )	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400 @ 9,350', set wireline CI spot 25 sxs neat Class H t @ 5,960', Displace well Delaware 5,400'-5,410' ( vater 	brizontally, give subsurface or provide the Bond No. o peration results in a multiple shall be filed only after all n ". Spot 25 sxs neat Class BP @ 8700' dump bail, cmt @ 7,580', tag cmt ( bore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid. 6/30 sand & 1301 bbis 2	ocations and measured n file with BLM/BIA. completion or recomp equirements, including b H cmt. <u>cmt. Tag top of cmt</u> 0 7,366'. pooh & spe idize with 1,000 gals ate 2nd Delaware 4.	and true vertical depth Required subsequent r pletion in a new interva reclamation, have bee <u>@ 8,652'</u> . of 25 sxs neat Class s 15% NEFE Acid. s 950'-4,979' (116 hol next page)	eports shall be filed withir I, a Form 3160-4 shall be : n completed, and the open	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is reac BLM Bond No. NMB005 Surety Bond No. B004230 9/17/2012 MIRU Pu, fih 9/18/2012 Drill out CIBF 9/19/2012 Tag Cmt top ( 9/20/2012 ThH w/tbg & s 9/21/2012 Tag top of cm 9/24/2012 Perforate 1st I 9/25-26/2012 Swab; all w 9/27/2012 Set CIBP @ 5, 2,500 gallons 15% NEFE 9/28-10/2/2012 Swab test v 10/3/2012 Acidize 2nd D 10/4-12/2012 Swab test v 10/15/2012 Frac 2nd Dels 14. I hereby certify that the for Name (Printed/Typed) Tammy R. Link Signature	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,404 @ 9,350', set wireline CI spot 25 sxs neat Class H t @ 5,960'. Displace well Delaware 5,400'-5,410' ( vater 350'. Dump bail 35' cm chain and the state of the state t well well aware with 6,000 gals well aware with 107,700 #'s 1 regoing is true and correct k	brizontally, give subsurface or provide the Bond No. o peration results in a multiple shall be filed only after all n 175' D'. Spot 25 sxs neat Class <u>BP @ 8700' dump bail,</u> cmt @ 7,580', tag cmt ( ibore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid. 6/30 sand & 1301 bbls 3	ocations and measured n file with BLM/BIA. completion or recomp equirements, including the cmt. <u>cmt. Tag top of cmt</u> 7,366'. pooh & spo idize with 1,000 gals ate 2nd Delaware 4, CL Gel. (continued r the Production Tec	and true vertical depth Required subsequent r pletion in a new interva reclamation, have bee <u>@ 8,652'</u> . of 25 sxs neat Class s 15% NEFE Acid. s 950'-4,979' (116 hol next page)	eports shall be filed withir I, a Form 3160-4 shall be : n completed, and the open	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is read <b>BLM Bond No. NMB005</b> <b>Surety Bond No. B00423</b> 9/17/2012 <b>MIRU Pu, tih</b> 9/18/2012 Drill out CIBF 9/19/2012 Tag Cmt top (0 9/20/2012 TIH w/tbg & s 9/21/2012 Tag top of cmi 9/24/2012 Perforate 1st I 9/25-26/2012 Swab; all w 9/27/2012 <u>Set CIBP @ 5</u> , 2,500 gallons 15% NEFE 9/28-10/2/2012 Swab test 10/3/2012 Acidize 2nd D 10/4-12/2012 Frac 2nd Dels 14. I hereby certify that the for Name ( <i>Printed/Typed</i> )	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400 @ 9,350', set wireline <u>CI</u> spot 25 sxs neat Class H t @ 5,960', Displace well Delaware 5,400'-5,410' ( vater .350'. Dump bail 35' cm C Acid. t well wavare with 6,000 gals well aware with 107,700 #'s 1 regoing is true and correct k	brizontally, give subsurface or provide the Bond No. o peration results in a multiple shall be filed only after all r ". Spot 25 sxs neat Class BP @ 8700' dump bail, cmt @ 7,580', tag cmt (i bbore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid. 6/30 sand & 1301 bbls 3 st L	ocations and measured n file with BLM/BIA. completion or recomp equirements, including 6 H cmt. cmt. Tag top of cmt 9 7,366'. pooh & spe idize with 1,000 gals ate 2nd Delaware 4, CL Gel. (continued r the Production Tec	t and true vertical depth Required subsequent r pletion in a new interva reclamation, have bee (@ 8,652'). (@	eports shall be filed withir I, a Form 3160-4 shall be n completed, and the open C cmt. es). Breakdown & acio	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is reac BLM Bond No. NMB005 Surety Bond No. B004230 9/17/2012 MIRU Pu, tih 9/18/2012 Drill out CIBF 9/19/2012 Tag Cmt top ( 9/20/2012 ThH w/tbg & s 9/21/2012 Tag top of cm 9/24/2012 Perforate 1st I 9/25-26/2012 Swab; all w 9/27/2012 Set CIBP @ 5, 2,500 gallons 15% NEFE 9/28-10/2/2012 Swab test 10/3/2012 Acidize 2nd D 10/4-12/2012 Swab test v 10/15/2012 Frac 2nd Dels 14. I hereby certify that the for Name (Printed/Typed) Tammy R. Link Signature	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400 @ 9,350', set wireline <u>CI</u> spot 25 sxs neat Class H t @ 5,960', Displace well Delaware 5,400'-5,410' ( vater .350'. Dump bail 35' cm C Acid. t well wavare with 6,000 gals well aware with 107,700 #'s 1 regoing is true and correct k	brizontally, give subsurface or provide the Bond No. o peration results in a multiple shall be filed only after all n 175' D'. Spot 25 sxs neat Class <u>BP @ 8700' dump bail,</u> cmt @ 7,580', tag cmt ( ibore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid. 6/30 sand & 1301 bbls 3	ocations and measured n file with BLM/BIA. completion or recomp equirements, including 6 H cmt. cmt. Tag top of cmt 9 7,366'. pooh & spe idize with 1,000 gals ate 2nd Delaware 4, CL Gel. (continued r the Production Tec	t and true vertical depth Required subsequent r pletion in a new interva reclamation, have bee (@ 8,652'). (@	eports shall be filed within 1, a Form 3160-4 shall be in completed, and the open C cmt. es). Breakdown & acio DFOR RE(	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is read BLM Bond No. NMB005 Surety Bond No. B004230 9/17/2012 MIRU Pu, tih 9/18/2012 Drill out CIBF 9/19/2012 Tag Cmt top (0 9/20/2012 The w/tbg & s 9/21/2012 Tag top of cmi 9/24/2012 Perforate 1st I 9/25-26/2012 Swab; all w 9/27/2012 Set CIBP (0.5, 2,500 gallons 15% NEFE 9/28-10/2/2012 Swab test 10/3/2012 Acidize 2nd D 10/4-12/2012 Swab test v 10/15/2012 Frac 2nd Dels 14. I hereby certify that the for Name (Printed/Typed) Tammy R. Lint Signature Approved by Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant to	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400 @ 9,350', set wireline CI spot 25 srs neat Class H t @ 5,960'. Displace well Delaware 5,400'-5,410' ( vater 350'. Dump bail 35' cm C Acid. t well telaware with 6,000 gals well aware with 107,700 #'s 1 regoing is true and correct k THIS SPACE IHIS SPACE	brizontally, give subsurface or provide the Bond No. or peration results in a multiple shall be filed only after all r 175' D'. Spot 25 sxs neat Class <u>BP @ 8700' dump bail,</u> cmt @ 7,580', tag cmt ( bore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid. 6/30 sand & 1301 bbls 2 st FOR FEDERAL C s notice does not warrant of erights in the subject lease con.	ocations and measured n file with BLM/BIA. completion or recomp equirements, including at the cmt. Tag top of cmt of cmt	t and true vertical depth Required subsequent r pletion in a new interva greclamation, have bee (@. 8,652'). of 25 sxs neat Class ( s 15% NEFE Acid. ,950'-4,979' (116 hol next page) The true of the true of the true fice use DE DE BUZEAU OF	eports shall be filed within 1, a Form 3160-4 shall be in completed, and the oper C cmt. es). Breakdown & acid D FOR RE( C 2 2 2012 Nate LAND MANAGEM	
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is reac BLM Bond No. NMB005 Surety Bond No. B004230 9/17/2012 MIRU Pu, tih 9/18/2012 Drill out CIBF 9/19/2012 Tag Cmt top ( 9/20/2012 The Writeg & s 9/21/2012 Tag top of cmi 9/24/2012 Perforate 1st I 9/25-26/2012 Swab; all w 9/27/2012 Set CIBP @ 5, 2,500 gallons 15% NEFE 9/28-10/2/2012 Swab test v 10/15/2012 Frac 2nd Dels 14. I hereby certify that the for Name (Printed/Typed) Tammy R. Lint Signature	the work will be performed nvolved operations. If the o Final Abandonment Notices dy for final inspection.) 520 0 w/workstring & bit to 9 P @ 9175'. TIH to 10,400 @ 9,350', set wireline CI spot 25 srs neat Class H t @ 5,960'. Displace well Delaware 5,400'-5,410' ( vater 350'. Dump bail 35' cm C Acid. t well telaware with 6,000 gals well aware with 107,700 #'s 1 regoing is true and correct k THIS SPACE [ e attached. Approval of this yal or equitable title to those to conduct operations there the 43 U.S.C. Section 1212' f	brizontally, give subsurface or provide the Bond No. or peration results in a multiple shall be filed only after all r ". Spot 25 sxs neat Class <u>BP @ 8700' dump bail,</u> cmt @ 7,580', tag cmt ( bore w/clean 2% KCL. 40 holes) break dn & ac t on top of CIBP. Perfor 15% NEFE Acid. 6/30 sand & 1301 bbls 2 ct FOR FEDERAL C s notice does not warrant of crights in the subject lease con.	ocations and measured n file with BLM/BIA. completion or recomp equirements, including at the term to the term of the term of the term at the term of term the term of the term of the term of the term of term	t and true vertical depth Required subsequent r pletion in a new interva greclamation, have bee (@. 8,652'). of 25 sxs neat Class ( s 15% NEFE Acid. ,950'-4,979' (116 hol next page) The true of the true of the true fice use DE DE BUZEAU OF	eports shall be filed withir 1, a Form 3160-4 shall be in completed, and the open C cmt. es). Breakdown & acid D FOR RE( C 2 2 2012 Nate LAND MANAGEM	

1

10/16/2012 TIH w/tbg & cln out well to 5,815. TOH w/tbg.

10/17/2012 RIH w/tbg string, rods & pump, set TAC @ 4,795', SN @ 4,826'. Turn Well to Production.